

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA	70			
										Target Air Quality Levels				
										EPA Site Specific Trigger Levels				
ASBESTOS-ST1-1/13/09	030901215-0001	Southwest Area (sidewalk bridge level)	1/13/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/14/09	< 13.00		No	No	
ASBESTOS-ST2-1/13/09	030901215-0002	Southeast Area (sidewalk bridge level)	1/13/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/14/09	< 13.00		No	No	
ASBESTOS-ST4-1/13/09	030901215-0003	Northwest Area (street-level)	1/13/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/14/09	< 13.00		No	No	
ASBESTOS-ST5-1/13/09	030901215-0004	Firehouse #10 (roof level)	1/13/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/14/09	< 13.00		No	No	
ASBESTOS-ST10-1/13/09	030901215-0005	North Side Sidewalk Bridge	1/13/09	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/14/09	< 13.00		No	No	
ASBESTOS-ST11-1/13/09	030901215-0006	90 Trinity Place (roof level)	1/13/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/14/09	< 13.00		No	No	
ASBESTOS-ST12-1/13/09	030901215-0007	110 Greenwich Street (roof level)	1/13/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/14/09	< 13.00		No	No	
ASBESTOS-ST13-1/13/09	030901215-0008	Marriott Hotel, 38th Floor (roof level)	1/13/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/14/09	< 13.00		No	No	
ASBESTOS-ST14-1/13/09	030901215-0009	West Face - South end at corner (scaffolding level)	1/13/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/14/09	< 13.00		No	No	
ASBESTOS-ST15-1/13/09	030901215-0010	South Face - East end at corner (scaffolding level)	1/13/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/14/09	< 13.00		No	No	
ASBESTOS-ST16-1/13/09	030901215-0011	East Face - North end at corner (scaffolding level)	1/13/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/14/09	< 13.00		No	No	
ASBESTOS-ST17-1/13/09	030901215-0012	North Face - West end at corner (scaffolding level)	1/13/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/14/09	< 13.00		No	No	
ASBESTOS-ST1-1/14/09	030901330-0001	Southwest Area (sidewalk bridge level)	1/14/09	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 15.00		No	No	
ASBESTOS-ST2-1/14/09	030901330-0002	Southeast Area (sidewalk bridge level)	1/14/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 15.00		No	No	
ASBESTOS-ST4-1/14/09	030901330-0003	Northwest Area (street-level)	1/14/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 13.00		No	No	
ASBESTOS-ST5-1/14/09	030901330-0004	Firehouse #10 (roof level)	1/14/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 13.00		No	No	
ASBESTOS-ST10-1/14/09	030901330-0005	North Side Sidewalk Bridge	1/14/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 13.00		No	No	
ASBESTOS-ST100-1/14/09	030901330-0013	Station 10 Field Duplicate	1/14/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 13.00		No	No	
ASBESTOS-ST11-1/14/09	030901330-0006	90 Trinity Place (roof level)	1/14/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 13.00		No	No	
ASBESTOS-ST12-1/14/09	030901330-0007	110 Greenwich Street (roof level)	1/14/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 13.00		No	No	
ASBESTOS-ST13-1/14/09	030901330-0008	Marriott Hotel, 38th Floor (roof level)	1/14/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 13.00		No	No	
ASBESTOS-ST14-1/14/09	030901330-0009	West Face - South end at corner (scaffolding level)	1/14/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 13.00		No	No	
ASBESTOS-ST15-1/14/09	030901330-0010	South Face - East end at corner (scaffolding level)	1/14/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 13.00		No	No	
ASBESTOS-ST16-1/14/09	030901330-0011	East Face - North end at corner (scaffolding level)	1/14/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 13.00		No	No	
ASBESTOS-ST17-1/14/09	030901330-0012	North Face - West end at corner (scaffolding level)	1/14/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/09	< 13.00		No	No	
ASBESTOS-ST1-1/15/09	030901440-0001	Southwest Area (sidewalk bridge level)	1/15/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/09	< 15.00		No	No	
ASBESTOS-ST2-1/15/09	030901440-0002	Southeast Area (sidewalk bridge level)	1/15/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/09	< 15.00		No	No	
ASBESTOS-ST4-1/15/09	030901440-0003	Northwest Area (street-level)	1/15/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/09	< 13.00		No	No	
ASBESTOS-ST5-1/15/09	030901440-0004	Firehouse #10 (roof level)	1/15/09	1	2.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/09	< 13.00		No	No	Note 1
ASBESTOS-ST10-1/15/09	030901440-0005	North Side Sidewalk Bridge	1/15/09	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/09	< 15.00		No	No	
ASBESTOS-ST11-1/15/09	030901440-0006	90 Trinity Place (roof level)	1/15/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/09	< 13.00		No	No	
ASBESTOS-ST12-1/15/09	030901440-0007	110 Greenwich Street (roof level)	1/15/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/09	< 13.00		No	No	
ASBESTOS-ST13-1/15/09	030901440-0008	Marriott Hotel, 38th Floor (roof level)	1/15/09	1	2.810	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/09	< 13.00		No	No	Note 1
ASBESTOS-ST14-1/15/09	030901440-0009	West Face - South end at corner (scaffolding level)	1/15/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/09	< 13.00		No	No	
ASBESTOS-ST15-1/15/09	030901440-0010	South Face - East end at corner (scaffolding level)	1/15/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/09	< 13.00		No	No	
ASBESTOS-ST16-1/15/09	030901440-0011	East Face - North end at corner (scaffolding level)	1/15/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/09	< 15.00		No	No	
ASBESTOS-ST17-1/15/09	030901440-0012	North Face - West end at corner (scaffolding level)	1/15/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/09	< 13.00		No	No	
ASBESTOS-ST1-1/16/09	030901524-0001	Southwest Area (sidewalk bridge level)	1/16/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/09	< 13.00		No	No	
ASBESTOS-ST2-1/16/09	030901524-0002	Southeast Area (sidewalk bridge level)	1/16/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/09	< 13.00		No	No	
ASBESTOS-ST4-1/16/09	030901524-0003	Northwest Area (street-level)	1/16/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/09	< 13.00		No	No	
ASBESTOS-ST5-1/16/09	030901524-0004	Firehouse #10 (roof level)	1/16/09	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/09	< 13.00		No	No	
ASBESTOS-ST10-1/16/09	030901524-0005	North Side Sidewalk Bridge	1/16/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/09	< 13.00		No	No	
ASBESTOS-ST11-1/16/09	030901524-0006	90 Trinity Place (roof level)	1/16/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/09	< 13.00		No	No	
ASBESTOS-ST12-1/16/09	030901524-0007	110 Greenwich Street (roof level)	1/16/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/09	< 13.00		No	No	
ASBESTOS-ST13-1/16/09	030901524-0008	Marriott Hotel, 38th Floor (roof level)	1/16/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/09	< 13.00		No	No	
ASBESTOS-ST14-1/16/09	030901524-0009	West Face - South end at corner (scaffolding level)	1/16/09	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/09	< 13.00		No	No	
ASBESTOS-ST15-1/16/09	030901524-0010	South Face - East end at corner (scaffolding level)	1/16/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/09	< 13.00		No	No	
ASBESTOS-ST16-1/16/09	030901524-0011	East Face - North end at corner (scaffolding level)	1/16/09	1	2.850	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/09	< 13.00		No	No	
ASBESTOS-ST17-1/16/09	030901524-0012	North Face - West end at corner (scaffolding level)	1/16/09	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/09	< 13.00		No	No	

Note:
1. Due to a final flow rate below 2.0 lpm for asbestos at Station 5 (Firehouse #10 [roof-level]) and Station 13 (Marriott Hotel, 38th floor [roof-level]) on January 15, 2009, the sample volumes and subsequent sample results are estimated.