

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels											70	Levels	Trigger Levels	
ASBESTOS-ST1-1/14/08	030801163-0001	Southwest Area (sidewalk bridge level)	1/14/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 13.00	No	No		
ASBESTOS-ST2-1/14/08	030801163-0002	Southeast Area (sidewalk bridge level)	1/14/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 13.00	No	No		
ASBESTOS-ST4-1/14/08	030801163-0003	Northwest Area (street-level)	1/14/08	1	2.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 9.60	No	No	Note 1	
ASBESTOS-ST5-1/14/08	030801163-0004	Firehouse #10 (roof level)	1/14/08	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 13.00	No	No		
ASBESTOS-ST10-1/14/08	030801163-0005	North Side Sidewalk Bridge	1/14/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 13.00	No	No		
ASBESTOS-ST100-1/14/08	030801163-0013	Station 10 Field Duplicate	1/14/08	1	3.520	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 13.00	No	No		
ASBESTOS-ST11-1/14/08	030801163-0006	90 Trinity Place (roof level)	1/14/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 13.00	No	No		
ASBESTOS-ST12-1/14/08	030801163-0007	110 Greenwich Street (roof level)	1/14/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 13.00	No	No		
ASBESTOS-ST13-1/14/08	030801163-0008	Marriott Hotel, 38th Floor (roof level)	1/14/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 13.00	No	No		
ASBESTOS-ST14-1/14/08	030801163-0009	West Face - South end at corner (scaffolding level)	1/14/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 13.00	No	No		
ASBESTOS-ST15-1/14/08	030801163-0010	South Face - East end at corner (scaffolding level)	1/14/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 13.00	No	No		
ASBESTOS-ST16-1/14/08	030801163-0011	East Face - North end at corner (scaffolding level)	1/14/08	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 13.00	No	No		
ASBESTOS-ST17-1/14/08	030801163-0012	North Face - West end at corner (scaffolding level)	1/14/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/08	< 13.00	No	No		
ASBESTOS-ST1-1/15/08	030801308-0001	Southwest Area (sidewalk bridge level)	1/15/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/08	< 13.00	No	No		
ASBESTOS-ST2-1/15/08	030801308-0002	Southeast Area (sidewalk bridge level)	1/15/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/08	< 15.00	No	No		
ASBESTOS-ST4-1/15/08	030801308-0003	Northwest Area (street-level)	1/15/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/08	< 13.00	No	No		
ASBESTOS-ST5-1/15/08	030801308-0004	Firehouse #10 (roof level)	1/15/08	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/08	< 13.00	No	No		
ASBESTOS-ST10-1/15/08	030801308-0005	North Side Sidewalk Bridge	1/15/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/08	< 13.00	No	No		
ASBESTOS-ST11-1/15/08	030801308-0006	90 Trinity Place (roof level)	1/15/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/08	< 13.00	No	No		
ASBESTOS-ST12-1/15/08	030801308-0007	110 Greenwich Street (roof level)	1/15/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/08	< 13.00	No	No		
ASBESTOS-ST13-1/15/08	030801308-0008	Marriott Hotel, 38th Floor (roof level)	1/15/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/08	< 13.00	No	No		
ASBESTOS-ST14-1/15/08	030801308-0009	West Face - South end at corner (scaffolding level)	1/15/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/08	< 13.00	No	No		
ASBESTOS-ST15-1/15/08	030801308-0010	South Face - East end at corner (scaffolding level)	1/15/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/08	< 13.00	No	No		
ASBESTOS-ST16-1/15/08	030801308-0011	East Face - North end at corner (scaffolding level)	1/15/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/08	< 13.00	No	No		
ASBESTOS-ST17-1/15/08	030801308-0012	North Face - West end at corner (scaffolding level)	1/15/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/08	< 13.00	No	No		
ASBESTOS-ST1-1/16/08	030801439-0001	Southwest Area (sidewalk bridge level)	1/16/08	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/08	< 13.00	No	No		
ASBESTOS-ST2-1/16/08	030801439-0002	Southeast Area (sidewalk bridge level)	1/16/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/08	< 13.00	No	No		
ASBESTOS-ST5-1/16/08	030801439-0003	Firehouse #10 (roof level)	1/16/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/08	< 13.00	No	No		
ASBESTOS-ST10-1/16/08	030801439-0004	North Side Sidewalk Bridge	1/16/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/08	< 13.00	No	No		
ASBESTOS-ST11-1/16/08	030801439-0005	90 Trinity Place (roof level)	1/16/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/08	< 13.00	No	No		
ASBESTOS-ST12-1/16/08	030801439-0006	110 Greenwich Street (roof level)	1/16/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/08	< 13.00	No	No		
ASBESTOS-ST13-1/16/08	030801439-0007	Marriott Hotel, 38th Floor (roof level)	1/16/08	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/08	< 13.00	No	No		
ASBESTOS-ST14-1/16/08	030801439-0008	West Face - South end at corner (scaffolding level)	1/16/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/08	< 13.00	No	No		
ASBESTOS-ST15-1/16/08	030801439-0009	South Face - East end at corner (scaffolding level)	1/16/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/08	< 13.00	No	No		
ASBESTOS-ST16-1/16/08	030801439-0010	East Face - North end at corner (scaffolding level)	1/16/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/08	< 13.00	No	No		
ASBESTOS-ST17-1/16/08	030801439-0011	North Face - West end at corner (scaffolding level)	1/16/08	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/17/08	< 13.00	No	No		

Note:

1. Due to flow rate RPD exceedance (90.6%) for Asbestos at Station 4 (Northwest Area [street-level]) on January 14, 2007 the results for this sample are not valid.
2. Asbestos sample at Station 4 (Northwest Area [street-level]) on January 16, 2008 was not available for analysis on account of pump failure.