

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-1/27/09	030902652-0001	Southwest Area (sidewalk bridge level)	1/27/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/28/09	< 13.00	No	No	
ASBESTOS-ST2-1/27/09	030902652-0002	Southeast Area (sidewalk bridge level)	1/27/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/28/09	< 13.00	No	No	
ASBESTOS-ST4-1/27/09	030902652-0003	Northwest Area (street-level)	1/27/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/28/09	< 13.00	No	No	
ASBESTOS-ST5-1/27/09	030902652-0004	Firehouse #10 (roof level)	1/27/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/28/09	< 13.00	No	No	
ASBESTOS-ST10-1/27/09	030902652-0005	North Side Sidewalk Bridge	1/27/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/28/09	< 13.00	No	No	
ASBESTOS-ST11-1/27/09	030902652-0006	90 Trinity Place (roof level)	1/27/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/28/09	< 13.00	No	No	
ASBESTOS-ST12-1/27/09	030902652-0007	110 Greenwich Street (roof level)	1/27/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/28/09	< 13.00	No	No	
ASBESTOS-ST13-1/27/09	030902652-0008	Marriott Hotel, 38th Floor (roof level)	1/27/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/28/09	< 13.00	No	No	
ASBESTOS-ST14-1/27/09	030902652-0009	West Face - South end at corner (scaffolding level)	1/27/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/28/09	< 13.00	No	No	
ASBESTOS-ST15-1/27/09	030902652-0010	South Face - East end at corner (scaffolding level)	1/27/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/28/09	< 13.00	No	No	
ASBESTOS-ST16-1/27/09	030902652-0011	East Face - North end at corner (scaffolding level)	1/27/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/28/09	< 13.00	No	No	
ASBESTOS-ST17-1/27/09	030902652-0012	North Face - West end at corner (scaffolding level)	1/27/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/28/09	< 13.00	No	No	
ASBESTOS-ST1-1/28/09	030902762-0001	Southwest Area (sidewalk bridge level)	1/28/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/29/09	< 13.00	No	No	
ASBESTOS-ST2-1/28/09	030902762-0002	Southeast Area (sidewalk bridge level)	1/28/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/29/09	< 13.00	No	No	
ASBESTOS-ST4-1/28/09	030902762-0003	Northwest Area (street-level)	1/28/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/29/09	< 13.00	No	No	
ASBESTOS-ST5-1/28/09	030902762-0004	Firehouse #10 (roof level)	1/28/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/29/09	< 13.00	No	No	
ASBESTOS-ST10-1/28/09	030902762-0005	North Side Sidewalk Bridge	1/28/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/29/09	< 13.00	No	No	
ASBESTOS-ST11-1/28/09	030902762-0006	90 Trinity Place (roof level)	1/28/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/29/09	< 13.00	No	No	
ASBESTOS-ST12-1/28/09	030902762-0007	110 Greenwich Street (roof level)	1/28/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/29/09	< 13.00	No	No	
ASBESTOS-ST13-1/28/09	030902762-0008	Marriott Hotel, 38th Floor (roof level)	1/28/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/29/09	< 13.00	No	No	
ASBESTOS-ST14-1/28/09	030902762-0009	West Face - South end at corner (scaffolding level)	1/28/09	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/29/09	< 13.00	No	No	
ASBESTOS-ST15-1/28/09	030902762-0010	South Face - East end at corner (scaffolding level)	1/28/09	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/29/09	< 13.00	No	No	
ASBESTOS-ST17-1/28/09	030902762-0011	North Face - West end at corner (scaffolding level)	1/28/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/29/09	< 13.00	No	No	

Note:

- The asbestos sample from Station 16 (East Face - North end at corner [scaffolding level]) on January 28, 2009 was not available for analysis on account of power failure.