

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target | Exceeds EPA | Comments |
|-----------------------|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|--------------------|------------------------------|----------|
| | | | | | | | | | | NA | Air Quality Levels | Site Specific Trigger Levels | |
| | | | | | | | | | | 70 | | | |
| | | | | | | | | | | Target Air Quality Levels | | | |
| | | | | | | | | | | EPA Site Specific Trigger Levels | | | |
| ASBESTOS-ST1-2/23/07 | 030705948-0001 | Southwest Area (sidewalk bridge level) | 2/23/07 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST2-2/23/07 | 030705948-0002 | Southeast Area (sidewalk bridge level) | 2/23/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST4-2/23/07 | 030705948-0003 | Northwest Area (street-level) | 2/23/07 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST5-2/23/07 | 030705948-0004 | Firehouse #10 (roof level) | 2/23/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST10-2/23/07 | 030705948-0005 | North Side Sidewalk Bridge | 2/23/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST11-2/23/07 | 030705948-0006 | 90 Trinity Place (roof level) | 2/23/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST12-2/23/07 | 030705948-0007 | 110 Greenwich Street (roof level) | 2/23/07 | 1 | 2.880 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST13-2/23/07 | 030705948-0008 | Marriott Hotel, 38th Floor (roof level) | 2/23/07 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST14-2/23/07 | 030705948-0009 | West Face - South end at corner (scaffolding level) | 2/23/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST15-2/23/07 | 030705948-0010 | South Face - East end at corner (scaffolding level) | 2/23/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST16-2/23/07 | 030705948-0011 | East Face - North end at corner (scaffolding level) | 2/23/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST17-2/23/07 | 030705948-0012 | North Face - West end at corner (scaffolding level) | 2/23/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST1-2/24/07 | 030705949-0001 | Southwest Area (sidewalk bridge level) | 2/24/07 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST2-2/24/07 | 030705949-0002 | Southeast Area (sidewalk bridge level) | 2/24/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST4-2/24/07 | 030705949-0003 | Northwest Area (street-level) | 2/24/07 | 1 | 2.950 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST5-2/24/07 | 030705949-0004 | Firehouse #10 (roof level) | 2/24/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST10-2/24/07 | 030705949-0005 | North Side Sidewalk Bridge | 2/24/07 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST11-2/24/07 | 030705949-0006 | 90 Trinity Place (roof level) | 2/24/07 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST12-2/24/07 | 030705949-0007 | 110 Greenwich Street (roof level) | 2/24/07 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST13-2/24/07 | 030705949-0008 | Marriott Hotel, 38th Floor (roof level) | 2/24/07 | 1 | 2.910 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST14-2/24/07 | 030705949-0009 | West Face - South end at corner (scaffolding level) | 2/24/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST15-2/24/07 | 030705949-0010 | South Face - East end at corner (scaffolding level) | 2/24/07 | 1 | 2.930 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST16-2/24/07 | 030705949-0011 | East Face - North end at corner (scaffolding level) | 2/24/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST17-2/24/07 | 030705949-0012 | North Face - West end at corner (scaffolding level) | 2/24/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 2/26/07 | < 13.00 | No | No | |