

| TRC Field Sample No.                    | Sample No.     | Sampling Location                                   | Collection Start Date | Work Shift | Sample Volume (m <sup>3</sup> ) | Analyte  | Analytical Method               | Lab  | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|-----------------------------------|--|----------|
| <b>Target Air Quality Levels</b>        |                |   |                       |            |                                 |          |                                 |      |                         | NA                                   |                                   |  |          |
| <b>EPA Site Specific Trigger Levels</b> |                |   |                       |            |                                 |          |                                 |      |                         | 70                                   |                                   |  |          |
| ASBESTOS-ST1-4/27/06                    | 030612802-0001 | Southwest Area (sidewalk bridge level)              | 4/27/06               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/28/06                 | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST2-4/27/06                    | 030612802-0002 | Southeast Area (sidewalk bridge level)              | 4/27/06               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/28/06                 | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST4-4/27/06                    | 030612802-0003 | Northwest Area (street-level)                       | 4/27/06               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/28/06                 | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST5-4/27/06                    | 030612802-0004 | Firehouse #10 (roof level)                          | 4/27/06               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/28/06                 | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST10-4/27/06                   | 030612802-0005 | North Side Sidewalk Bridge                          | 4/27/06               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/28/06                 | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST11-4/27/06                   | 030612802-0006 | 90 Trinity Place (roof level)                       | 4/27/06               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/28/06                 | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST12-4/27/06                   | 030612802-0007 | 110 Greenwich Street (roof level)                   | 4/27/06               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/28/06                 | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST13-4/27/06                   | 030612802-0008 | Marriott Hotel, 38th Floor (roof level)             | 4/27/06               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/28/06                 | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST14-4/27/06                   | 030612802-0009 | West Face - South end at corner (scaffolding level) | 4/27/06               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/28/06                 | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST15-4/27/06                   | 030612802-0010 | South Face - East end at corner (scaffolding level) | 4/27/06               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/28/06                 | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST16-4/27/06                   | 030612802-0011 | East Face - North end at corner (scaffolding level) | 4/27/06               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/28/06                 | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST17-4/27/06                   | 030612802-0012 | North Face - West end at corner (scaffolding level) | 4/27/06               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/28/06                 | < 13.00                              | No                                | No                                       |          |