

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-5/5/06	030613945-0001	Southwest Area (sidewalk bridge level)	5/5/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST2-5/5/06	030613945-0002	Southeast Area (sidewalk bridge level)	5/5/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST4-5/5/06	030613945-0003	Northwest Area (street-level)	5/5/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST5-5/5/06	030613945-0004	Firehouse #10 (roof level)	5/5/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST10-5/5/06	030613945-0005	North Side Sidewalk Bridge	5/5/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST11-5/5/06	030613945-0006	90 Trinity Place (roof level)	5/5/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST12-5/5/06	030613945-0007	110 Greenwich Street (roof level)	5/5/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST13-5/5/06	030613945-0008	Marriott Hotel, 38th Floor (roof level)	5/5/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST14-5/5/06	030613945-0009	West Face - South end at corner (scaffolding level)	5/5/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST15-5/5/06	030613945-0010	South Face - East end at corner (scaffolding level)	5/5/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST16-5/5/06	030613945-0011	East Face - North end at corner (scaffolding level)	5/5/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST17-5/5/06	030613945-0012	North Face - West end at corner (scaffolding level)	5/5/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST1-5/6/06	030613946-0001	Southwest Area (sidewalk bridge level)	5/6/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST2-5/6/06	030613946-0002	Southeast Area (sidewalk bridge level)	5/6/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST4-5/6/06	030613946-0003	Northwest Area (street-level)	5/6/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST5-5/6/06	030613946-0004	Firehouse #10 (roof level)	5/6/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST10-5/6/06	030613946-0005	North Side Sidewalk Bridge	5/6/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST11-5/6/06	030613946-0006	90 Trinity Place (roof level)	5/6/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST12-5/6/06	030613946-0007	110 Greenwich Street (roof level)	5/6/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST13-5/6/06	030613946-0008	Marriott Hotel, 38th Floor (roof level)	5/6/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST14-5/6/06	030613946-0009	West Face - South end at corner (scaffolding level)	5/6/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST15-5/6/06	030613946-0010	South Face - East end at corner (scaffolding level)	5/6/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST16-5/6/06	030613946-0011	East Face - North end at corner (scaffolding level)	5/6/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST17-5/6/06	030613946-0012	North Face - West end at corner (scaffolding level)	5/6/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST1-5/7/06	030613944-0001	Southwest Area (sidewalk bridge level)	5/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST2-5/7/06	030613944-0002	Southeast Area (sidewalk bridge level)	5/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST4-5/7/06	030613944-0003	Northwest Area (street-level)	5/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST5-5/7/06	030613944-0004	Firehouse #10 (roof level)	5/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST10-5/7/06	030613944-0005	North Side Sidewalk Bridge	5/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST11-5/7/06	030613944-0006	90 Trinity Place (roof level)	5/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST12-5/7/06	030613944-0007	110 Greenwich Street (roof level)	5/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST13-5/7/06	030613944-0008	Marriott Hotel, 38th Floor (roof level)	5/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST14-5/7/06	030613944-0009	West Face - South end at corner (scaffolding level)	5/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST15-5/7/06	030613944-0010	South Face - East end at corner (scaffolding level)	5/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST16-5/7/06	030613944-0011	East Face - North end at corner (scaffolding level)	5/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST17-5/7/06	030613944-0012	North Face - West end at corner (scaffolding level)	5/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/06	< 13.00	No	No		
ASBESTOS-ST1-5/8/06	030614100-0001	Southwest Area (sidewalk bridge level)	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		
ASBESTOS-ST2-5/8/06	030614100-0002	Southeast Area (sidewalk bridge level)	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		
ASBESTOS-ST4-5/8/06	030614100-0003	Northwest Area (street-level)	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		
ASBESTOS-ST5-5/8/06	030614100-0004	Firehouse #10 (roof level)	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		
ASBESTOS-ST10-5/8/06	030614100-0005	North Side Sidewalk Bridge	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		
ASBESTOS-ST100-5/8/06	030614100-0013	Station 10 Field Duplicate	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		
ASBESTOS-ST11-5/8/06	030614100-0006	90 Trinity Place (roof level)	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		
ASBESTOS-ST12-5/8/06	030614100-0007	110 Greenwich Street (roof level)	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		
ASBESTOS-ST13-5/8/06	030614100-0008	Marriott Hotel, 38th Floor (roof level)	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		
ASBESTOS-ST14-5/8/06	030614100-0009	West Face - South end at corner (scaffolding level)	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		
ASBESTOS-ST15-5/8/06	030614100-0010	South Face - East end at corner (scaffolding level)	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		
ASBESTOS-ST16-5/8/06	030614100-0011	East Face - North end at corner (scaffolding level)	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		
ASBESTOS-ST17-5/8/06	030614100-0012	North Face - West end at corner (scaffolding level)	5/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/06	< 13.00	No	No		