

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA	70			
										Target Air Quality Levels				
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-5/12/09	030912079-0001	Southwest Area (sidewalk bridge level)	5/12/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	
ASBESTOS-ST2-5/12/09	030912079-0002	Southeast Area (sidewalk bridge level)	5/12/09	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	
ASBESTOS-ST4-5/12/09	030912079-0003	Northwest Area (street-level)	5/12/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	
ASBESTOS-ST5-5/12/09	030912079-0004	Firehouse #10 (roof level)	5/12/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	
ASBESTOS-ST10-5/12/09	030912079-0005	North Side Sidewalk Bridge	5/12/09	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	Note 1
ASBESTOS-ST11-5/12/09	030912079-0006	90 Trinity Place (roof level)	5/12/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	
ASBESTOS-ST12-5/12/09	030912079-0007	110 Greenwich Street (roof level)	5/12/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	
ASBESTOS-ST13-5/12/09	030912079-0008	Marriott Hotel, 38th Floor (roof level)	5/12/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	
ASBESTOS-ST14-5/12/09	030912079-0009	West Face - South end at corner (scaffolding level)	5/12/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	
ASBESTOS-ST15-5/12/09	030912079-0010	South Face - East end at corner (scaffolding level)	5/12/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	
ASBESTOS-ST16-5/12/09	030912079-0011	East Face - North end at corner (scaffolding level)	5/12/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	
ASBESTOS-ST17-5/12/09	030912079-0012	North Face - West end at corner (scaffolding level)	5/12/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	
ASBESTOS-ST100-5/12/09	030912079-0013	Station 10 Field Duplicate	5/12/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/09	< 13.00		No	No	
ASBESTOS-ST1-5/13/09	030912180-0001	Southwest Area (sidewalk bridge level)	5/13/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/09	< 13.00		No	No	
ASBESTOS-ST2-5/13/09	030912180-0002	Southeast Area (sidewalk bridge level)	5/13/09	1	2.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/09	< 13.00		No	No	Note 2
ASBESTOS-ST4-5/13/09	030912180-0003	Northwest Area (street-level)	5/13/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/09	< 13.00		No	No	
ASBESTOS-ST5-5/13/09	030912180-0004	Firehouse #10 (roof level)	5/13/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/09	< 13.00		No	No	
ASBESTOS-ST10-5/13/09	030912180-0005	North Side Sidewalk Bridge	5/13/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/09	< 13.00		No	No	
ASBESTOS-ST11-5/13/09	030912180-0006	90 Trinity Place (roof level)	5/13/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/09	< 13.00		No	No	
ASBESTOS-ST12-5/13/09	030912180-0007	110 Greenwich Street (roof level)	5/13/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/09	< 13.00		No	No	
ASBESTOS-ST13-5/13/09	030912180-0008	Marriott Hotel, 38th Floor (roof level)	5/13/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/09	< 13.00		No	No	
ASBESTOS-ST14-5/13/09	030912180-0009	West Face - South end at corner (scaffolding level)	5/13/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/09	< 13.00		No	No	
ASBESTOS-ST15-5/13/09	030912180-0010	South Face - East end at corner (scaffolding level)	5/13/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/09	< 13.00		No	No	
ASBESTOS-ST16-5/13/09	030912180-0011	East Face - North end at corner (scaffolding level)	5/13/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/09	< 13.00		No	No	
ASBESTOS-ST17-5/13/09	030912180-0012	North Face - West end at corner (scaffolding level)	5/13/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/09	< 13.00		No	No	
ASBESTOS-ST1-5/14/09	030912285-0001	Southwest Area (sidewalk bridge level)	5/14/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/09	< 13.00		No	No	
ASBESTOS-ST2-5/14/09	030912285-0002	Southeast Area (sidewalk bridge level)	5/14/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/09	< 13.00		No	No	
ASBESTOS-ST4-5/14/09	030912285-0003	Northwest Area (street-level)	5/14/09	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/09	< 13.00		No	No	
ASBESTOS-ST5-5/14/09	030912285-0004	Firehouse #10 (roof level)	5/14/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/09	< 13.00		No	No	
ASBESTOS-ST10-5/14/09	030912285-0005	North Side Sidewalk Bridge	5/14/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/09	< 13.00		No	No	
ASBESTOS-ST11-5/14/09	030912285-0006	90 Trinity Place (roof level)	5/14/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/09	< 13.00		No	No	
ASBESTOS-ST12-5/14/09	030912285-0007	110 Greenwich Street (roof level)	5/14/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/09	< 13.00		No	No	
ASBESTOS-ST13-5/14/09	030912285-0008	Marriott Hotel, 38th Floor (roof level)	5/14/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/09	< 13.00		No	No	
ASBESTOS-ST14-5/14/09	030912285-0009	West Face - South end at corner (scaffolding level)	5/14/09	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/09	< 13.00		No	No	
ASBESTOS-ST15-5/14/09	030912285-0010	South Face - East end at corner (scaffolding level)	5/14/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/09	< 13.00		No	No	
ASBESTOS-ST16-5/14/09	030912285-0011	East Face - North end at corner (scaffolding level)	5/14/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/09	< 13.00		No	No	
ASBESTOS-ST17-5/14/09	030912285-0012	North Face - West end at corner (scaffolding level)	5/14/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/09	< 13.00		No	No	
ASBESTOS-ST1-5/15/09	030912362-0001	Southwest Area (sidewalk bridge level)	5/15/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/16/09	< 13.00		No	No	
ASBESTOS-ST2-5/15/09	030912362-0002	Southeast Area (sidewalk bridge level)	5/15/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/16/09	< 13.00		No	No	
ASBESTOS-ST4-5/15/09	030912362-0003	Northwest Area (street-level)	5/15/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/16/09	< 13.00		No	No	
ASBESTOS-ST5-5/15/09	030912362-0004	Firehouse #10 (roof level)	5/15/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/16/09	< 13.00		No	No	
ASBESTOS-ST10-5/15/09	030912362-0005	North Side Sidewalk Bridge	5/15/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/16/09	< 13.00		No	No	
ASBESTOS-ST11-5/15/09	030912362-0006	90 Trinity Place (roof level)	5/15/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/16/09	< 13.00		No	No	
ASBESTOS-ST12-5/15/09	030912362-0007	110 Greenwich Street (roof level)	5/15/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/16/09	< 13.00		No	No	
ASBESTOS-ST13-5/15/09	030912362-0008	Marriott Hotel, 38th Floor (roof level)	5/15/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/16/09	< 13.00		No	No	
ASBESTOS-ST14-5/15/09	030912362-0009	West Face - South end at corner (scaffolding level)	5/15/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/16/09	< 13.00		No	No	
ASBESTOS-ST15-5/15/09	030912362-0010	South Face - East end at corner (scaffolding level)	5/15/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/16/09	< 13.00		No	No	
ASBESTOS-ST16-5/15/09	030912362-0011	East Face - North end at corner (scaffolding level)	5/15/09	1	2.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/16/09	< 13.00		No	No	
ASBESTOS-ST17-5/15/09	030912362-0012	North Face - West end at corner (scaffolding level)	5/15/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/16/09	< 13.00		No	No	

Note:

1. Due to a final flow rate below 2 liters per minute (lpm) for the asbestos sample at Station 10 (North Side Sidewalk Bridge) on May 12, 2009 the sample volume and subsequent sample result are estimated.
2. Due to a final flow rate below 2 liters per minute (lpm) for the asbestos sample at Station 2 (Southeast Area [sidewalk bridge level]) on May 13, 2009 the sample volume and subsequent sample result are estimated.