

| TRC Field Sample No.             | Sample No.     | Sampling Location                                   | Collection Start Date | Work Shift | Sample Volume (m <sup>3</sup> ) | Analyte  | Analytical Method               | Lab  | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) |  | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|----------------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|--|-----------------------------------|--|----------|
|                                  |                |   |                       |            |                                 |          |                                 |      |                         | NA                                   |  |                                   |  |          |
|                                  |                |   |                       |            |                                 |          |                                 |      |                         | 70                                   |  |                                   |  |          |
| Target Air Quality Levels        |                |   |                       |            |                                 |          |                                 |      |                         |                                      |  |                                   |  |          |
| EPA Site Specific Trigger Levels |                |   |                       |            |                                 |          |                                 |      |                         |                                      |  |                                   |  |          |
| ASBESTOS-ST1-5/25/09             | 030913077-0001 | Southwest Area (sidewalk bridge level)              | 5/25/09               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/26/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST2-5/25/09             | 030913077-0002 | Southeast Area (sidewalk bridge level)              | 5/25/09               | 1          | 3.140                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/26/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST4-5/25/09             | 030913077-0003 | Northwest Area (street-level)                       | 5/25/09               | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/26/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST5-5/25/09             | 030913077-0004 | Firehouse #10 (roof level)                          | 5/25/09               | 1          | 3.200                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/26/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST10-5/25/09            | 030913077-0005 | North Side Sidewalk Bridge                          | 5/25/09               | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/26/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST11-5/25/09            | 030913077-0006 | 90 Trinity Place (roof level)                       | 5/25/09               | 1          | 3.050                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/26/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST12-5/25/09            | 030913077-0007 | 110 Greenwich Street (roof level)                   | 5/25/09               | 1          | 3.020                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/26/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST13-5/25/09            | 030913077-0008 | Marriott Hotel, 38th Floor (roof level)             | 5/25/09               | 1          | 3.020                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/26/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST14-5/25/09            | 030913077-0009 | West Face - South end at corner (scaffolding level) | 5/25/09               | 1          | 3.190                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/26/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST15-5/25/09            | 030913077-0010 | South Face - East end at corner (scaffolding level) | 5/25/09               | 1          | 3.120                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/26/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST16-5/25/09            | 030913077-0011 | East Face - North end at corner (scaffolding level) | 5/25/09               | 1          | 3.230                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/26/09                 | < 15.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST17-5/25/09            | 030913077-0012 | North Face - West end at corner (scaffolding level) | 5/25/09               | 1          | 3.130                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/26/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST1-5/26/09             | 030913194-0001 | Southwest Area (sidewalk bridge level)              | 5/26/09               | 1          | 3.140                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/27/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST2-5/26/09             | 030913194-0002 | Southeast Area (sidewalk bridge level)              | 5/26/09               | 1          | 3.110                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/27/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST4-5/26/09             | 030913194-0003 | Northwest Area (street-level)                       | 5/26/09               | 1          | 2.950                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/27/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST5-5/26/09             | 030913194-0004 | Firehouse #10 (roof level)                          | 5/26/09               | 1          | 3.030                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/27/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST10-5/26/09            | 030913194-0005 | North Side Sidewalk Bridge                          | 5/26/09               | 1          | 2.980                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/27/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST11-5/26/09            | 030913194-0006 | 90 Trinity Place (roof level)                       | 5/26/09               | 1          | 2.990                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/27/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST12-5/26/09            | 030913194-0007 | 110 Greenwich Street (roof level)                   | 5/26/09               | 1          | 3.050                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/27/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST13-5/26/09            | 030913194-0008 | Marriott Hotel, 38th Floor (roof level)             | 5/26/09               | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/27/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST14-5/26/09            | 030913194-0009 | West Face - South end at corner (scaffolding level) | 5/26/09               | 1          | 3.040                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/27/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST15-5/26/09            | 030913194-0010 | South Face - East end at corner (scaffolding level) | 5/26/09               | 1          | 3.050                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/27/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST16-5/26/09            | 030913194-0011 | East Face - North end at corner (scaffolding level) | 5/26/09               | 1          | 3.080                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/27/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST17-5/26/09            | 030913194-0012 | North Face - West end at corner (scaffolding level) | 5/26/09               | 1          | 3.050                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/27/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST1-5/27/09             | 030913281-0001 | Southwest Area (sidewalk bridge level)              | 5/27/09               | 1          | 3.140                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/28/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST2-5/27/09             | 030913281-0002 | Southeast Area (sidewalk bridge level)              | 5/27/09               | 1          | 3.140                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/28/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST4-5/27/09             | 030913281-0003 | Northwest Area (street-level)                       | 5/27/09               | 1          | 3.090                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/28/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST5-5/27/09             | 030913281-0004 | Firehouse #10 (roof level)                          | 5/27/09               | 1          | 3.020                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/28/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST10-5/27/09            | 030913281-0005 | North Side Sidewalk Bridge                          | 5/27/09               | 1          | 3.020                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/28/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST11-5/27/09            | 030913281-0006 | 90 Trinity Place (roof level)                       | 5/27/09               | 1          | 3.060                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/28/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST12-5/27/09            | 030913281-0007 | 110 Greenwich Street (roof level)                   | 5/27/09               | 1          | 3.120                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/28/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST13-5/27/09            | 030913281-0008 | Marriott Hotel, 38th Floor (roof level)             | 5/27/09               | 1          | 3.030                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/28/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST14-5/27/09            | 030913281-0009 | West Face - South end at corner (scaffolding level) | 5/27/09               | 1          | 3.140                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/28/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST15-5/27/09            | 030913281-0010 | South Face - East end at corner (scaffolding level) | 5/27/09               | 1          | 2.990                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/28/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST16-5/27/09            | 030913281-0011 | East Face - North end at corner (scaffolding level) | 5/27/09               | 1          | 3.110                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/28/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST17-5/27/09            | 030913281-0012 | North Face - West end at corner (scaffolding level) | 5/27/09               | 1          | 3.080                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/28/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST1-5/28/09             | 030913388-0001 | Southwest Area (sidewalk bridge level)              | 5/28/09               | 1          | 3.160                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 15.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST2-5/28/09             | 030913388-0002 | Southeast Area (sidewalk bridge level)              | 5/28/09               | 1          | 3.150                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 15.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST4-5/28/09             | 030913388-0003 | Northwest Area (street-level)                       | 5/28/09               | 1          | 2.950                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST5-5/28/09             | 030913388-0004 | Firehouse #10 (roof level)                          | 5/28/09               | 1          | 3.050                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST10-5/28/09            | 030913388-0005 | North Side Sidewalk Bridge                          | 5/28/09               | 1          | 2.930                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST100-5/28/09           | 030913388-0013 | Station 10 Field Duplicate                          | 5/28/09               | 1          | 3.040                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST11-5/28/09            | 030913388-0006 | 90 Trinity Place (roof level)                       | 5/28/09               | 1          | 3.020                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST12-5/28/09            | 030913388-0007 | 110 Greenwich Street (roof level)                   | 5/28/09               | 1          | 3.090                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 15.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST13-5/28/09            | 030913388-0008 | Marriott Hotel, 38th Floor (roof level)             | 5/28/09               | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST14-5/28/09            | 030913388-0009 | West Face - South end at corner (scaffolding level) | 5/28/09               | 1          | 3.070                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 15.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST15-5/28/09            | 030913388-0010 | South Face - East end at corner (scaffolding level) | 5/28/09               | 1          | 2.980                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST16-5/28/09            | 030913388-0011 | East Face - North end at corner (scaffolding level) | 5/28/09               | 1          | 2.990                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST17-5/28/09            | 030913388-0012 | North Face - West end at corner (scaffolding level) | 5/28/09               | 1          | 3.120                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/29/09                 | < 15.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST1-5/29/09             | 030913487-0001 | Southwest Area (sidewalk bridge level)              | 5/29/09               | 1          | 3.090                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/30/09                 | < 15.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST2-5/29/09             | 030913487-0002 | Southeast Area (sidewalk bridge level)              | 5/29/09               | 1          | 3.080                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/30/09                 | < 15.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST4-5/29/09             | 030913487-0003 | Northwest Area (street-level)                       | 5/29/09               | 1          | 3.020                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/30/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST5-5/29/09             | 030913487-0004 | Firehouse #10 (roof level)                          | 5/29/09               | 1          | 3.040                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/30/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST10-5/29/09            | 030913487-0005 | North Side Sidewalk Bridge                          | 5/29/09               | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/30/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST11-5/29/09            | 030913487-0006 | 90 Trinity Place (roof level)                       | 5/29/09               | 1          | 2.980                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/30/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST12-5/29/09            | 030913487-0007 | 110 Greenwich Street (roof level)                   | 5/29/09               | 1          | 2.980                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/30/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST13-5/29/09            | 030913487-0008 | Marriott Hotel, 38th Floor (roof level)             | 5/29/09               | 1          | 3.050                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/30/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST14-5/29/09            | 030913487-0009 | West Face - South end at corner (scaffolding level) | 5/29/09               | 1          | 2.930                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/30/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST15-5/29/09            | 030913487-0010 | South Face - East end at corner (scaffolding level) | 5/29/09               | 1          | 2.940                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/30/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST16-5/29/09            | 030913487-0011 | East Face - North end at corner (scaffolding level) | 5/29/09               | 1          | 2.890                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/30/09                 | < 13.00                              |  | No                                | No                                       |          |
| ASBESTOS-ST17-5/29/09            | 030913487-0012 | North Face - West end at corner (scaffolding level) | 5/29/09               | 1          | 2.900                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 5/30/09                 | < 13.00                              |  | No                                | No                                       |          |