

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|-----------------------------------|--|----------|
| Target Air Quality Levels | | | | | | | | | | NA | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | 70 | | | |
| ASBESTOS-ST1-6/10/09 | 030914413-0001 | Southwest Area (sidewalk bridge level) | 6/10/09 | 1 | 3.070 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/11/09 | < 13.00 | No | No | |
| ASBESTOS-ST2-6/10/09 | 030914413-0002 | Southeast Area (sidewalk bridge level) | 6/10/09 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/11/09 | < 13.00 | No | No | |
| ASBESTOS-ST4-6/10/09 | 030914413-0003 | Northwest Area (street-level) | 6/10/09 | 1 | 2.960 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/11/09 | < 13.00 | No | No | |
| ASBESTOS-ST5-6/10/09 | 030914413-0004 | Firehouse #10 (roof level) | 6/10/09 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/11/09 | < 13.00 | No | No | |
| ASBESTOS-ST10-6/10/09 | 030914413-0005 | North Side Sidewalk Bridge | 6/10/09 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/11/09 | < 13.00 | No | No | |
| ASBESTOS-ST11-6/10/09 | 030914413-0006 | 90 Trinity Place (roof level) | 6/10/09 | 1 | 3.120 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/11/09 | < 13.00 | No | No | |
| ASBESTOS-ST12-6/10/09 | 030914413-0007 | 110 Greenwich Street (roof level) | 6/10/09 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/11/09 | < 13.00 | No | No | |
| ASBESTOS-ST13-6/10/09 | 030914413-0008 | Marriott Hotel, 38th Floor (roof level) | 6/10/09 | 1 | 3.080 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/11/09 | < 13.00 | No | No | |
| ASBESTOS-ST1-6/11/09 | 030914569-0001 | Southwest Area (sidewalk bridge level) | 6/11/09 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/12/09 | < 13.00 | No | No | |
| ASBESTOS-ST2-6/11/09 | 030914569-0002 | Southeast Area (sidewalk bridge level) | 6/11/09 | 1 | 3.070 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/12/09 | < 13.00 | No | No | |
| ASBESTOS-ST4-6/11/09 | 030914569-0003 | Northwest Area (street-level) | 6/11/09 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/12/09 | < 13.00 | No | No | |
| ASBESTOS-ST5-6/11/09 | 030914569-0004 | Firehouse #10 (roof level) | 6/11/09 | 1 | 3.110 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/12/09 | < 13.00 | No | No | |
| ASBESTOS-ST10-6/11/09 | 030914569-0005 | North Side Sidewalk Bridge | 6/11/09 | 1 | 3.080 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/12/09 | < 13.00 | No | No | |
| ASBESTOS-ST11-6/11/09 | 030914569-0006 | 90 Trinity Place (roof level) | 6/11/09 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/12/09 | < 13.00 | No | No | |
| ASBESTOS-ST12-6/11/09 | 030914569-0007 | 110 Greenwich Street (roof level) | 6/11/09 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/12/09 | < 13.00 | No | No | |
| ASBESTOS-ST13-6/11/09 | 030914569-0008 | Marriott Hotel, 38th Floor (roof level) | 6/11/09 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/12/09 | < 13.00 | No | No | |
| ASBESTOS-ST1-6/12/09 | 030914640-0001 | Southwest Area (sidewalk bridge level) | 6/12/09 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST2-6/12/09 | 030914640-0002 | Southeast Area (sidewalk bridge level) | 6/12/09 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST4-6/12/09 | 030914640-0003 | Northwest Area (street-level) | 6/12/09 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST5-6/12/09 | 030914640-0004 | Firehouse #10 (roof level) | 6/12/09 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST10-6/12/09 | 030914640-0005 | North Side Sidewalk Bridge | 6/12/09 | 1 | 2.950 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST11-6/12/09 | 030914640-0006 | 90 Trinity Place (roof level) | 6/12/09 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST12-6/12/09 | 030914640-0007 | 110 Greenwich Street (roof level) | 6/12/09 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST13-6/12/09 | 030914640-0008 | Marriott Hotel, 38th Floor (roof level) | 6/12/09 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/13/09 | < 13.00 | No | No | |