

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-6/21/07	030720334-0001	Southwest Area (sidewalk bridge level)	6/21/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/22/07	< 13.00	No	No	
ASBESTOS-ST2-6/21/07	030720334-0002	Southeast Area (sidewalk bridge level)	6/21/07	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/22/07	< 13.00	No	No	
ASBESTOS-ST4-6/21/07	030720334-0003	Northwest Area (street-level)	6/21/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/22/07	< 13.00	No	No	
ASBESTOS-ST5-6/21/07	030720334-0004	Firehouse #10 (roof level)	6/21/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/22/07	< 13.00	No	No	
ASBESTOS-ST10-6/21/07	030720334-0005	North Side Sidewalk Bridge	6/21/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/22/07	< 13.00	No	No	
ASBESTOS-ST11-6/21/07	030720334-0006	90 Trinity Place (roof level)	6/21/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/22/07	< 13.00	No	No	
ASBESTOS-ST12-6/21/07	030720334-0007	110 Greenwich Street (roof level)	6/21/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/22/07	< 13.00	No	No	
ASBESTOS-ST13-6/21/07	030720334-0008	Marriott Hotel, 38th Floor (roof level)	6/21/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/22/07	< 13.00	No	No	
ASBESTOS-ST14-6/21/07	030720334-0009	West Face - South end at corner (scaffolding level)	6/21/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/22/07	< 13.00	No	No	
ASBESTOS-ST15-6/21/07	030720334-0010	South Face - East end at corner (scaffolding level)	6/21/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/22/07	< 13.00	No	No	
ASBESTOS-ST16-6/21/07	030720334-0011	East Face - North end at corner (scaffolding level)	6/21/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/22/07	< 13.00	No	No	
ASBESTOS-ST17-6/21/07	030720334-0012	North Face - West end at corner (scaffolding level)	6/21/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/22/07	< 13.00	No	No	
ASBESTOS-ST1-6/22/07	030720684-0001	Southwest Area (sidewalk bridge level)	6/22/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST2-6/22/07	030720684-0002	Southeast Area (sidewalk bridge level)	6/22/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST4-6/22/07	030720684-0003	Northwest Area (street-level)	6/22/07	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST5-6/22/07	030720684-0004	Firehouse #10 (roof level)	6/22/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST10-6/22/07	030720684-0005	North Side Sidewalk Bridge	6/22/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST11-6/22/07	030720684-0006	90 Trinity Place (roof level)	6/22/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST12-6/22/07	030720684-0007	110 Greenwich Street (roof level)	6/22/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST13-6/22/07	030720684-0008	Marriott Hotel, 38th Floor (roof level)	6/22/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST14-6/22/07	030720684-0009	West Face - South end at corner (scaffolding level)	6/22/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST15-6/22/07	030720684-0010	South Face - East end at corner (scaffolding level)	6/22/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST16-6/22/07	030720684-0011	East Face - North end at corner (scaffolding level)	6/22/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST17-6/22/07	030720684-0012	North Face - West end at corner (scaffolding level)	6/22/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST1-6/23/07	030720683-0001	Southwest Area (sidewalk bridge level)	6/23/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST2-6/23/07	030720683-0002	Southeast Area (sidewalk bridge level)	6/23/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST4-6/23/07	030720683-0003	Northwest Area (street-level)	6/23/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST5-6/23/07	030720683-0004	Firehouse #10 (roof level)	6/23/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST10-6/23/07	030720683-0005	North Side Sidewalk Bridge	6/23/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST11-6/23/07	030720683-0006	90 Trinity Place (roof level)	6/23/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST12-6/23/07	030720683-0007	110 Greenwich Street (roof level)	6/23/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST13-6/23/07	030720683-0008	Marriott Hotel, 38th Floor (roof level)	6/23/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST14-6/23/07	030720683-0009	West Face - South end at corner (scaffolding level)	6/23/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST15-6/23/07	030720683-0010	South Face - East end at corner (scaffolding level)	6/23/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST16-6/23/07	030720683-0011	East Face - North end at corner (scaffolding level)	6/23/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST17-6/23/07	030720683-0012	North Face - West end at corner (scaffolding level)	6/23/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST1-6/24/07	030720714-0001	Southwest Area (sidewalk bridge level)	6/24/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST2-6/24/07	030720714-0002	Southeast Area (sidewalk bridge level)	6/24/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 15.00	No	No	
ASBESTOS-ST4-6/24/07	030720714-0003	Northwest Area (street-level)	6/24/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST5-6/24/07	030720714-0004	Firehouse #10 (roof level)	6/24/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST10-6/24/07	030720714-0005	North Side Sidewalk Bridge	6/24/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 15.00	No	No	
ASBESTOS-ST11-6/24/07	030720714-0006	90 Trinity Place (roof level)	6/24/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST12-6/24/07	030720714-0007	110 Greenwich Street (roof level)	6/24/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	
ASBESTOS-ST13-6/24/07	030720714-0008	Marriott Hotel, 38th Floor (roof level)	6/24/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/25/07	< 13.00	No	No	

Note:
1. The asbestos readings at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on June 24, 2007 were not available. These stations were offline for relocation to the 15th floor scaffolding from the 20th floor scaffolding.