

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels											70			
ASBESTOS-ST1-06/29/07	030721643-0001	Southwest Area (sidewalk bridge level)	6/29/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST2-06/29/07	030721643-0002	Southeast Area (sidewalk bridge level)	6/29/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST4-06/29/07	030721643-0003	Northwest Area (street-level)	6/29/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST5-06/29/07	030721643-0004	Firehouse #10 (roof level)	6/29/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST10-06/29/07	030721643-0005	North Side Sidewalk Bridge	6/29/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST11-06/29/07	030721643-0006	90 Trinity Place (roof level)	6/29/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST12-06/29/07	030721643-0007	110 Greenwich Street (roof level)	6/29/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST13-06/29/07	030721643-0008	Marriott Hotel, 38th Floor (roof level)	6/29/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST14-06/29/07	030721643-0009	West Face - South end at corner (scaffolding level)	6/29/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST15-06/29/07	030721643-0010	South Face - East end at corner (scaffolding level)	6/29/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST16-06/29/07	030721643-0011	East Face - North end at corner (scaffolding level)	6/29/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST17-06/29/07	030721643-0012	North Face - West end at corner (scaffolding level)	6/29/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST1-6/30/07	030721644-0001	Southwest Area (sidewalk bridge level)	6/30/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST2-6/30/07	030721644-0002	Southeast Area (sidewalk bridge level)	6/30/07	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST4-6/30/07	030721644-0003	Northwest Area (street-level)	6/30/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST5-6/30/07	030721644-0004	Firehouse #10 (roof level)	6/30/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST10-6/30/07	030721644-0005	North Side Sidewalk Bridge	6/30/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST11-6/30/07	030721644-0006	90 Trinity Place (roof level)	6/30/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST12-6/30/07	030721644-0007	110 Greenwich Street (roof level)	6/30/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST13-6/30/07	030721644-0008	Marriott Hotel, 38th Floor (roof level)	6/30/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST14-6/30/07	030721644-0009	West Face - South end at corner (scaffolding level)	6/30/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST15-6/30/07	030721644-0010	South Face - East end at corner (scaffolding level)	6/30/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST16-6/30/07	030721644-0011	East Face - North end at corner (scaffolding level)	6/30/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST17-6/30/07	030721644-0012	North Face - West end at corner (scaffolding level)	6/30/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST1-7/1/07	030721645-0001	Southwest Area (sidewalk bridge level)	7/1/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST2-7/1/07	030721645-0002	Southeast Area (sidewalk bridge level)	7/1/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 15.00	No	No		
ASBESTOS-ST4-7/1/07	030721645-0003	Northwest Area (street-level)	7/1/07	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 15.00	No	No		
ASBESTOS-ST5-7/1/07	030721645-0004	Firehouse #10 (roof level)	7/1/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST10-7/1/07	030721645-0005	North Side Sidewalk Bridge	7/1/07	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST11-7/1/07	030721645-0006	90 Trinity Place (roof level)	7/1/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST12-7/1/07	030721645-0007	110 Greenwich Street (roof level)	7/1/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST13-7/1/07	030721645-0008	Marriott Hotel, 38th Floor (roof level)	7/1/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST14-7/1/07	030721645-0009	West Face - South end at corner (scaffolding level)	7/1/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		
ASBESTOS-ST15-7/1/07	030721645-0010	South Face - East end at corner (scaffolding level)	7/1/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 15.00	No	No		
ASBESTOS-ST16-7/1/07	030721645-0011	East Face - North end at corner (scaffolding level)	7/1/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 15.00	No	No		
ASBESTOS-ST17-7/1/07	030721645-0012	North Face - West end at corner (scaffolding level)	7/1/07	1	2.850	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/07	< 13.00	No	No		