

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality Levels	Site Specific Trigger Levels	Comments
EPA Site Specific Trigger Levels											70			
ASBESTOS-ST1-7/3/07	030721970-0001	Southwest Area (sidewalk bridge level)	7/3/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST2-7/3/07	030721970-0002	Southeast Area (sidewalk bridge level)	7/3/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST4-7/3/07	030721970-0003	Northwest Area (street-level)	7/3/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST5-7/3/07	030721970-0004	Firehouse #10 (roof level)	7/3/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST10-7/3/07	030721970-0005	North Side Sidewalk Bridge	7/3/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST11-7/3/07	030721970-0006	90 Trinity Place (roof level)	7/3/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 15.00	No	No		
ASBESTOS-ST12-7/3/07	030721970-0007	110 Greenwich Street (roof level)	7/3/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST13-7/3/07	030721970-0008	Marriott Hotel, 38th Floor (roof level)	7/3/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 15.00	No	No		
ASBESTOS-ST14-7/3/07	030721970-0009	West Face - South end at corner (scaffolding level)	7/3/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST15-7/3/07	030721970-0010	South Face - East end at corner (scaffolding level)	7/3/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 15.00	No	No		
ASBESTOS-ST16-7/3/07	030721970-0011	East Face - North end at corner (scaffolding level)	7/3/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST17-7/3/07	030721970-0012	North Face - West end at corner (scaffolding level)	7/3/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST1-7/4/07	030721963-0001	Southwest Area (sidewalk bridge level)	7/4/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST2-7/4/07	030721963-0002	Southeast Area (sidewalk bridge level)	7/4/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST4-7/4/07	030721963-0003	Northwest Area (street-level)	7/4/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST5-7/4/07	030721963-0004	Firehouse #10 (roof level)	7/4/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST10-7/4/07	030721963-0005	North Side Sidewalk Bridge	7/4/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST11-7/4/07	030721963-0006	90 Trinity Place (roof level)	7/4/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST12-7/4/07	030721963-0007	110 Greenwich Street (roof level)	7/4/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST13-7/4/07	030721963-0008	Marriott Hotel, 38th Floor (roof level)	7/4/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST14-7/4/07	030721963-0009	West Face - South end at corner (scaffolding level)	7/4/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST15-7/4/07	030721963-0010	South Face - East end at corner (scaffolding level)	7/4/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST16-7/4/07	030721963-0011	East Face - North end at corner (scaffolding level)	7/4/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST17-7/4/07	030721963-0012	North Face - West end at corner (scaffolding level)	7/4/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/5/07	< 13.00	No	No		
ASBESTOS-ST1-7/5/07	030722132-0001	Southwest Area (sidewalk bridge level)	7/5/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		
ASBESTOS-ST2-7/5/07	030722132-0002	Southeast Area (sidewalk bridge level)	7/5/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		
ASBESTOS-ST4-7/5/07	030722132-0003	Northwest Area (street-level)	7/5/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		
ASBESTOS-ST5-7/5/07	030722132-0004	Firehouse #10 (roof level)	7/5/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		
ASBESTOS-ST10-7/5/07	030722132-0005	North Side Sidewalk Bridge	7/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		
ASBESTOS-ST100-7/5/07	030722132-0013	Station 10 Field Duplicate	7/5/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		
ASBESTOS-ST11-7/5/07	030722132-0006	90 Trinity Place (roof level)	7/5/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		
ASBESTOS-ST12-7/5/07	030722132-0007	110 Greenwich Street (roof level)	7/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		
ASBESTOS-ST13-7/5/07	030722132-0008	Marriott Hotel, 38th Floor (roof level)	7/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		
ASBESTOS-ST14-7/5/07	030722132-0009	West Face - South end at corner (scaffolding level)	7/5/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		
ASBESTOS-ST15-7/5/07	030722132-0010	South Face - East end at corner (scaffolding level)	7/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		
ASBESTOS-ST16-7/5/07	030722132-0011	East Face - North end at corner (scaffolding level)	7/5/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		
ASBESTOS-ST17-7/5/07	030722132-0012	North Face - West end at corner (scaffolding level)	7/5/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/07	< 13.00	No	No		