

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels										70	Levels	Trigger Levels	
ASBESTOS-ST1-7/9/08	030822443-0001	Southwest Area (sidewalk bridge level)	7/9/08	1	3.280	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	< 13.00	No	No	
ASBESTOS-ST2-7/9/08	030822443-0002	Southeast Area (sidewalk bridge level)	7/9/08	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	13.00	No	No	
ASBESTOS-ST4-7/9/08	030822443-0003	Northwest Area (street-level)	7/9/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	< 13.00	No	No	
ASBESTOS-ST5-7/9/08	030822443-0004	Firehouse #10 (roof level)	7/9/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	< 13.00	No	No	
ASBESTOS-ST10-7/9/08	030822443-0005	North Side Sidewalk Bridge	7/9/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	< 13.00	No	No	
ASBESTOS-ST100-7/9/08	030822443-0013	Station 10 Field Duplicate	7/9/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	< 13.00	No	No	
ASBESTOS-ST11-7/9/08	030822443-0006	90 Trinity Place (roof level)	7/9/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	< 13.00	No	No	
ASBESTOS-ST12-7/9/08	030822443-0007	110 Greenwich Street (roof level)	7/9/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	< 13.00	No	No	
ASBESTOS-ST13-7/9/08	030822443-0008	Marriott Hotel, 38th Floor (roof level)	7/9/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	< 13.00	No	No	
ASBESTOS-ST14-7/9/08	030822443-0009	West Face - South end at corner (scaffolding level)	7/9/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	< 13.00	No	No	
ASBESTOS-ST15-7/9/08	030822443-0010	South Face - East end at corner (scaffolding level)	7/9/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	< 13.00	No	No	
ASBESTOS-ST16-7/9/08	030822443-0011	East Face - North end at corner (scaffolding level)	7/9/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	< 13.00	No	No	
ASBESTOS-ST17-7/9/08	030822443-0012	North Face - West end at corner (scaffolding level)	7/9/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/11/08	< 13.00	No	No	
ASBESTOS-ST1-7/10/08	030822687-0001	Southwest Area (sidewalk bridge level)	7/10/08	1	3.270	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST2-7/10/08	030822687-0002	Southeast Area (sidewalk bridge level)	7/10/08	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST4-7/10/08	030822687-0003	Northwest Area (street-level)	7/10/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST5-7/10/08	030822687-0004	Firehouse #10 (roof level)	7/10/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST10-7/10/08	030822687-0005	North Side Sidewalk Bridge	7/10/08	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST11-7/10/08	030822687-0006	90 Trinity Place (roof level)	7/10/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST12-7/10/08	030822687-0007	110 Greenwich Street (roof level)	7/10/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST13-7/10/08	030822687-0008	Marriott Hotel, 38th Floor (roof level)	7/10/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST14-7/10/08	030822687-0009	West Face - South end at corner (scaffolding level)	7/10/08	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST15-7/10/08	030822687-0010	South Face - East end at corner (scaffolding level)	7/10/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST16-7/10/08	030822687-0011	East Face - North end at corner (scaffolding level)	7/10/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST17-7/10/08	030822687-0012	North Face - West end at corner (scaffolding level)	7/10/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST1-7/11/08	030822689-0001	Southwest Area (sidewalk bridge level)	7/11/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 15.00	No	No	
ASBESTOS-ST2-7/11/08	030822689-0002	Southeast Area (sidewalk bridge level)	7/11/08	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 15.00	No	No	
ASBESTOS-ST4-7/11/08	030822689-0003	Northwest Area (street-level)	7/11/08	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 15.00	No	No	
ASBESTOS-ST5-7/11/08	030822689-0004	Firehouse #10 (roof level)	7/11/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST10-7/11/08	030822689-0005	North Side Sidewalk Bridge	7/11/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 15.00	No	No	
ASBESTOS-ST11-7/11/08	030822689-0006	90 Trinity Place (roof level)	7/11/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST12-7/11/08	030822689-0007	110 Greenwich Street (roof level)	7/11/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST13-7/11/08	030822689-0008	Marriott Hotel, 38th Floor (roof level)	7/11/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 15.00	No	No	
ASBESTOS-ST14-7/11/08	030822689-0009	West Face - South end at corner (scaffolding level)	7/11/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 15.00	No	No	
ASBESTOS-ST15-7/11/08	030822689-0010	South Face - East end at corner (scaffolding level)	7/11/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 15.00	No	No	
ASBESTOS-ST16-7/11/08	030822689-0011	East Face - North end at corner (scaffolding level)	7/11/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 15.00	No	No	
ASBESTOS-ST17-7/11/08	030822689-0012	North Face - West end at corner (scaffolding level)	7/11/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/08	< 13.00	No	No	
ASBESTOS-ST1-7/12/08	030822868-0001	Southwest Area (sidewalk bridge level)	7/12/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST2-7/12/08	030822868-0002	Southeast Area (sidewalk bridge level)	7/12/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST4-7/12/08	030822868-0003	Northwest Area (street-level)	7/12/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST5-7/12/08	030822868-0004	Firehouse #10 (roof level)	7/12/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST10-7/12/08	030822868-0005	North Side Sidewalk Bridge	7/12/08	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST11-7/12/08	030822868-0006	90 Trinity Place (roof level)	7/12/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST12-7/12/08	030822868-0007	110 Greenwich Street (roof level)	7/12/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST13-7/12/08	030822868-0008	Marriott Hotel, 38th Floor (roof level)	7/12/08	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST14-7/12/08	030822868-0009	West Face - South end at corner (scaffolding level)	7/12/08	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST15-7/12/08	030822868-0010	South Face - East end at corner (scaffolding level)	7/12/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST16-7/12/08	030822868-0011	East Face - North end at corner (scaffolding level)	7/12/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST17-7/12/08	030822868-0012	North Face - West end at corner (scaffolding level)	7/12/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST1-7/13/08	030822870-0001	Southwest Area (sidewalk bridge level)	7/13/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST2-7/13/08	030822870-0002	Southeast Area (sidewalk bridge level)	7/13/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST4-7/13/08	030822870-0003	Northwest Area (street-level)	7/13/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST5-7/13/08	030822870-0004	Firehouse #10 (roof level)	7/13/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST10-7/13/08	030822870-0005	North Side Sidewalk Bridge	7/13/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST11-7/13/08	030822870-0006	90 Trinity Place (roof level)	7/13/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST12-7/13/08	030822870-0007	110 Greenwich Street (roof level)	7/13/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST13-7/13/08	030822870-0008	Marriott Hotel, 38th Floor (roof level)	7/13/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST14-7/13/08	030822870-0009	West Face - South end at corner (scaffolding level)	7/13/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST15-7/13/08	030822870-0010	South Face - East end at corner (scaffolding level)	7/13/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST16-7/13/08	030822870-0011	East Face - North end at corner (scaffolding level)	7/13/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	
ASBESTOS-ST17-7/13/08	030822870-0012	North Face - West end at corner (scaffolding level)	7/13/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/08	< 13.00	No	No	