

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels											70	Levels	Trigger Levels	
ASBESTOS-ST1-7/14/08	030823149-0001	Southwest Area (sidewalk bridge level)	7/14/08	1	3.230	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/15/08	< 13.00	No	No		
ASBESTOS-ST2-7/14/08	030823149-0002	Southeast Area (sidewalk bridge level)	7/14/08	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/15/08	< 13.00	No	No		
ASBESTOS-ST4-7/14/08	030823149-0003	Northwest Area (street-level)	7/14/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/15/08	< 13.00	No	No		
ASBESTOS-ST5-7/14/08	030823149-0004	Firehouse #10 (roof level)	7/14/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/15/08	< 13.00	No	No		
ASBESTOS-ST10-7/14/08	030823149-0005	North Side Sidewalk Bridge	7/14/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/15/08	< 13.00	No	No		
ASBESTOS-ST11-7/14/08	030823149-0006	90 Trinity Place (roof level)	7/14/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/15/08	< 13.00	No	No		
ASBESTOS-ST12-7/14/08	030823149-0007	110 Greenwich Street (roof level)	7/14/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/15/08	< 13.00	No	No		
ASBESTOS-ST13-7/14/08	030823149-0008	Marriott Hotel, 38th Floor (roof level)	7/14/08	1	2.580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/15/08	< 13.00	No	No		
ASBESTOS-ST14-7/14/08	030823149-0009	West Face - South end at corner (scaffolding level)	7/14/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/15/08	< 13.00	No	No		
ASBESTOS-ST15-7/14/08	030823149-0010	South Face - East end at corner (scaffolding level)	7/14/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/15/08	< 13.00	No	No		
ASBESTOS-ST16-7/14/08	030823149-0011	East Face - North end at corner (scaffolding level)	7/14/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/15/08	< 13.00	No	No		
ASBESTOS-ST17-7/14/08	030823149-0012	North Face - West end at corner (scaffolding level)	7/14/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/15/08	< 13.00	No	No		
ASBESTOS-ST1-7/15/08	030823362-0001	Southwest Area (sidewalk bridge level)	7/15/08	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/08	< 13.00	No	No		
ASBESTOS-ST2-7/15/08	030823362-0002	Southeast Area (sidewalk bridge level)	7/15/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/08	< 13.00	No	No		
ASBESTOS-ST4-7/15/08	030823362-0003	Northwest Area (street-level)	7/15/08	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/08	< 13.00	No	No		
ASBESTOS-ST5-7/15/08	030823362-0004	Firehouse #10 (roof level)	7/15/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/08	< 13.00	No	No		
ASBESTOS-ST10-7/15/08	030823362-0005	North Side Sidewalk Bridge	7/15/08	1	3.200	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/08	< 13.00	No	No		
ASBESTOS-ST11-7/15/08	030823362-0006	90 Trinity Place (roof level)	7/15/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/08	< 13.00	No	No		
ASBESTOS-ST12-7/15/08	030823362-0007	110 Greenwich Street (roof level)	7/15/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/08	< 13.00	No	No		
ASBESTOS-ST13-7/15/08	030823362-0008	Marriott Hotel, 38th Floor (roof level)	7/15/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/08	< 13.00	No	No		
ASBESTOS-ST14-7/15/08	030823362-0009	West Face - South end at corner (scaffolding level)	7/15/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/08	< 13.00	No	No		
ASBESTOS-ST15-7/15/08	030823362-0010	South Face - East end at corner (scaffolding level)	7/15/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/08	< 13.00	No	No		
ASBESTOS-ST16-7/15/08	030823362-0011	East Face - North end at corner (scaffolding level)	7/15/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/08	< 13.00	No	No		
ASBESTOS-ST17-7/15/08	030823362-0012	North Face - West end at corner (scaffolding level)	7/15/08	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/08	< 13.00	No	No		
ASBESTOS-ST1-7/16/08	030823481-0001	Southwest Area (sidewalk bridge level)	7/16/08	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/17/08	< 13.00	No	No		
ASBESTOS-ST2-7/16/08	030823481-0002	Southeast Area (sidewalk bridge level)	7/16/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/17/08	< 13.00	No	No		
ASBESTOS-ST4-7/16/08	030823481-0003	Northwest Area (street-level)	7/16/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/17/08	< 13.00	No	No		
ASBESTOS-ST5-7/16/08	030823481-0004	Firehouse #10 (roof level)	7/16/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/17/08	< 13.00	No	No		
ASBESTOS-ST10-7/16/08	030823481-0005	North Side Sidewalk Bridge	7/16/08	1	3.200	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/17/08	< 13.00	No	No		
ASBESTOS-ST11-7/16/08	030823481-0006	90 Trinity Place (roof level)	7/16/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/17/08	< 13.00	No	No		
ASBESTOS-ST12-7/16/08	030823481-0007	110 Greenwich Street (roof level)	7/16/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/17/08	< 13.00	No	No		
ASBESTOS-ST13-7/16/08	030823481-0008	Marriott Hotel, 38th Floor (roof level)	7/16/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/17/08	< 13.00	No	No		
ASBESTOS-ST14-7/16/08	030823481-0009	West Face - South end at corner (scaffolding level)	7/16/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/17/08	< 13.00	No	No		
ASBESTOS-ST15-7/16/08	030823481-0010	South Face - East end at corner (scaffolding level)	7/16/08	1	2.590	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/17/08	< 13.00	No	No		
ASBESTOS-ST16-7/16/08	030823481-0011	East Face - North end at corner (scaffolding level)	7/16/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/17/08	< 13.00	No	No		
ASBESTOS-ST17-7/16/08	030823481-0012	North Face - West end at corner (scaffolding level)	7/16/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/17/08	< 13.00	No	No		