

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
										NA	Air Quality Levels	Site Specific Trigger Levels	
										70			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-7/24/06	030623269-0001	Southwest Area (sidewalk bridge level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST2-7/24/06	030623269-0002	Southeast Area (sidewalk bridge level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST4-7/24/06	030623269-0003	Northwest Area (street-level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST5-7/24/06	030623269-0004	Firehouse #10 (roof level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST6-7/24/06	030623273-0001	Southwest Area (roof level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST7-7/24/06	030623273-0002	Southeast Area (roof level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST8-7/24/06	030623273-0003	Northeast Area (roof level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST9-7/24/06	030623273-0004	Northwest Area (roof level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST10-7/24/06	030623269-0005	North Side Sidewalk Bridge	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST11-7/24/06	030623269-0006	90 Trinity Place (roof level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST12-7/24/06	030623269-0007	110 Greenwich Street (roof level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST13-7/24/06	030623269-0008	Marriott Hotel, 38th Floor (roof level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST14-7/24/06	030623269-0009	West Face - South end at corner (scaffolding level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST15-7/24/06	030623269-0010	South Face - East end at corner (scaffolding level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST16-7/24/06	030623269-0011	East Face - North end at corner (scaffolding level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST17-7/24/06	030623269-0012	North Face - West end at corner (scaffolding level)	7/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/25/06	< 13.00	No	No	
ASBESTOS-ST1-7/25/06	030623471-0001	Southwest Area (sidewalk bridge level)	7/25/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST2-7/25/06	030623471-0002	Southeast Area (sidewalk bridge level)	7/25/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST4-7/25/06	030623471-0003	Northwest Area (street-level)	7/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST5-7/25/06	030623471-0004	Firehouse #10 (roof level)	7/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST6-7/25/06	030623472-0001	Southwest Area (roof level)	7/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST7-7/25/06	030623472-0002	Southeast Area (roof level)	7/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST8-7/25/06	030623472-0003	Northeast Area (roof level)	7/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST10-7/25/06	030623471-0005	North Side Sidewalk Bridge	7/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST11-7/25/06	030623471-0006	90 Trinity Place (roof level)	7/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST12-7/25/06	030623471-0007	110 Greenwich Street (roof level)	7/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST13-7/25/06	030623471-0008	Marriott Hotel, 38th Floor (roof level)	7/25/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST14-7/25/06	030623471-0009	West Face - South end at corner (scaffolding level)	7/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST15-7/25/06	030623471-0010	South Face - East end at corner (scaffolding level)	7/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST16-7/25/06	030623471-0011	East Face - North end at corner (scaffolding level)	7/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	
ASBESTOS-ST17-7/25/06	030623471-0012	North Face - West end at corner (scaffolding level)	7/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/26/06	< 13.00	No	No	

Note:

- Asbestos sample at Station 9 (Northwest Area [roof level]) on July 25, 2006 was not available for analysis on account of instrument malfunction.