

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-7/29/09	030919552-0001	Southwest Area (sidewalk bridge level)	7/29/09	1	3.230	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/30/09	< 15.00	No	No	
ASBESTOS-ST2-7/29/09	030919552-0002	Southeast Area (sidewalk bridge level)	7/29/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/30/09	< 13.00	No	No	
ASBESTOS-ST4-7/29/09	030919552-0003	Northwest Area (street-level)	7/29/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/30/09	< 13.00	No	No	
ASBESTOS-ST5-7/29/09	030919552-0004	Firehouse #10 (roof level)	7/29/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/30/09	< 13.00	No	No	
ASBESTOS-ST10-7/29/09	030919552-0005	North Side Sidewalk Bridge	7/29/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/30/09	< 13.00	No	No	
ASBESTOS-ST11-7/29/09	030919552-0006	90 Trinity Place (roof level)	7/29/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/30/09	< 13.00	No	No	
ASBESTOS-ST12-7/29/09	030919552-0007	110 Greenwich Street (roof level)	7/29/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/30/09	< 13.00	No	No	
ASBESTOS-ST13-7/29/09	030919552-0008	Marriott Hotel, 38th Floor (roof level)	7/29/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/30/09	< 13.00	No	No	
ASBESTOS-ST1-7/30/09	030919678-0001	Southwest Area (sidewalk bridge level)	7/30/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/31/09	< 13.00	No	No	
ASBESTOS-ST2-7/30/09	030919678-0002	Southeast Area (sidewalk bridge level)	7/30/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/31/09	< 13.00	No	No	
ASBESTOS-ST4-7/30/09	030919678-0003	Northwest Area (street-level)	7/30/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/31/09	< 13.00	No	No	
ASBESTOS-ST5-7/30/09	030919678-0004	Firehouse #10 (roof level)	7/30/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/31/09	< 13.00	No	No	
ASBESTOS-ST10-7/30/09	030919678-0005	North Side Sidewalk Bridge	7/30/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/31/09	< 13.00	No	No	
ASBESTOS-ST11-7/30/09	030919678-0006	90 Trinity Place (roof level)	7/30/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/31/09	< 13.00	No	No	
ASBESTOS-ST12-7/30/09	030919678-0007	110 Greenwich Street (roof level)	7/30/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/31/09	< 13.00	No	No	
ASBESTOS-ST13-7/30/09	030919678-0008	Marriott Hotel, 38th Floor (roof level)	7/30/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/31/09	< 13.00	No	No	
ASBESTOS-ST1-7/31/09	030919776-0001	Southwest Area (sidewalk bridge level)	7/31/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/1/09	< 13.00	No	No	
ASBESTOS-ST2-7/31/09	030919776-0002	Southeast Area (sidewalk bridge level)	7/31/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/1/09	< 13.00	No	No	
ASBESTOS-ST4-7/31/09	030919776-0003	Northwest Area (street-level)	7/31/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/1/09	< 13.00	No	No	
ASBESTOS-ST5-7/31/09	030919776-0004	Firehouse #10 (roof level)	7/31/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/1/09	< 13.00	No	No	
ASBESTOS-ST10-7/31/09	030919776-0005	North Side Sidewalk Bridge	7/31/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/1/09	< 13.00	No	No	
ASBESTOS-ST11-7/31/09	030919776-0006	90 Trinity Place (roof level)	7/31/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/1/09	< 13.00	No	No	
ASBESTOS-ST12-7/31/09	030919776-0007	110 Greenwich Street (roof level)	7/31/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/1/09	< 13.00	No	No	
ASBESTOS-ST13-7/31/09	030919776-0008	Marriott Hotel, 38th Floor (roof level)	7/31/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/1/09	< 13.00	No	No	