

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-8/8/07	030727011-0001	Southwest Area (sidewalk bridge level)	8/8/07	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/07	< 15.00	No	No	
ASBESTOS-ST2-8/8/07	030727011-0002	Southeast Area (sidewalk bridge level)	8/8/07	1	2.990	Asbestos	SEM	EMSL	8/9/07	< 4.63	No	No	
ASBESTOS-ST5-8/8/07	030727011-0003	Firehouse #10 (roof level)	8/8/07	1	3.040	Asbestos	SEM	EMSL	8/9/07	< 4.63	No	No	
ASBESTOS-ST10-8/8/07	030727011-0004	North Side Sidewalk Bridge	8/8/07	1	3.030	Asbestos	SEM	EMSL	8/9/07	< 4.63	No	No	
ASBESTOS-ST100-8/8/07	030727011-0011	Station 10 Field Duplicate	8/8/07	1	3.030	Asbestos	SEM	EMSL	8/9/07	< 4.63	No	No	
ASBESTOS-ST11-8/8/07	030727011-0005	90 Trinity Place (roof level)	8/8/07	1	2.940	Asbestos	SEM	EMSL	8/9/07	< 4.63	No	No	
ASBESTOS-ST13-8/8/07	030727011-0006	Marriott Hotel, 38th Floor (roof level)	8/8/07	1	3.050	Asbestos	SEM	EMSL	8/9/07	< 4.63	No	No	
ASBESTOS-ST14-8/8/07	030727011-0007	West Face - South end at corner (scaffolding level)	8/8/07	1	3.050	Asbestos	SEM	EMSL	8/9/07	< 4.63	No	No	
ASBESTOS-ST15-8/8/07	030727011-0008	South Face - East end at corner (scaffolding level)	8/8/07	1	3.040	Asbestos	SEM	EMSL	8/9/07	< 4.63	No	No	
ASBESTOS-ST16-8/8/07	030727011-0009	East Face - North end at corner (scaffolding level)	8/8/07	1	3.000	Asbestos	SEM	EMSL	8/9/07	< 4.63	No	No	
ASBESTOS-ST17-8/8/07	030727011-0010	North Face - West end at corner (scaffolding level)	8/8/07	1	3.000	Asbestos	SEM	EMSL	8/9/07	< 4.63	No	No	
ASBESTOS-ST1-8/9/07	030727180-0001	Southwest Area (sidewalk bridge level)	8/9/07	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/10/07	< 13.00	No	No	
ASBESTOS-ST2-8/9/07	030727180-0002	Southeast Area (sidewalk bridge level)	8/9/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/10/07	< 13.00	No	No	
ASBESTOS-ST4-8/9/07	030727180-0003	Northwest Area (street-level)	8/9/07	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/10/07	< 13.00	No	No	
ASBESTOS-ST5-8/9/07	030727180-0004	Firehouse #10 (roof level)	8/9/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/10/07	< 13.00	No	No	
ASBESTOS-ST10-8/9/07	030727180-0005	North Side Sidewalk Bridge	8/9/07	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/10/07	< 13.00	No	No	
ASBESTOS-ST11-8/9/07	030727180-0006	90 Trinity Place (roof level)	8/9/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/10/07	< 13.00	No	No	
ASBESTOS-ST12-8/9/07	030727180-0007	110 Greenwich Street (roof level)	8/9/07	1	2.650	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/10/07	< 13.00	No	No	
ASBESTOS-ST13-8/9/07	030727180-0008	Marriott Hotel, 38th Floor (roof level)	8/9/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/10/07	< 13.00	No	No	
ASBESTOS-ST14-8/9/07	030727180-0009	West Face - South end at corner (scaffolding level)	8/9/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/10/07	< 13.00	No	No	
ASBESTOS-ST15-8/9/07	030727180-0010	South Face - East end at corner (scaffolding level)	8/9/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/10/07	< 13.00	No	No	
ASBESTOS-ST16-8/9/07	030727180-0011	East Face - North end at corner (scaffolding level)	8/9/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/10/07	< 13.00	No	No	
ASBESTOS-ST17-8/9/07	030727180-0012	North Face - West end at corner (scaffolding level)	8/9/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/10/07	< 13.00	No	No	
ASBESTOS-ST1-8/10/07	030727270-0001	Southwest Area (sidewalk bridge level)	8/10/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/07	< 13.00	No	No	
ASBESTOS-ST2-8/10/07	030727270-0002	Southeast Area (sidewalk bridge level)	8/10/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/07	< 13.00	No	No	
ASBESTOS-ST4-8/10/07	030727270-0003	Northwest Area (street-level)	8/10/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/07	< 13.00	No	No	
ASBESTOS-ST5-8/10/07	030727270-0004	Firehouse #10 (roof level)	8/10/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/07	< 13.00	No	No	
ASBESTOS-ST10-8/10/07	030727270-0005	North Side Sidewalk Bridge	8/10/07	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/07	< 13.00	No	No	
ASBESTOS-ST11-8/10/07	030727270-0006	90 Trinity Place (roof level)	8/10/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/07	< 13.00	No	No	
ASBESTOS-ST12-8/10/07	030727270-0007	110 Greenwich Street (roof level)	8/10/07	1	2.580	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/07	< 13.00	No	No	
ASBESTOS-ST13-8/10/07	030727270-0008	Marriott Hotel, 38th Floor (roof level)	8/10/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/07	< 13.00	No	No	
ASBESTOS-ST14-8/10/07	030727270-0009	West Face - South end at corner (scaffolding level)	8/10/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/07	< 13.00	No	No	
ASBESTOS-ST15-8/10/07	030727270-0010	South Face - East end at corner (scaffolding level)	8/10/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/07	< 13.00	No	No	
ASBESTOS-ST16-8/10/07	030727270-0011	East Face - North end at corner (scaffolding level)	8/10/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/07	< 13.00	No	No	
ASBESTOS-ST17-8/10/07	030727270-0012	North Face - West end at corner (scaffolding level)	8/10/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/07	< 13.00	No	No	

Note:

- Asbestos samples at Station 4 (Northwest Area [street-level]) and Station 12 (110 Greenwich Street [roof level]) on August 8, 2007 were not available for analysis on account of power failure.