

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels											70	Levels	Trigger Levels	
ASBESTOS-ST1-8/16/06	030626762-0001	Southwest Area (sidewalk bridge level)	8/16/06	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST2-8/16/06	030626762-0002	Southeast Area (sidewalk bridge level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST4-8/16/06	030626762-0003	Northwest Area (street-level)	8/16/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST5-8/16/06	030626762-0004	Firehouse #10 (roof level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST6-8/16/06	030626763-0001	Southwest Area (roof level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST7-8/16/06	030626763-0002	Southeast Area (roof level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST8-8/16/06	030626763-0003	Northeast Area (roof level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST9-8/16/06	030626763-0004	Northwest Area (roof level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST10-8/16/06	030626762-0005	North Side Sidewalk Bridge	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST100-8/16/06	030626762-0013	Station 10 Field Duplicate	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST11-8/16/06	030626762-0006	90 Trinity Place (roof level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST12-8/16/06	030626762-0007	110 Greenwich Street (roof level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST13-8/16/06	030626762-0008	Marriott Hotel, 38th Floor (roof level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST14-8/16/06	030626762-0009	West Face - South end at corner (scaffolding level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST15-8/16/06	030626762-0010	South Face - East end at corner (scaffolding level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST16-8/16/06	030626762-0011	East Face - North end at corner (scaffolding level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST17-8/16/06	030626762-0012	North Face - West end at corner (scaffolding level)	8/16/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/17/06	< 13.00	No	No		
ASBESTOS-ST1-8/17/06	030626912-0001	Southwest Area (sidewalk bridge level)	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST2-8/17/06	030626912-0002	Southeast Area (sidewalk bridge level)	8/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST4-8/17/06	030626912-0003	Northwest Area (street-level)	8/17/06	1	3.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No	Note 1.	
ASBESTOS-ST5-8/17/06	030626912-0004	Firehouse #10 (roof level)	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST6-8/17/06	030626915-0001	Southwest Area (roof level)	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST7-8/17/06	030626915-0002	Southeast Area (roof level)	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST8-8/17/06	030626915-0003	Northeast Area (roof level)	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST9-8/17/06	030626915-0004	Northwest Area (roof level)	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST10-8/17/06	030626912-0005	North Side Sidewalk Bridge	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST11-8/17/06	030626912-0006	90 Trinity Place (roof level)	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST12-8/17/06	030626912-0007	110 Greenwich Street (roof level)	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST13-8/17/06	030626912-0008	Marriott Hotel, 38th Floor (roof level)	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST14-8/17/06	030626912-0009	West Face - South end at corner (scaffolding level)	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST15-8/17/06	030626912-0010	South Face - East end at corner (scaffolding level)	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST16-8/17/06	030626912-0011	East Face - North end at corner (scaffolding level)	8/17/06	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		
ASBESTOS-ST17-8/17/06	030626912-0012	North Face - West end at corner (scaffolding level)	8/17/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/18/06	< 13.00	No	No		

Note:

1. Due to a flow rate RPD exceedance at Station 4 (Northwest Area [street-level]) on August 17, 2006, the sample volume and subsequent sample result are estimated.