

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA			
										70			
ASBESTOS-ST5-8/27/07	030729524-0001	Firehouse #10 (roof level)	8/27/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/07	< 11.00	No	No	
ASBESTOS-ST10-8/27/07	030729524-0002	North Side Sidewalk Bridge	8/27/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/07	< 11.00	No	No	
ASBESTOS-ST11-8/27/07	030729524-0003	90 Trinity Place (roof level)	8/27/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/07	< 11.00	No	No	
ASBESTOS-ST12-8/27/07	030729524-0004	110 Greenwich Street (roof level)	8/27/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/07	< 11.00	No	No	
ASBESTOS-ST13-8/27/07	030729524-0005	Marriott Hotel, 38th Floor (roof level)	8/27/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/07	< 11.00	No	No	

Note:

- Asbestos samples at Station 1 (Southwest Area [sidewalk bridge level]), Station 2 (Southeast Area [sidewalk bridge level]) and Station 4 (Northwest Area [street-level]) on August 27, 2007 were not collected. The stations were not accessible on account of a fire at 130 Liberty Street that caused unsafe conditions in the vicinity of the stations.
- Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]) and Station 17 (North Face - West end at corner [scaffolding level]) on August 27, 2007 were not collected on account of sampler error.