

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target | Exceeds EPA | Comments | |
|----------------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|--------------------|------------------------------|----------|--|
| | | | | | | | | | | NA | Air Quality Levels | Site Specific Trigger Levels | | |
| | | | | | | | | | | 70 | | | | |
| Target Air Quality Levels | | | | | | | | | | | | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | | | | | |
| ASBESTOS-ST1-9/12/07 | 030731127-0001 | Southwest Area (sidewalk bridge level) | 9/12/07 | 1 | 2.840 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 13.00 | No | No | | |
| ASBESTOS-ST2-9/12/07 | 030731127-0002 | Southeast Area (sidewalk bridge level) | 9/12/07 | 1 | 2.960 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 13.00 | No | No | | |
| ASBESTOS-ST4-9/12/07 | 030731127-0003 | Northwest Area (street-level) | 9/12/07 | 1 | 2.880 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 13.00 | No | No | | |
| ASBESTOS-ST5-9/12/07 | 030731127-0004 | Firehouse #10 (roof level) | 9/12/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 13.00 | No | No | | |
| ASBESTOS-ST10-9/12/07 | 030731127-0005 | North Side Sidewalk Bridge | 9/12/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 13.00 | No | No | | |
| ASBESTOS-ST100-9/12/07 | 030731127-0013 | Station 10 Field Duplicate | 9/12/07 | 1 | 3.070 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 13.00 | No | No | | |
| ASBESTOS-ST11-9/12/07 | 030731127-0006 | 90 Trinity Place (roof level) | 9/12/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 13.00 | No | No | | |
| ASBESTOS-ST12-9/12/07 | 030731127-0007 | 110 Greenwich Street (roof level) | 9/12/07 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 13.00 | No | No | | |
| ASBESTOS-ST13-9/12/07 | 030731127-0008 | Marriott Hotel, 38th Floor (roof level) | 9/12/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 13.00 | No | No | | |
| ASBESTOS-ST14-9/12/07 | 030731127-0009 | West Face - South end at corner (scaffolding level) | 9/12/07 | 1 | 2.280 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 11.00 | No | No | | |
| ASBESTOS-ST15-9/12/07 | 030731127-0010 | South Face - East end at corner (scaffolding level) | 9/12/07 | 1 | 2.250 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 11.00 | No | No | | |
| ASBESTOS-ST16-9/12/07 | 030731127-0011 | East Face - North end at corner (scaffolding level) | 9/12/07 | 1 | 2.300 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 11.00 | No | No | | |
| ASBESTOS-ST17-9/12/07 | 030731127-0012 | North Face - West end at corner (scaffolding level) | 9/12/07 | 1 | 2.230 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/13/07 | < 11.00 | No | No | | |
| ASBESTOS-ST1-9/13/07 | 03073142-0001 | Southwest Area (sidewalk bridge level) | 9/13/07 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/14/07 | < 13.00 | No | No | | |
| ASBESTOS-ST2-9/13/07 | 03073142-0002 | Southeast Area (sidewalk bridge level) | 9/13/07 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/14/07 | < 13.00 | No | No | | |
| ASBESTOS-ST4-9/13/07 | 03073142-0003 | Northwest Area (street-level) | 9/13/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/14/07 | < 13.00 | No | No | | |
| ASBESTOS-ST5-9/13/07 | 03073142-0004 | Firehouse #10 (roof level) | 9/13/07 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/14/07 | < 13.00 | No | No | | |
| ASBESTOS-ST10-9/13/07 | 03073142-0005 | North Side Sidewalk Bridge | 9/13/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/14/07 | < 13.00 | No | No | | |
| ASBESTOS-ST11-9/13/07 | 03073142-0006 | 90 Trinity Place (roof level) | 9/13/07 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/14/07 | < 13.00 | No | No | | |
| ASBESTOS-ST12-9/13/07 | 03073142-0007 | 110 Greenwich Street (roof level) | 9/13/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/14/07 | < 13.00 | No | No | | |
| ASBESTOS-ST13-9/13/07 | 03073142-0008 | Marriott Hotel, 38th Floor (roof level) | 9/13/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/14/07 | < 13.00 | No | No | | |
| ASBESTOS-ST14-9/13/07 | 03073142-0009 | West Face - South end at corner (scaffolding level) | 9/13/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/14/07 | < 13.00 | No | No | | |
| ASBESTOS-ST15-9/13/07 | 03073142-0010 | South Face - East end at corner (scaffolding level) | 9/13/07 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/14/07 | < 13.00 | No | No | | |
| ASBESTOS-ST16-9/13/07 | 03073142-0011 | East Face - North end at corner (scaffolding level) | 9/13/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/14/07 | < 13.00 | No | No | | |
| ASBESTOS-ST17-9/13/07 | 03073142-0012 | North Face - West end at corner (scaffolding level) | 9/13/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/14/07 | < 13.00 | No | No | | |