

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-9/16/09	030923885-0001	Southwest Area (sidewalk bridge level)	9/16/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/17/09	< 13.00	No	No	
ASBESTOS-ST2-9/16/09	030923885-0002	Southeast Area (sidewalk bridge level)	9/16/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/17/09	< 13.00	No	No	
ASBESTOS-ST4-9/16/09	030923885-0003	Northwest Area (street-level)	9/16/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/17/09	< 13.00	No	No	
ASBESTOS-ST5-9/16/09	030923885-0004	Firehouse #10 (roof level)	9/16/09	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/17/09	< 13.00	No	No	
ASBESTOS-ST10-9/16/09	030923885-0005	North Side Sidewalk Bridge	9/16/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/17/09	< 13.00	No	No	
ASBESTOS-ST100-9/16/09	030923885-0009	Station 10 Field Duplicate	9/16/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/17/09	< 13.00	No	No	
ASBESTOS-ST11-9/16/09	030923885-0006	90 Trinity Place (roof level)	9/16/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/17/09	< 13.00	No	No	
ASBESTOS-ST12-9/16/09	030923885-0007	110 Greenwich Street (roof level)	9/16/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/17/09	< 13.00	No	No	
ASBESTOS-ST13-9/16/09	030923885-0008	Marriott Hotel, 38th Floor (roof level)	9/16/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/17/09	< 13.00	No	No	
ASBESTOS-ST1-9/17/09	030923994-0001	Southwest Area (sidewalk bridge level)	9/17/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/09	< 13.00	No	No	
ASBESTOS-ST2-9/17/09	030923994-0002	Southeast Area (sidewalk bridge level)	9/17/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/09	< 13.00	No	No	
ASBESTOS-ST4-9/17/09	030923994-0003	Northwest Area (street-level)	9/17/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/09	< 13.00	No	No	
ASBESTOS-ST5-9/17/09	030923994-0004	Firehouse #10 (roof level)	9/17/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/09	< 13.00	No	No	
ASBESTOS-ST10-9/17/09	030923994-0005	North Side Sidewalk Bridge	9/17/09	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/09	< 13.00	No	No	
ASBESTOS-ST11-9/17/09	030923994-0006	90 Trinity Place (roof level)	9/17/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/09	< 13.00	No	No	
ASBESTOS-ST12-9/17/09	030923994-0007	110 Greenwich Street (roof level)	9/17/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/09	< 13.00	No	No	
ASBESTOS-ST13-9/17/09	030923994-0008	Marriott Hotel, 38th Floor (roof level)	9/17/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/09	< 13.00	No	No	
ASBESTOS-ST1-9/18/09	030924089-0001	Southwest Area (sidewalk bridge level)	9/18/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/09	< 13.00	No	No	
ASBESTOS-ST2-9/18/09	030924089-0002	Southeast Area (sidewalk bridge level)	9/18/09	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/09	< 13.00	No	No	
ASBESTOS-ST4-9/18/09	030924089-0003	Northwest Area (street-level)	9/18/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/09	< 13.00	No	No	
ASBESTOS-ST5-9/18/09	030924089-0004	Firehouse #10 (roof level)	9/18/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/09	< 13.00	No	No	
ASBESTOS-ST10-9/18/09	030924089-0005	North Side Sidewalk Bridge	9/18/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/09	< 13.00	No	No	
ASBESTOS-ST11-9/18/09	030924089-0006	90 Trinity Place (roof level)	9/18/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/09	< 13.00	No	No	
ASBESTOS-ST12-9/18/09	030924089-0007	110 Greenwich Street (roof level)	9/18/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/09	< 15.00	No	No	
ASBESTOS-ST13-9/18/09	030924089-0008	Marriott Hotel, 38th Floor (roof level)	9/18/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/09	< 13.00	No	No	