

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
										NA	Air Quality	Exceeds EPA	
										70	Levels	Site Specific	
												Trigger Levels	
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-9/19/09	030924196-0001	Southwest Area (sidewalk bridge level)	9/19/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST2-9/19/09	030924196-0002	Southeast Area (sidewalk bridge level)	9/19/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST4-9/19/09	030924196-0003	Northwest Area (street-level)	9/19/09	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST5-9/19/09	030924196-0004	Firehouse #10 (roof level)	9/19/09	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST10-9/19/09	030924196-0005	North Side Sidewalk Bridge	9/19/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST11-9/19/09	030924196-0006	90 Trinity Place (roof level)	9/19/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST12-9/19/09	030924196-0007	110 Greenwich Street (roof level)	9/19/09	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST13-9/19/09	030924196-0008	Marriott Hotel, 38th Floor (roof level)	9/19/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST1-9/20/09	030924195-0001	Southwest Area (sidewalk bridge level)	9/20/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST2-9/20/09	030924195-0002	Southeast Area (sidewalk bridge level)	9/20/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST4-9/20/09	030924195-0003	Northwest Area (street-level)	9/20/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST5-9/20/09	030924195-0004	Firehouse #10 (roof level)	9/20/09	1	2.840	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST10-9/20/09	030924195-0005	North Side Sidewalk Bridge	9/20/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST11-9/20/09	030924195-0006	90 Trinity Place (roof level)	9/20/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST12-9/20/09	030924195-0007	110 Greenwich Street (roof level)	9/20/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST13-9/20/09	030924195-0008	Marriott Hotel, 38th Floor (roof level)	9/20/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/09	< 13.00	No	No	
ASBESTOS-ST1-9/21/09	030924310-0001	Southwest Area (sidewalk bridge level)	9/21/09	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/09	< 13.00	No	No	
ASBESTOS-ST2-9/21/09	030924310-0002	Southeast Area (sidewalk bridge level)	9/21/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/09	< 13.00	No	No	
ASBESTOS-ST4-9/21/09	030924310-0003	Northwest Area (street-level)	9/21/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/09	< 13.00	No	No	
ASBESTOS-ST5-9/21/09	030924310-0004	Firehouse #10 (roof level)	9/21/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/09	< 13.00	No	No	
ASBESTOS-ST10-9/21/09	030924310-0005	North Side Sidewalk Bridge	9/21/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/09	< 13.00	No	No	
ASBESTOS-ST11-9/21/09	030924310-0006	90 Trinity Place (roof level)	9/21/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/09	< 13.00	No	No	
ASBESTOS-ST12-9/21/09	030924310-0007	110 Greenwich Street (roof level)	9/21/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/09	< 13.00	No	No	
ASBESTOS-ST13-9/21/09	030924310-0008	Marriott Hotel, 38th Floor (roof level)	9/21/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/09	< 13.00	No	No	
ASBESTOS-ST1-9/22/09	030924418-0001	Southwest Area (sidewalk bridge level)	9/22/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/09	< 13.00	No	No	
ASBESTOS-ST2-9/22/09	030924418-0002	Southeast Area (sidewalk bridge level)	9/22/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/09	< 13.00	No	No	
ASBESTOS-ST4-9/22/09	030924418-0003	Northwest Area (street-level)	9/22/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/09	< 13.00	No	No	
ASBESTOS-ST5-9/22/09	030924418-0004	Firehouse #10 (roof level)	9/22/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/09	< 13.00	No	No	
ASBESTOS-ST10-9/22/09	030924418-0005	North Side Sidewalk Bridge	9/22/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/09	< 13.00	No	No	
ASBESTOS-ST11-9/22/09	030924418-0006	90 Trinity Place (roof level)	9/22/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/09	< 13.00	No	No	
ASBESTOS-ST12-9/22/09	030924418-0007	110 Greenwich Street (roof level)	9/22/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/09	< 13.00	No	No	
ASBESTOS-ST13-9/22/09	030924418-0008	Marriott Hotel, 38th Floor (roof level)	9/22/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/09	< 13.00	No	No	