

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA			
										70			
ASBESTOS-ST1-9/21/05A	030528252-0001	Southwest Area (street-level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST1-9/21/05B	030528252-0010	Southwest Area (street-level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST2-9/21/05A	030528252-0002	Southeast Area (street-level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST2-9/21/05B	030528252-0011	Southeast Area (street-level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST4-9/21/05A	030528252-0003	Northwest Area (street-level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST4-9/21/05B	030528252-0012	Northwest Area (street-level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST5-9/21/05A	030528252-0004	Firehouse #10 (roof level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST5-9/21/05B	030528252-0013	Firehouse #10 (roof level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST6-9/21/05A	030528252-0005	Southwest Area (roof level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST6-9/21/05B	030528252-0014	Southwest Area (roof level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST7-9/21/05A	030528252-0006	Southeast Area (roof level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST7-9/21/05B	030528252-0015	Southeast Area (roof level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST8-9/21/05A	030528252-0007	Northeast Area (roof level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST8-9/21/05B	030528252-0016	Northeast Area (roof level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST9-9/21/05A	030528252-0008	Northwest Area (roof level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST9-9/21/05B	030528252-0017	Northwest Area (roof level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST10-9/21/05A	030528252-0009	North Side Sidewalk Bridge	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST10-9/21/05B	030528252-0018	North Side Sidewalk Bridge	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST1-9/22/05A	030528386-0001	Southwest Area (street-level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST1-9/22/05B	030528386-0010	Southwest Area (street-level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST2-9/22/05A	030528386-0002	Southeast Area (street-level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST2-9/22/05B	030528386-0011	Southeast Area (street-level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST4-9/22/05A	030528386-0003	Northwest Area (street-level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST4-9/22/05B	030528386-0012	Northwest Area (street-level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST5-9/22/05A	030528386-0004	Firehouse #10 (roof level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST5-9/22/05B	030528386-0013	Firehouse #10 (roof level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST6-9/22/05A	030528386-0005	Southwest Area (roof level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST6-9/22/05B	030528386-0014	Southwest Area (roof level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST7-9/22/05A	030528386-0006	Southeast Area (roof level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST7-9/22/05B	030528386-0015	Southeast Area (roof level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST8-9/22/05A	030528386-0007	Northeast Area (roof level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST8-9/22/05B	030528386-0016	Northeast Area (roof level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST9-9/22/05A	030528386-0008	Northwest Area (roof level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST9-9/22/05B	030528386-0017	Northwest Area (roof level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST10-9/22/05A	030528386-0009	North Side Sidewalk Bridge	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST10-9/22/05B	030528386-0018	North Side Sidewalk Bridge	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	