

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-10/3/09	030925434-0001	Southwest Area (sidewalk bridge level)	10/3/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST2-10/3/09	030925434-0002	Southeast Area (sidewalk bridge level)	10/3/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST4-10/3/09	030925434-0003	Northwest Area (street-level)	10/3/09	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST5-10/3/09	030925434-0004	Firehouse #10 (roof level)	10/3/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST10-10/3/09	030925434-0005	North Side Sidewalk Bridge	10/3/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST11-10/3/09	030925434-0006	90 Trinity Place (roof level)	10/3/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST12-10/3/09	030925434-0007	110 Greenwich Street (roof level)	10/3/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST13-10/3/09	030925434-0008	Marriott Hotel, 38th Floor (roof level)	10/3/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST1-10/4/09	030925435-0001	Southwest Area (sidewalk bridge level)	10/4/09	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST2-10/4/09	030925435-0002	Southeast Area (sidewalk bridge level)	10/4/09	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST4-10/4/09	030925435-0003	Northwest Area (street-level)	10/4/09	1	3.290	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST5-10/4/09	030925435-0004	Firehouse #10 (roof level)	10/4/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST10-10/4/09	030925435-0005	North Side Sidewalk Bridge	10/4/09	1	3.270	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST11-10/4/09	030925435-0006	90 Trinity Place (roof level)	10/4/09	1	2.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST12-10/4/09	030925435-0007	110 Greenwich Street (roof level)	10/4/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	
ASBESTOS-ST13-10/4/09	030925435-0008	Marriott Hotel, 38th Floor (roof level)	10/4/09	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/09	< 13.00	No	No	