

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target | Exceeds EPA | Comments | |
|----------------------------------|----------------|-----------------------------------------------------|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|----------------|-------------|----------------|----------|
| Target Air Quality Levels | | | | | | | | | | | NA | Air Quality | Site Specific | Comments |
| EPA Site Specific Trigger Levels | | | | | | | | | | | 70 | Levels | Trigger Levels | |
| ASBESTOS-ST1-10/10/07 | 030733573-0001 | Southwest Area (sidewalk bridge level) | 10/10/07 | 1 | 3.070 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/11/07 | < 13.00 | No | No | | |
| ASBESTOS-ST2-10/10/07 | 030733573-0002 | Southeast Area (sidewalk bridge level) | 10/10/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/11/07 | < 13.00 | No | No | | |
| ASBESTOS-ST4-10/10/07 | 030733573-0003 | Northwest Area (street-level) | 10/10/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/11/07 | < 13.00 | No | No | | |
| ASBESTOS-ST5-10/10/07 | 030733573-0004 | Firehouse #10 (roof level) | 10/10/07 | 1 | 2.960 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/11/07 | < 13.00 | No | No | | |
| ASBESTOS-ST10-10/10/07 | 030733573-0005 | North Side Sidewalk Bridge | 10/10/07 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/11/07 | < 13.00 | No | No | | |
| ASBESTOS-ST11-10/10/07 | 030733573-0006 | 90 Trinity Place (roof level) | 10/10/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/11/07 | < 13.00 | No | No | | |
| ASBESTOS-ST12-10/10/07 | 030733573-0007 | 110 Greenwich Street (roof level) | 10/10/07 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/11/07 | < 13.00 | No | No | | |
| ASBESTOS-ST13-10/10/07 | 030733573-0008 | Marriott Hotel, 38th Floor (roof level) | 10/10/07 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/11/07 | < 13.00 | No | No | | |
| ASBESTOS-ST14-10/10/07 | 030733573-0009 | West Face - South end at corner (scaffolding level) | 10/10/07 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/11/07 | < 13.00 | No | No | | |
| ASBESTOS-ST15-10/10/07 | 030733573-0010 | South Face - East end at corner (scaffolding level) | 10/10/07 | 1 | 3.120 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/11/07 | < 13.00 | No | No | | |
| ASBESTOS-ST16-10/10/07 | 030733573-0011 | East Face - North end at corner (scaffolding level) | 10/10/07 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/11/07 | < 13.00 | No | No | | |
| ASBESTOS-ST17-10/10/07 | 030733573-0012 | North Face - West end at corner (scaffolding level) | 10/10/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/11/07 | < 13.00 | No | No | | |
| ASBESTOS-ST1-10/11/07 | 030733690-0001 | Southwest Area (sidewalk bridge level) | 10/11/07 | 1 | 2.980 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/12/07 | < 13.00 | No | No | | |
| ASBESTOS-ST4-10/11/07 | 030733690-0002 | Northwest Area (street-level) | 10/11/07 | 1 | 2.800 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/12/07 | < 13.00 | No | No | | |
| ASBESTOS-ST5-10/11/07 | 030733690-0003 | Firehouse #10 (roof level) | 10/11/07 | 1 | 2.960 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/12/07 | < 13.00 | No | No | | |
| ASBESTOS-ST10-10/11/07 | 030733690-0004 | North Side Sidewalk Bridge | 10/11/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/12/07 | < 13.00 | No | No | | |
| ASBESTOS-ST11-10/11/07 | 030733690-0005 | 90 Trinity Place (roof level) | 10/11/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/12/07 | < 13.00 | No | No | | |
| ASBESTOS-ST12-10/11/07 | 030733690-0006 | 110 Greenwich Street (roof level) | 10/11/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/12/07 | < 13.00 | No | No | | |
| ASBESTOS-ST14-10/11/07 | 030733690-0007 | West Face - South end at corner (scaffolding level) | 10/11/07 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/12/07 | < 13.00 | No | No | | |
| ASBESTOS-ST15-10/11/07 | 030733690-0008 | South Face - East end at corner (scaffolding level) | 10/11/07 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/12/07 | < 13.00 | No | No | | |
| ASBESTOS-ST16-10/11/07 | 030733690-0009 | East Face - North end at corner (scaffolding level) | 10/11/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/12/07 | < 13.00 | No | No | | |
| ASBESTOS-ST17-10/11/07 | 030733690-0010 | North Face - West end at corner (scaffolding level) | 10/11/07 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/12/07 | < 13.00 | No | No | | |
| ASBSETOS-ST1-10/12/07 | 030733780-0001 | Southwest Area (sidewalk bridge level) | 10/12/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/13/07 | < 13.00 | No | No | | |
| ASBSETOS-ST2-10/12/07 | 030733780-0002 | Southeast Area (sidewalk bridge level) | 10/12/07 | 1 | 2.620 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/13/07 | < 13.00 | No | No | | |
| ASBSETOS-ST4-10/12/07 | 030733780-0003 | Northwest Area (street-level) | 10/12/07 | 1 | 2.920 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/13/07 | < 13.00 | No | No | | |
| ASBSETOS-ST5-10/12/07 | 030733780-0004 | Firehouse #10 (roof level) | 10/12/07 | 1 | 3.150 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/13/07 | < 13.00 | No | No | | |
| ASBSETOS-ST10-10/12/07 | 030733780-0005 | North Side Sidewalk Bridge | 10/12/07 | 1 | 2.860 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/13/07 | < 13.00 | No | No | | |
| ASBSETOS-ST11-10/12/07 | 030733780-0006 | 90 Trinity Place (roof level) | 10/12/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/13/07 | < 13.00 | No | No | | |
| ASBSETOS-ST12-10/12/07 | 030733780-0007 | 110 Greenwich Street (roof level) | 10/12/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/13/07 | < 13.00 | No | No | | |
| ASBSETOS-ST13-10/12/07 | 030733780-0008 | Marriott Hotel, 38th Floor (roof level) | 10/12/07 | 1 | 2.960 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/13/07 | < 13.00 | No | No | | |
| ASBSETOS-ST14-10/12/07 | 030733780-0009 | West Face - South end at corner (scaffolding level) | 10/12/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/13/07 | < 13.00 | No | No | | |
| ASBSETOS-ST15-10/12/07 | 030733780-0010 | South Face - East end at corner (scaffolding level) | 10/12/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/13/07 | < 13.00 | No | No | | |
| ASBSETOS-ST16-10/12/07 | 030733780-0011 | East Face - North end at corner (scaffolding level) | 10/12/07 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/13/07 | < 13.00 | No | No | | |
| ASBSETOS-ST17-10/12/07 | 030733780-0012 | North Face - West end at corner (scaffolding level) | 10/12/07 | 1 | 2.980 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/13/07 | < 13.00 | No | No | | |

Note:

1. Asbestos sample at Station 2 (Southeast Area [sidewalk bridge level]) on October 11, 2007 was not available for analysis on account of power failure.
2. Asbestos sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on October 11, 2007 was not available for analysis on account of sample damage.