

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-10/15/07	030734027-0001	Southwest Area (sidewalk bridge level)	10/15/07	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/07	< 13.00	No	No	
ASBESTOS-ST2-10/15/07	030734027-0002	Southeast Area (sidewalk bridge level)	10/15/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/07	< 13.00	No	No	
ASBESTOS-ST4-10/15/07	030734027-0003	Northwest Area (street-level)	10/15/07	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/07	< 13.00	No	No	
ASBESTOS-ST5-10/15/07	030734027-0004	Firehouse #10 (roof level)	10/15/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/07	< 13.00	No	No	
ASBESTOS-ST10-10/15/07	030734027-0005	North Side Sidewalk Bridge	10/15/07	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/07	< 13.00	No	No	
ASBESTOS-ST11-10/15/07	030734027-0006	90 Trinity Place (roof level)	10/15/07	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/07	< 13.00	No	No	
ASBESTOS-ST12-10/15/07	030734027-0007	110 Greenwich Street (roof level)	10/15/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/07	< 13.00	No	No	
ASBESTOS-ST13-10/15/07	030734027-0008	Marriott Hotel, 38th Floor (roof level)	10/15/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/07	< 13.00	No	No	
ASBESTOS-ST14-10/15/07	030734027-0009	West Face - South end at corner (scaffolding level)	10/15/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/07	< 13.00	No	No	
ASBESTOS-ST15-10/15/07	030734027-0010	South Face - East end at corner (scaffolding level)	10/15/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/07	< 13.00	No	No	
ASBESTOS-ST17-10/15/07	030734027-0011	North Face - West end at corner (scaffolding level)	10/15/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/07	< 13.00	No	No	
ASBESTOS-ST1-10/16/07	030734128-0001	Southwest Area (sidewalk bridge level)	10/16/07	1	3.340	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/07	< 15.00	No	No	
ASBESTOS-ST2-10/16/07	030734128-0002	Southeast Area (sidewalk bridge level)	10/16/07	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/07	< 15.00	No	No	
ASBESTOS-ST4-10/16/07	030734128-0003	Northwest Area (street-level)	10/16/07	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/07	< 15.00	No	No	
ASBESTOS-ST5-10/16/07	030734128-0004	Firehouse #10 (roof level)	10/16/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/07	< 15.00	No	No	
ASBESTOS-ST10-10/16/07	030734128-0005	North Side Sidewalk Bridge	10/16/07	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/07	< 15.00	No	No	
ASBESTOS-ST11-10/16/07	030734128-0006	90 Trinity Place (roof level)	10/16/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/07	< 13.00	No	No	
ASBESTOS-ST12-10/16/07	030734128-0007	110 Greenwich Street (roof level)	10/16/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/07	< 13.00	No	No	
ASBESTOS-ST13-10/16/07	030734128-0008	Marriott Hotel, 38th Floor (roof level)	10/16/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/07	< 13.00	No	No	
ASBESTOS-ST14-10/16/07	030734128-0009	West Face - South end at corner (scaffolding level)	10/16/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/07	< 13.00	No	No	
ASBESTOS-ST15-10/16/07	030734128-0010	South Face - East end at corner (scaffolding level)	10/16/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/07	< 13.00	No	No	
ASBESTOS-ST16-10/16/07	030734128-0011	East Face - North end at corner (scaffolding level)	10/16/07	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/07	< 13.00	No	No	
ASBESTOS-ST17-10/16/07	030734128-0012	North Face - West end at corner (scaffolding level)	10/16/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/07	< 13.00	No	No	
ASBESTOS-ST1-10/17/07	030734233-0001	Southwest Area (sidewalk bridge level)	10/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	
ASBESTOS-ST2-10/17/07	030734233-0002	Southeast Area (sidewalk bridge level)	10/17/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	
ASBESTOS-ST4-10/17/07	030734233-0003	Northwest Area (street-level)	10/17/07	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	
ASBESTOS-ST5-10/17/07	030734233-0004	Firehouse #10 (roof level)	10/17/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	
ASBESTOS-ST10-10/17/07	030734233-0005	North Side Sidewalk Bridge	10/17/07	1	3.230	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	
ASBESTOS-ST100-10/17/07	030734233-0013	Station 10 Field Duplicate	10/17/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	
ASBESTOS-ST11-10/17/07	030734233-0006	90 Trinity Place (roof level)	10/17/07	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	
ASBESTOS-ST12-10/17/07	030734233-0007	110 Greenwich Street (roof level)	10/17/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	
ASBESTOS-ST13-10/17/07	030734233-0008	Marriott Hotel, 38th Floor (roof level)	10/17/07	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	
ASBESTOS-ST14-10/17/07	030734233-0009	West Face - South end at corner (scaffolding level)	10/17/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	
ASBESTOS-ST15-10/17/07	030734233-0010	South Face - East end at corner (scaffolding level)	10/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	
ASBESTOS-ST16-10/17/07	030734233-0011	East Face - North end at corner (scaffolding level)	10/17/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	
ASBESTOS-ST17-10/17/07	030734233-0012	North Face - West end at corner (scaffolding level)	10/17/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/18/07	< 13.00	No	No	

Note:

1. Asbestos sample at Station 16 (East Face - North end at corner (scaffolding level)) on October 15, 2007 was not available for analysis on account of pump failure.