

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>										<b>NA</b>			
<b>EPA Site Specific Trigger Levels</b>										<b>70</b>			
ASBESTOS-ST1-10/19/05	030531342-0001	Southwest Area (street-level)	10/19/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/20/2005	< 13.00	No	No	
ASBESTOS-ST2-10/19/05	030531342-0002	Southeast Area (sidewalk bridge level)	10/19/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/20/2005	< 13.00	No	No	
ASBESTOS-ST4-10/19/05	030531342-0003	Northwest Area (street-level)	10/19/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/20/2005	< 13.00	No	No	
ASBESTOS-ST5-10/19/05	030531342-0004	Firehouse #10 (roof level)	10/19/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/20/2005	< 13.00	No	No	
ASBESTOS-ST10-10/19/05	030531342-0005	North Side Sidewalk Bridge	10/19/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/20/2005	< 13.00	No	No	
ASBESTOS-ST11-10/19/05	030531342-0006	90 Trinity Place (roof level)	10/19/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/20/2005	< 13.00	No	No	
ASBESTOS-ST12-10/19/05	030531342-0007	110 Greenwich Street (roof level)	10/19/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/20/2005	< 13.00	No	No	
ASBESTOS-ST13-10/19/05	030531342-0008	Marriott Hotel, 38th Floor (roof level)	10/19/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/20/2005	< 13.00	No	No	
ASBESTOS-ST1-10/20/05	030531481-0001	Southwest Area (street-level)	10/20/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/21/2005	< 13.00	No	No	
ASBESTOS-ST2-10/20/05	030531481-0002	Southeast Area (sidewalk bridge level)	10/20/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/21/2005	< 13.00	No	No	
ASBESTOS-ST4-10/20/05	030531481-0003	Northwest Area (street-level)	10/20/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/21/2005	< 13.00	No	No	
ASBESTOS-ST5-10/20/05	030531481-0004	Firehouse #10 (roof level)	10/20/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/21/2005	< 13.00	No	No	
ASBESTOS-ST10-10/20/05	030531481-0005	North Side Sidewalk Bridge	10/20/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/21/2005	< 13.00	No	No	
ASBESTOS-ST11-10/20/05	030531481-0006	90 Trinity Place (roof level)	10/20/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/21/2005	< 13.00	No	No	
ASBESTOS-ST12-10/20/05	030531481-0007	110 Greenwich Street (roof level)	10/20/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/21/2005	< 13.00	No	No	
ASBESTOS-ST13-10/20/05	030531481-0008	Marriott Hotel, 38th Floor (roof level)	10/20/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/21/2005	< 13.00	No	No	