

| TRC Field Sample No.             | Sample No.     | Sampling Location                                   | Collection Start Date | Work Shift | Sample Volume (m <sup>3</sup> ) | Analyte  | Analytical Method               | Lab  | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|----------------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|-----------------------------------|--|----------|
| Target Air Quality Levels        |                |   |                       |            |                                 |          |                                 |      |                         |                                      | NA                                |  |          |
| EPA Site Specific Trigger Levels |                |   |                       |            |                                 |          |                                 |      |                         |                                      | 70                                |  |          |
| ASBESTOS-ST1-10/29/08            | 030838634-0001 | Southwest Area (sidewalk bridge level)              | 10/29/08              | 1          | 3.110                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/30/08                | < 15.00                              | No                                | No                                       |          |
| ASBESTOS-ST2-10/29/08            | 030838634-0002 | Southeast Area (sidewalk bridge level)              | 10/29/08              | 1          | 3.080                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/30/08                | < 15.00                              | No                                | No                                       |          |
| ASBESTOS-ST4-10/29/08            | 030838634-0003 | Northwest Area (street-level)                       | 10/29/08              | 1          | 2.880                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/30/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST5-10/29/08            | 030838634-0004 | Firehouse #10 (roof level)                          | 10/29/08              | 1          | 2.990                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/30/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST10-10/29/08           | 030838634-0005 | North Side Sidewalk Bridge                          | 10/29/08              | 1          | 3.040                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/30/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST11-10/29/08           | 030838634-0006 | 90 Trinity Place (roof level)                       | 10/29/08              | 1          | 2.990                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/30/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST12-10/29/08           | 030838634-0007 | 110 Greenwich Street (roof level)                   | 10/29/08              | 1          | 3.050                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/30/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST13-10/29/08           | 030838634-0008 | Marriott Hotel, 38th Floor (roof level)             | 10/29/08              | 1          | 3.080                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/30/08                | < 15.00                              | No                                | No                                       |          |
| ASBESTOS-ST14-10/29/08           | 030838634-0009 | West Face - South end at corner (scaffolding level) | 10/29/08              | 1          | 3.050                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/30/08                | < 15.00                              | No                                | No                                       |          |
| ASBESTOS-ST15-10/29/08           | 030838634-0010 | South Face - East end at corner (scaffolding level) | 10/29/08              | 1          | 3.060                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/30/08                | < 15.00                              | No                                | No                                       |          |
| ASBESTOS-ST16-10/29/08           | 030838634-0011 | East Face - North end at corner (scaffolding level) | 10/29/08              | 1          | 3.100                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/30/08                | < 15.00                              | No                                | No                                       |          |
| ASBESTOS-ST17-10/29/08           | 030838634-0012 | North Face - West end at corner (scaffolding level) | 10/29/08              | 1          | 3.290                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/30/08                | < 15.00                              | No                                | No                                       |          |
| ASBESTOS-ST1-10/30/08            | 030838781-0001 | Southwest Area (sidewalk bridge level)              | 10/30/08              | 1          | 2.750                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/31/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST2-10/30/08            | 030838781-0002 | Southeast Area (sidewalk bridge level)              | 10/30/08              | 1          | 3.080                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/31/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST4-10/30/08            | 030838781-0003 | Northwest Area (street-level)                       | 10/30/08              | 1          | 3.080                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/31/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST5-10/30/08            | 030838781-0004 | Firehouse #10 (roof level)                          | 10/30/08              | 1          | 3.020                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/31/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST10-10/30/08           | 030838781-0005 | North Side Sidewalk Bridge                          | 10/30/08              | 1          | 3.130                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/31/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST11-10/30/08           | 030838781-0006 | 90 Trinity Place (roof level)                       | 10/30/08              | 1          | 3.060                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/31/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST12-10/30/08           | 030838781-0007 | 110 Greenwich Street (roof level)                   | 10/30/08              | 1          | 3.060                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/31/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST13-10/30/08           | 030838781-0008 | Marriott Hotel, 38th Floor (roof level)             | 10/30/08              | 1          | 3.080                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/31/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST14-10/30/08           | 030838781-0009 | West Face - South end at corner (scaffolding level) | 10/30/08              | 1          | 2.990                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/31/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST15-10/30/08           | 030838781-0010 | South Face - East end at corner (scaffolding level) | 10/30/08              | 1          | 3.110                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/31/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST16-10/30/08           | 030838781-0011 | East Face - North end at corner (scaffolding level) | 10/30/08              | 1          | 3.070                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/31/08                | < 13.00                              | No                                | No                                       |          |
| ASBESTOS-ST17-10/30/08           | 030838781-0012 | North Face - West end at corner (scaffolding level) | 10/30/08              | 1          | 3.030                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 10/31/08                | < 13.00                              | No                                | No                                       |          |