

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-11/03/06	030636195-0001	Southwest Area (sidewalk bridge level)	11/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST2-11/03/06	030636195-0002	Southeast Area (sidewalk bridge level)	11/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST4-11/03/06	030636195-0003	Northwest Area (street-level)	11/3/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST5-11/03/06	030636195-0004	Firehouse #10 (roof level)	11/3/06	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST10-11/03/06	030636195-0005	North Side Sidewalk Bridge	11/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST11-11/03/06	030636195-0006	90 Trinity Place (roof level)	11/3/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST12-11/03/06	030636195-0007	110 Greenwich Street (roof level)	11/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST13-11/03/06	030636195-0008	Marriott Hotel, 38th Floor (roof level)	11/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST14-11/03/06	030636195-0009	West Face - South end at corner (scaffolding level)	11/3/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST15-11/03/06	030636195-0010	South Face - East end at corner (scaffolding level)	11/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST16-11/03/06	030636195-0011	East Face - North end at corner (scaffolding level)	11/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST17-11/03/06	030636195-0012	North Face - West end at corner (scaffolding level)	11/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST1-11/04/06	030636196-0001	Southwest Area (sidewalk bridge level)	11/4/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST2-11/04/06	030636196-0002	Southeast Area (sidewalk bridge level)	11/4/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST4-11/04/06	030636196-0003	Northwest Area (street-level)	11/4/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST5-11/04/06	030636196-0004	Firehouse #10 (roof level)	11/4/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST10-11/04/06	030636196-0005	North Side Sidewalk Bridge	11/4/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST11-11/04/06	030636196-0006	90 Trinity Place (roof level)	11/4/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST12-11/04/06	030636196-0007	110 Greenwich Street (roof level)	11/4/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST13-11/04/06	030636196-0008	Marriott Hotel, 38th Floor (roof level)	11/4/06	1	2.840	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST14-11/04/06	030636196-0009	West Face - South end at corner (scaffolding level)	11/4/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST15-11/04/06	030636196-0010	South Face - East end at corner (scaffolding level)	11/4/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST16-11/04/06	030636196-0011	East Face - North end at corner (scaffolding level)	11/4/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST17-11/04/06	030636196-0012	North Face - West end at corner (scaffolding level)	11/4/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST1-11/05/06	030636197-0001	Southwest Area (sidewalk bridge level)	11/5/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST2-11/05/06	030636197-0002	Southeast Area (sidewalk bridge level)	11/5/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST4-11/05/06	030636197-0003	Northwest Area (street-level)	11/5/06	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST5-11/05/06	030636197-0004	Firehouse #10 (roof level)	11/5/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST10-11/05/06	030636197-0005	North Side Sidewalk Bridge	11/5/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST11-11/05/06	030636197-0006	90 Trinity Place (roof level)	11/5/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST12-11/05/06	030636197-0007	110 Greenwich Street (roof level)	11/5/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST13-11/05/06	030636197-0008	Marriott Hotel, 38th Floor (roof level)	11/5/06	1	2.840	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST14-11/05/06	030636197-0009	West Face - South end at corner (scaffolding level)	11/5/06	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST15-11/05/06	030636197-0010	South Face - East end at corner (scaffolding level)	11/5/06	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST16-11/05/06	030636197-0011	East Face - North end at corner (scaffolding level)	11/5/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST17-11/05/06	030636197-0012	North Face - West end at corner (scaffolding level)	11/5/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/6/06	< 13.00		No	No	
ASBESTOS-ST1-11/06/06	030636337-0001	Southwest Area (sidewalk bridge level)	11/6/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/06	< 13.00		No	No	
ASBESTOS-ST2-11/06/06	030636337-0002	Southeast Area (sidewalk bridge level)	11/6/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/06	< 13.00		No	No	
ASBESTOS-ST4-11/06/06	030636337-0003	Northwest Area (street-level)	11/6/06	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/06	< 13.00		No	No	
ASBESTOS-ST5-11/06/06	030636337-0004	Firehouse #10 (roof level)	11/6/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/06	< 13.00		No	No	
ASBESTOS-ST10-11/06/06	030636337-0005	North Side Sidewalk Bridge	11/6/06	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/06	< 13.00		No	No	
ASBESTOS-ST11-11/06/06	030636337-0006	90 Trinity Place (roof level)	11/6/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/06	< 13.00		No	No	
ASBESTOS-ST12-11/06/06	030636337-0007	110 Greenwich Street (roof level)	11/6/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/06	< 13.00		No	No	
ASBESTOS-ST13-11/06/06	030636337-0008	Marriott Hotel, 38th Floor (roof level)	11/6/06	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/06	< 13.00		No	No	
ASBESTOS-ST14-11/06/06	030636337-0009	West Face - South end at corner (scaffolding level)	11/6/06	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/06	< 13.00		No	No	
ASBESTOS-ST15-11/06/06	030636337-0010	South Face - East end at corner (scaffolding level)	11/6/06	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/06	< 13.00		No	No	
ASBESTOS-ST16-11/06/06	030636337-0011	East Face - North end at corner (scaffolding level)	11/6/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/06	< 13.00		No	No	
ASBESTOS-ST17-11/06/06	030636337-0012	North Face - West end at corner (scaffolding level)	11/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/06	< 13.00		No	No	