

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels										70	Levels	Trigger Levels	
ASBESTOS-ST1-11/10/07	030736392-0001	Southwest Area (sidewalk bridge level)	11/10/07	1	2.780	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST2-11/10/07	030736392-0002	Southeast Area (sidewalk bridge level)	11/10/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST4-11/10/07	030736392-0003	Northwest Area (street-level)	11/10/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST5-11/10/07	030736392-0004	Firehouse #10 (roof level)	11/10/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST10-11/10/07	030736392-0005	North Side Sidewalk Bridge	11/10/07	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST11-11/10/07	030736392-0006	90 Trinity Place (roof level)	11/10/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST12-11/10/07	030736392-0007	110 Greenwich Street (roof level)	11/10/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST13-11/10/07	030736392-0008	Marriott Hotel, 38th Floor (roof level)	11/10/07	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 15.00	No	No	
ASBESTOS-ST14-11/10/07	030736392-0009	West Face - South end at corner (scaffolding level)	11/10/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST15-11/10/07	030736392-0010	South Face - East end at corner (scaffolding level)	11/10/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 15.00	No	No	
ASBESTOS-ST16-11/10/07	030736392-0011	East Face - North end at corner (scaffolding level)	11/10/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST17-11/10/07	030736392-0012	North Face - West end at corner (scaffolding level)	11/10/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST1-11/11/07	030736424-0001	Southwest Area (sidewalk bridge level)	11/11/07	1	3.340	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 15.00	No	No	
ASBESTOS-ST2-11/11/07	030736424-0002	Southeast Area (sidewalk bridge level)	11/11/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 15.00	No	No	
ASBESTOS-ST4-11/11/07	030736424-0003	Northwest Area (street-level)	11/11/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 15.00	No	No	
ASBESTOS-ST5-11/11/07	030736424-0004	Firehouse #10 (roof level)	11/11/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 15.00	No	No	
ASBESTOS-ST10-11/11/07	030736424-0005	North Side Sidewalk Bridge	11/11/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST11-11/11/07	030736424-0006	90 Trinity Place (roof level)	11/11/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 15.00	No	No	
ASBESTOS-ST12-11/11/07	030736424-0007	110 Greenwich Street (roof level)	11/11/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST13-11/11/07	030736424-0008	Marriott Hotel, 38th Floor (roof level)	11/11/07	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST14-11/11/07	030736424-0009	West Face - South end at corner (scaffolding level)	11/11/07	1	2.840	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST15-11/11/07	030736424-0010	South Face - East end at corner (scaffolding level)	11/11/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST16-11/11/07	030736424-0011	East Face - North end at corner (scaffolding level)	11/11/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST17-11/11/07	030736424-0012	North Face - West end at corner (scaffolding level)	11/11/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/07	< 13.00	No	No	
ASBESTOS-ST1-11/12/07	030736517-0001	Southwest Area (sidewalk bridge level)	11/12/07	1	2.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST2-11/12/07	030736517-0002	Southeast Area (sidewalk bridge level)	11/12/07	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST4-11/12/07	030736517-0003	Northwest Area (street-level)	11/12/07	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST5-11/12/07	030736517-0004	Firehouse #10 (roof level)	11/12/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST10-11/12/07	030736517-0005	North Side Sidewalk Bridge	11/12/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST100-11/12/07	030736517-0013	Station 10 Field Duplicate	11/12/07	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST11-11/12/07	030736517-0006	90 Trinity Place (roof level)	11/12/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST12-11/12/07	030736517-0007	110 Greenwich Street (roof level)	11/12/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST13-11/12/07	030736517-0008	Marriott Hotel, 38th Floor (roof level)	11/12/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST14-11/12/07	030736517-0009	West Face - South end at corner (scaffolding level)	11/12/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST15-11/12/07	030736517-0010	South Face - East end at corner (scaffolding level)	11/12/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST16-11/12/07	030736517-0011	East Face - North end at corner (scaffolding level)	11/12/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST17-11/12/07	030736517-0012	North Face - West end at corner (scaffolding level)	11/12/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/13/07	< 13.00	No	No	
ASBESTOS-ST1-11/13/07	030736628-0001	Southwest Area (sidewalk bridge level)	11/13/07	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/07	< 13.00	No	No	
ASBESTOS-ST2-11/13/07	030736628-0002	Southeast Area (sidewalk bridge level)	11/13/07	1	2.840	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/07	< 13.00	No	No	
ASBESTOS-ST4-11/13/07	030736628-0003	Northwest Area (street-level)	11/13/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/07	< 13.00	No	No	
ASBESTOS-ST5-11/13/07	030736628-0004	Firehouse #10 (roof level)	11/13/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/07	13.00	No	No	
ASBESTOS-ST10-11/13/07	030736628-0005	North Side Sidewalk Bridge	11/13/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/07	< 13.00	No	No	
ASBESTOS-ST11-11/13/07	030736628-0006	90 Trinity Place (roof level)	11/13/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/07	< 13.00	No	No	
ASBESTOS-ST12-11/13/07	030736628-0007	110 Greenwich Street (roof level)	11/13/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/07	< 13.00	No	No	
ASBESTOS-ST13-11/13/07	030736628-0008	Marriott Hotel, 38th Floor (roof level)	11/13/07	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/07	< 13.00	No	No	
ASBESTOS-ST14-11/13/07	030736628-0009	West Face - South end at corner (scaffolding level)	11/13/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/07	< 13.00	No	No	
ASBESTOS-ST15-11/13/07	030736628-0010	South Face - East end at corner (scaffolding level)	11/13/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/07	< 13.00	No	No	
ASBESTOS-ST16-11/13/07	030736628-0011	East Face - North end at corner (scaffolding level)	11/13/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/07	< 13.00	No	No	
ASBESTOS-ST17-11/13/07	030736628-0012	North Face - West end at corner (scaffolding level)	11/13/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/07	< 13.00	No	No	
ASBESTOS-ST1-11/14/07	030736719-0001	Southwest Area (sidewalk bridge level)	11/14/07	1	2.850	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/07	13.00	No	No	
ASBESTOS-ST2-11/14/07	030736719-0002	Southeast Area (sidewalk bridge level)	11/14/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/07	26.00	No	No	
ASBESTOS-ST4-11/14/07	030736719-0003	Northwest Area (street-level)	11/14/07	1	3.340	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/07	< 13.00	No	No	
ASBESTOS-ST5-11/14/07	030736719-0004	Firehouse #10 (roof level)	11/14/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/07	< 13.00	No	No	
ASBESTOS-ST10-11/14/07	030736719-0005	North Side Sidewalk Bridge	11/14/07	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/07	< 13.00	No	No	
ASBESTOS-ST11-11/14/07	030736719-0006	90 Trinity Place (roof level)	11/14/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/07	< 13.00	No	No	
ASBESTOS-ST12-11/14/07	030736719-0007	110 Greenwich Street (roof level)	11/14/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/07	< 13.00	No	No	
ASBESTOS-ST13-11/14/07	030736719-0008	Marriott Hotel, 38th Floor (roof level)	11/14/07	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/07	< 13.00	No	No	
ASBESTOS-ST14-11/14/07	030736719-0009	West Face - South end at corner (scaffolding level)	11/14/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/07	< 13.00	No	No	
ASBESTOS-ST15-11/14/07	030736719-0010	South Face - East end at corner (scaffolding level)	11/14/07	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/07	< 13.00	No	No	
ASBESTOS-ST16-11/14/07	030736719-0011	East Face - North end at corner (scaffolding level)	11/14/07	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/07	< 13.00	No	No	
ASBESTOS-ST17-11/14/07	030736719-0012	North Face - West end at corner (scaffolding level)	11/14/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/07	< 13.00	No	No	