

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-12/24/08	030844770-0001	Southwest Area (sidewalk bridge level)	12/24/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST2-12/24/08	030844770-0002	Southeast Area (sidewalk bridge level)	12/24/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST4-12/24/08	030844770-0003	Northwest Area (street-level)	12/24/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 15.00	No	No		
ASBESTOS-ST5-12/24/08	030844770-0004	Firehouse #10 (roof level)	12/24/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST10-12/24/08	030844770-0005	North Side Sidewalk Bridge	12/24/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 15.00	No	No		
ASBESTOS-ST11-12/24/08	030844770-0006	90 Trinity Place (roof level)	12/24/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST12-12/24/08	030844770-0007	110 Greenwich Street (roof level)	12/24/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST13-12/24/08	030844770-0008	Marriott Hotel, 38th Floor (roof level)	12/24/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 15.00	No	No		
ASBESTOS-ST14-12/24/08	030844770-0009	West Face - South end at corner (scaffolding level)	12/24/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 15.00	No	No		
ASBESTOS-ST15-12/24/08	030844770-0010	South Face - East end at corner (scaffolding level)	12/24/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 15.00	No	No		
ASBESTOS-ST16-12/24/08	030844770-0011	East Face - North end at corner (scaffolding level)	12/24/08	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 15.00	No	No		
ASBESTOS-ST17-12/24/08	030844770-0012	North Face - West end at corner (scaffolding level)	12/24/08	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 15.00	No	No		
ASBESTOS-ST1-12/25/08	030844768-0001	Southwest Area (sidewalk bridge level)	12/25/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST2-12/25/08	030844768-0002	Southeast Area (sidewalk bridge level)	12/25/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST4-12/25/08	030844768-0003	Northwest Area (street-level)	12/25/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST5-12/25/08	030844768-0004	Firehouse #10 (roof level)	12/25/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST10-12/25/08	030844768-0005	North Side Sidewalk Bridge	12/25/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST11-12/25/08	030844768-0006	90 Trinity Place (roof level)	12/25/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST12-12/25/08	030844768-0007	110 Greenwich Street (roof level)	12/25/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST13-12/25/08	030844768-0008	Marriott Hotel, 38th Floor (roof level)	12/25/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST14-12/25/08	030844768-0009	West Face - South end at corner (scaffolding level)	12/25/08	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST15-12/25/08	030844768-0010	South Face - East end at corner (scaffolding level)	12/25/08	1	2.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST16-12/25/08	030844768-0011	East Face - North end at corner (scaffolding level)	12/25/08	1	2.840	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST17-12/25/08	030844768-0012	North Face - West end at corner (scaffolding level)	12/25/08	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/08	< 13.00	No	No		
ASBESTOS-ST1-12/26/08	030844877-0001	Southwest Area (sidewalk bridge level)	12/26/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST2-12/26/08	030844877-0002	Southeast Area (sidewalk bridge level)	12/26/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST4-12/26/08	030844877-0003	Northwest Area (street-level)	12/26/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST5-12/26/08	030844877-0004	Firehouse #10 (roof level)	12/26/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST10-12/26/08	030844877-0005	North Side Sidewalk Bridge	12/26/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST11-12/26/08	030844877-0006	90 Trinity Place (roof level)	12/26/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST12-12/26/08	030844877-0007	110 Greenwich Street (roof level)	12/26/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST13-12/26/08	030844877-0008	Marriott Hotel, 38th Floor (roof level)	12/26/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST14-12/26/08	030844877-0009	West Face - South end at corner (scaffolding level)	12/26/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST15-12/26/08	030844877-0010	South Face - East end at corner (scaffolding level)	12/26/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST16-12/26/08	030844877-0011	East Face - North end at corner (scaffolding level)	12/26/08	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST17-12/26/08	030844877-0012	North Face - West end at corner (scaffolding level)	12/26/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST1-12/27/08	030844952-0001	Southwest Area (sidewalk bridge level)	12/27/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST2-12/27/08	030844952-0002	Southeast Area (sidewalk bridge level)	12/27/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST4-12/27/08	030844952-0003	Northwest Area (street-level)	12/27/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST5-12/27/08	030844952-0004	Firehouse #10 (roof level)	12/27/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST10-12/27/08	030844952-0005	North Side Sidewalk Bridge	12/27/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST11-12/27/08	030844952-0006	90 Trinity Place (roof level)	12/27/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST12-12/27/08	030844952-0007	110 Greenwich Street (roof level)	12/27/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST13-12/27/08	030844952-0008	Marriott Hotel, 38th Floor (roof level)	12/27/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST14-12/27/08	030844952-0009	West Face - South end at corner (scaffolding level)	12/27/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST15-12/27/08	030844952-0010	South Face - East end at corner (scaffolding level)	12/27/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST16-12/27/08	030844952-0011	East Face - North end at corner (scaffolding level)	12/27/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST17-12/27/08	030844952-0012	North Face - West end at corner (scaffolding level)	12/27/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST1-12/28/08	030844954-0001	Southwest Area (sidewalk bridge level)	12/28/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 15.00	No	No		
ASBESTOS-ST2-12/28/08	030844954-0002	Southeast Area (sidewalk bridge level)	12/28/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST4-12/28/08	030844954-0003	Northwest Area (street-level)	12/28/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 15.00	No	No		
ASBESTOS-ST5-12/28/08	030844954-0004	Firehouse #10 (roof level)	12/28/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 15.00	No	No		
ASBESTOS-ST10-12/28/08	030844954-0005	North Side Sidewalk Bridge	12/28/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 15.00	No	No		
ASBESTOS-ST11-12/28/08	030844954-0006	90 Trinity Place (roof level)	12/28/08	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST12-12/28/08	030844954-0007	110 Greenwich Street (roof level)	12/28/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST13-12/28/08	030844954-0008	Marriott Hotel, 38th Floor (roof level)	12/28/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 13.00	No	No		
ASBESTOS-ST14-12/28/08	030844954-0009	West Face - South end at corner (scaffolding level)	12/28/08	1	3.260	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 15.00	No	No		
ASBESTOS-ST15-12/28/08	030844954-0010	South Face - East end at corner (scaffolding level)	12/28/08	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 15.00	No	No		
ASBESTOS-ST16-12/28/08	030844954-0011	East Face - North end at corner (scaffolding level)	12/28/08	1	3.270	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 15.00	No	No		
ASBESTOS-ST17-12/28/08	030844954-0012	North Face - West end at corner (scaffolding level)	12/28/08	1	3.290	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/29/08	< 15.00	No	No		