

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-1/17/08	0803039-01	Southwest Area (sidewalk bridge level)	1/17/08	0.64	Mercury	EPA 324/1631	BRL	1/19/08	< 23.0	No	No	
TotalHg-ST2-1/17/08	0803039-02	Southeast Area (sidewalk bridge level)	1/17/08	0.57	Mercury	EPA 324/1631	BRL	1/19/08	< 26.0	No	No	
TotalHg-ST4-1/17/08	0803039-03	Northwest Area (street-level)	1/17/08	0.62	Mercury	EPA 324/1631	BRL	1/19/08	< 24.0	No	No	
TotalHg-ST5-1/17/08	0803039-04	Firehouse #10 (roof level)	1/17/08	0.55	Mercury	EPA 324/1631	BRL	1/19/08	< 27.0	No	No	
TotalHg-ST10-1/17/08	0803039-05	North Side Sidewalk Bridge	1/17/08	0.53	Mercury	EPA 324/1631	BRL	1/19/08	< 28.0	No	No	
TotalHg-ST11-1/17/08	0803039-06	90 Trinity Place (roof level)	1/17/08	0.55	Mercury	EPA 324/1631	BRL	1/19/08	< 27.0	No	No	
TotalHg-ST12-1/17/08	0803039-07	110 Greenwich Street (roof level)	1/17/08	0.56	Mercury	EPA 324/1631	BRL	1/19/08	< 27.0	No	No	
TotalHg-ST13-1/17/08	0803039-08	Marriott Hotel, 38th Floor (roof level)	1/17/08	0.57	Mercury	EPA 324/1631	BRL	1/19/08	< 26.0	No	No	
TotalHg-ST14-1/17/08	0803039-09	West Face - South end at corner (scaffolding level)	1/17/08	0.57	Mercury	EPA 324/1631	BRL	1/19/08	< 26.0	No	No	
TotalHg-ST15-1/17/08	0803039-10	South Face - East end at corner (scaffolding level)	1/17/08	0.56	Mercury	EPA 324/1631	BRL	1/19/08	< 27.0	No	No	
TotalHg-ST16-1/17/08	0803039-11	East Face - North end at corner (scaffolding level)	1/17/08	0.55	Mercury	EPA 324/1631	BRL	1/19/08	< 27.0	No	No	
TotalHg-ST17-1/17/08	0803039-12	North Face - West end at corner (scaffolding level)	1/17/08	0.63	Mercury	EPA 324/1631	BRL	1/19/08	< 24.0	No	No	
TotalHg-ST1-1/18/08	0804001-01	Southwest Area (sidewalk bridge level)	1/18/08	0.59	Mercury	EPA 324/1631	BRL	1/21/08	< 25.0	No	No	
TotalHg-ST2-1/18/08	0804001-02	Southeast Area (sidewalk bridge level)	1/18/08	0.62	Mercury	EPA 324/1631	BRL	1/21/08	< 24.0	No	No	
TotalHg-ST4-1/18/08	0804001-03	Northwest Area (street-level)	1/18/08	0.60	Mercury	EPA 324/1631	BRL	1/21/08	< 25.0	No	No	
TotalHg-ST5-1/18/08	0804001-04	Firehouse #10 (roof level)	1/18/08	0.55	Mercury	EPA 324/1631	BRL	1/21/08	< 27.0	No	No	
TotalHg-ST10-1/18/08	0804001-05	North Side Sidewalk Bridge	1/18/08	0.56	Mercury	EPA 324/1631	BRL	1/21/08	< 27.0	No	No	
TotalHg-ST11-1/18/08	0804001-06	90 Trinity Place (roof level)	1/18/08	0.54	Mercury	EPA 324/1631	BRL	1/21/08	< 28.0	No	No	
TotalHg-ST12-1/18/08	0804001-07	110 Greenwich Street (roof level)	1/18/08	0.55	Mercury	EPA 324/1631	BRL	1/21/08	< 27.0	No	No	
TotalHg-ST13-1/18/08	0804001-08	Marriott Hotel, 38th Floor (roof level)	1/18/08	0.56	Mercury	EPA 324/1631	BRL	1/21/08	< 27.0	No	No	
TotalHg-ST14-1/18/08	0804001-09	West Face - South end at corner (scaffolding level)	1/18/08	0.53	Mercury	EPA 324/1631	BRL	1/21/08	< 28.0	No	No	
TotalHg-ST15-1/18/08	0804001-10	South Face - East end at corner (scaffolding level)	1/18/08	0.51	Mercury	EPA 324/1631	BRL	1/21/08	< 29.0	No	No	
TotalHg-ST16-1/18/08	0804001-11	East Face - North end at corner (scaffolding level)	1/18/08	0.55	Mercury	EPA 324/1631	BRL	1/21/08	< 27.0	No	No	
TotalHg-ST17-1/18/08	0804001-12	North Face - West end at corner (scaffolding level)	1/18/08	0.51	Mercury	EPA 324/1631	BRL	1/21/08	< 29.0	No	No	