

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300	3,000			
									EPA Site Specific Trigger Levels				
TotalHg-ST1-1/19/08	0804015-01	Southwest Area (sidewalk bridge level)	1/19/08	0.58	Mercury	EPA 324/1631	BRL	1/23/08	< 26.0		No	No	
TotalHg-ST2-1/19/08	0804015-02	Southeast Area (sidewalk bridge level)	1/19/08	0.58	Mercury	EPA 324/1631	BRL	1/23/08	< 26.0		No	No	
TotalHg-ST4-1/19/08	0804015-03	Northwest Area (street-level)	1/19/08	0.54	Mercury	EPA 324/1631	BRL	1/23/08	< 28.0		No	No	
TotalHg-ST5-1/19/08	0804015-04	Firehouse #10 (roof level)	1/19/08	0.59	Mercury	EPA 324/1631	BRL	1/23/08	< 25.0		No	No	
TotalHg-ST10-1/19/08	0804015-05	North Side Sidewalk Bridge	1/19/08	0.56	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST11-1/19/08	0804015-06	90 Trinity Place (roof level)	1/19/08	0.54	Mercury	EPA 324/1631	BRL	1/23/08	< 28.0		No	No	
TotalHg-ST12-1/19/08	0804015-07	110 Greenwich Street (roof level)	1/19/08	0.55	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST13-1/19/08	0804015-08	Marriott Hotel, 38th Floor (roof level)	1/19/08	0.54	Mercury	EPA 324/1631	BRL	1/23/08	< 28.0		No	No	
TotalHg-ST14-1/19/08	0804015-09	Marriott Hotel, 38th Floor (roof level)	1/19/08	0.56	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST15-1/19/08	0804015-10	South Face - East end at corner (scaffolding level)	1/19/08	0.56	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST16-1/19/08	0804015-11	East Face - North end at corner (scaffolding level)	1/19/08	0.61	Mercury	EPA 324/1631	BRL	1/23/08	< 25.0		No	No	
TotalHg-ST17-1/19/08	0804015-12	North Face - West end at corner (scaffolding level)	1/19/08	0.56	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST1-1/20/08	0804016-01	Southwest Area (sidewalk bridge level)	1/20/08	0.57	Mercury	EPA 324/1631	BRL	1/23/08	< 26.0		No	No	
TotalHg-ST2-1/20/08	0804016-02	Southeast Area (sidewalk bridge level)	1/20/08	0.57	Mercury	EPA 324/1631	BRL	1/23/08	< 26.0		No	No	
TotalHg-ST4-1/20/08	0804016-03	Northwest Area (street-level)	1/20/08	0.55	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST5-1/20/08	0804016-04	Firehouse #10 (roof level)	1/20/08	0.55	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST10-1/20/08	0804016-05	North Side Sidewalk Bridge	1/20/08	0.58	Mercury	EPA 324/1631	BRL	1/23/08	< 26.0		No	No	
TotalHg-ST11-1/20/08	0804016-06	90 Trinity Place (roof level)	1/20/08	0.57	Mercury	EPA 324/1631	BRL	1/23/08	< 26.0		No	No	
TotalHg-ST12-1/20/08	0804016-07	110 Greenwich Street (roof level)	1/20/08	0.55	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST13-1/20/08	0804016-08	Marriott Hotel, 38th Floor (roof level)	1/20/08	0.56	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST14-1/20/08	0804016-09	West Face - South end at corner (scaffolding level)	1/20/08	0.59	Mercury	EPA 324/1631	BRL	1/23/08	< 25.0		No	No	
TotalHg-ST15-1/20/08	0804016-10	South Face - East end at corner (scaffolding level)	1/20/08	0.60	Mercury	EPA 324/1631	BRL	1/23/08	< 25.0		No	No	
TotalHg-ST16-1/20/08	0804016-11	East Face - North end at corner (scaffolding level)	1/20/08	0.55	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST17-1/20/08	0804016-12	North Face - West end at corner (scaffolding level)	1/20/08	0.56	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST1-1/21/08	0804017-01	Southwest Area (sidewalk bridge level)	1/21/08	0.58	Mercury	EPA 324/1631	BRL	1/23/08	< 26.0		No	No	
TotalHg-ST2-1/21/08	0804017-02	Southeast Area (sidewalk bridge level)	1/21/08	0.56	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST4-1/21/08	0804017-03	Northwest Area (street-level)	1/21/08	0.61	Mercury	EPA 324/1631	BRL	1/23/08	< 25.0		No	No	
TotalHg-ST5-1/21/08	0804017-04	Firehouse #10 (roof level)	1/21/08	0.59	Mercury	EPA 324/1631	BRL	1/23/08	< 25.0		No	No	
TotalHg-ST10-1/21/08	0804017-05	North Side Sidewalk Bridge	1/21/08	0.60	Mercury	EPA 324/1631	BRL	1/23/08	< 25.0		No	No	
TotalHg-ST11-1/21/08	0804017-06	90 Trinity Place (roof level)	1/21/08	0.57	Mercury	EPA 324/1631	BRL	1/23/08	< 26.0		No	No	
TotalHg-ST12-1/21/08	0804017-07	110 Greenwich Street (roof level)	1/21/08	0.55	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST13-1/21/08	0804017-08	Marriott Hotel, 38th Floor (roof level)	1/21/08	0.55	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST14-1/21/08	0804017-09	West Face - South end at corner (scaffolding level)	1/21/08	0.58	Mercury	EPA 324/1631	BRL	1/23/08	27.0		No	No	
TotalHg-ST15-1/21/08	0804017-10	South Face - East end at corner (scaffolding level)	1/21/08	0.56	Mercury	EPA 324/1631	BRL	1/23/08	< 27.0		No	No	
TotalHg-ST16-1/21/08	0804017-11	East Face - North end at corner (scaffolding level)	1/21/08	0.54	Mercury	EPA 324/1631	BRL	1/23/08	< 28.0		No	No	
TotalHg-ST17-1/21/08	0804017-12	North Face - West end at corner (scaffolding level)	1/21/08	0.54	Mercury	EPA 324/1631	BRL	1/23/08	< 28.0		No	No	
TotalHg-ST1-1/22/08	0804024-01	Southwest Area (sidewalk bridge level)	1/22/08	0.54	Mercury	EPA 324/1631	BRL	1/24/08	< 28.0		No	No	
TotalHg-ST2-1/22/08	0804024-02	Southeast Area (sidewalk bridge level)	1/22/08	0.57	Mercury	EPA 324/1631	BRL	1/24/08	< 26.0		No	No	
TotalHg-ST4-1/22/08	0804024-03	Northwest Area (street-level)	1/22/08	0.58	Mercury	EPA 324/1631	BRL	1/24/08	< 26.0		No	No	
TotalHg-ST5-1/22/08	0804024-04	Firehouse #10 (roof level)	1/22/08	0.60	Mercury	EPA 324/1631	BRL	1/24/08	< 25.0		No	No	
TotalHg-ST10-1/22/08	0804024-05	North Side Sidewalk Bridge	1/22/08	0.59	Mercury	EPA 324/1631	BRL	1/24/08	< 25.0		No	No	
TotalHg-ST11-1/22/08	0804024-06	90 Trinity Place (roof level)	1/22/08	0.55	Mercury	EPA 324/1631	BRL	1/24/08	< 27.0		No	No	
TotalHg-ST12-1/22/08	0804024-07	110 Greenwich Street (roof level)	1/22/08	0.52	Mercury	EPA 324/1631	BRL	1/24/08	< 29.0		No	No	
TotalHg-ST13-1/22/08	0804024-08	Marriott Hotel, 38th Floor (roof level)	1/22/08	0.56	Mercury	EPA 324/1631	BRL	1/24/08	< 27.0		No	No	
TotalHg-ST14-1/22/08	0804024-09	West Face - South end at corner (scaffolding level)	1/22/08	0.53	Mercury	EPA 324/1631	BRL	1/24/08	< 28.0		No	No	
TotalHg-ST15-1/22/08	0804024-10	South Face - East end at corner (scaffolding level)	1/22/08	0.61	Mercury	EPA 324/1631	BRL	1/24/08	< 25.0		No	No	
TotalHg-ST16-1/22/08	0804024-11	East Face - North end at corner (scaffolding level)	1/22/08	0.56	Mercury	EPA 324/1631	BRL	1/24/08	< 27.0		No	No	
TotalHg-ST17-1/22/08	0804024-12	North Face - West end at corner (scaffolding level)	1/22/08	0.55	Mercury	EPA 324/1631	BRL	1/24/08	< 27.0		No	No	