

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target	Exceeds EPA	Comments
									300	Air Quality Levels	Site Specific Trigger Levels	
									3,000			
									Target Air Quality Levels			
									EPA Site Specific Trigger Levels			
TotalHg-ST1-1/23/08	0804031-01	Southwest Area (sidewalk bridge level)	1/23/08	0.54	Mercury	EPA 324/1631	BRL	1/25/08	< 28.0	No	No	
TotalHg-ST2-1/23/08	0804031-02	Southeast Area (sidewalk bridge level)	1/23/08	0.53	Mercury	EPA 324/1631	BRL	1/25/08	< 28.0	No	No	
TotalHg-ST4-1/23/08	0804031-03	Northwest Area (street-level)	1/23/08	0.55	Mercury	EPA 324/1631	BRL	1/25/08	< 27.0	No	No	
TotalHg-ST5-1/23/08	0804031-04	Firehouse #10 (roof level)	1/23/08	0.55	Mercury	EPA 324/1631	BRL	1/25/08	< 27.0	No	No	
TotalHg-ST10-1/23/08	0804031-05	North Side Sidewalk Bridge	1/23/08	0.52	Mercury	EPA 324/1631	BRL	1/25/08	< 29.0	No	No	
TotalHg-ST11-1/23/08	0804031-06	90 Trinity Place (roof level)	1/23/08	0.54	Mercury	EPA 324/1631	BRL	1/25/08	< 28.0	No	No	
TotalHg-ST12-1/23/08	0804031-07	110 Greenwich Street (roof level)	1/23/08	0.54	Mercury	EPA 324/1631	BRL	1/25/08	< 28.0	No	No	
TotalHg-ST13-1/23/08	0804031-08	Marriott Hotel, 38th Floor (roof level)	1/23/08	0.59	Mercury	EPA 324/1631	BRL	1/25/08	< 25.0	No	No	
TotalHg-ST14-1/23/08	0804031-09	West Face - South end at corner (scaffolding level)	1/23/08	0.59	Mercury	EPA 324/1631	BRL	1/25/08	< 25.0	No	No	
TotalHg-ST15-1/23/08	0804031-10	South Face - East end at corner (scaffolding level)	1/23/08	0.63	Mercury	EPA 324/1631	BRL	1/25/08	< 24.0	No	No	
TotalHg-ST16-1/23/08	0804031-11	East Face - North end at corner (scaffolding level)	1/23/08	0.59	Mercury	EPA 324/1631	BRL	1/25/08	< 25.0	No	No	
TotalHg-ST17-1/23/08	0804031-12	North Face - West end at corner (scaffolding level)	1/23/08	0.58	Mercury	EPA 324/1631	BRL	1/25/08	< 26.0	No	No	
TotalHg-ST1-1/24/08	0804037-01	Southwest Area (sidewalk bridge level)	1/24/08	0.54	Mercury	EPA 324/1631	BRL	1/26/08	< 28.0	No	No	
TotalHg-ST2-1/24/08	0804037-02	Southeast Area (sidewalk bridge level)	1/24/08	0.55	Mercury	EPA 324/1631	BRL	1/26/08	< 27.0	No	No	
TotalHg-ST4-1/24/08	0804037-03	Northwest Area (street-level)	1/24/08	0.53	Mercury	EPA 324/1631	BRL	1/26/08	< 28.0	No	No	
TotalHg-ST5-1/24/08	0804037-04	Firehouse #10 (roof level)	1/24/08	0.57	Mercury	EPA 324/1631	BRL	1/26/08	< 26.0	No	No	
TotalHg-ST10-1/24/08	0804037-05	North Side Sidewalk Bridge	1/24/08	0.56	Mercury	EPA 324/1631	BRL	1/26/08	< 27.0	No	No	
TotalHg-ST11-1/24/08	0804037-06	90 Trinity Place (roof level)	1/24/08	0.56	Mercury	EPA 324/1631	BRL	1/26/08	< 27.0	No	No	
TotalHg-ST12-1/24/08	0804037-07	110 Greenwich Street (roof level)	1/24/08	0.57	Mercury	EPA 324/1631	BRL	1/26/08	< 26.0	No	No	
TotalHg-ST13-1/24/08	0804037-08	Marriott Hotel, 38th Floor (roof level)	1/24/08	0.58	Mercury	EPA 324/1631	BRL	1/26/08	< 26.0	No	No	
TotalHg-ST14-1/24/08	0804037-09	West Face - South end at corner (scaffolding level)	1/24/08	0.51	Mercury	EPA 324/1631	BRL	1/26/08	< 29.0	No	No	
TotalHg-ST15-1/24/08	0804037-10	South Face - East end at corner (scaffolding level)	1/24/08	0.49	Mercury	EPA 324/1631	BRL	1/26/08	< 31.0	No	No	
TotalHg-ST16-1/24/08	0804037-11	East Face - North end at corner (scaffolding level)	1/24/08	0.51	Mercury	EPA 324/1631	BRL	1/26/08	< 29.0	No	No	
TotalHg-ST17-1/24/08	0804037-12	North Face - West end at corner (scaffolding level)	1/24/08	0.50	Mercury	EPA 324/1631	BRL	1/26/08	< 30.0	No	No	
TotalHg-ST1-1/25/08	0805002-01	Southwest Area (sidewalk bridge level)	1/25/08	0.56	Mercury	EPA 324/1631	BRL	1/28/08	< 27.0	No	No	
TotalHg-ST2-1/25/08	0805002-02	Southeast Area (sidewalk bridge level)	1/25/08	0.57	Mercury	EPA 324/1631	BRL	1/28/08	< 26.0	No	No	
TotalHg-ST4-1/25/08	0805002-03	Northwest Area (street-level)	1/25/08	0.57	Mercury	EPA 324/1631	BRL	1/28/08	< 26.0	No	No	
TotalHg-ST5-1/25/08	0805002-04	Firehouse #10 (roof level)	1/25/08	0.57	Mercury	EPA 324/1631	BRL	1/28/08	< 26.0	No	No	
TotalHg-ST10-1/25/08	0805002-05	North Side Sidewalk Bridge	1/25/08	0.53	Mercury	EPA 324/1631	BRL	1/28/08	< 28.0	No	No	
TotalHg-ST11-1/25/08	0805002-06	90 Trinity Place (roof level)	1/25/08	0.55	Mercury	EPA 324/1631	BRL	1/28/08	< 27.0	No	No	
TotalHg-ST12-1/25/08	0805002-07	110 Greenwich Street (roof level)	1/25/08	0.52	Mercury	EPA 324/1631	BRL	1/28/08	< 29.0	No	No	
TotalHg-ST13-1/25/08	0805002-08	Marriott Hotel, 38th Floor (roof level)	1/25/08	0.60	Mercury	EPA 324/1631	BRL	1/28/08	< 25.0	No	No	
TotalHg-ST14-1/25/08	0805002-09	West Face - South end at corner (scaffolding level)	1/25/08	0.56	Mercury	EPA 324/1631	BRL	1/28/08	< 27.0	No	No	
TotalHg-ST15-1/25/08	0805002-10	South Face - East end at corner (scaffolding level)	1/25/08	0.55	Mercury	EPA 324/1631	BRL	1/28/08	< 27.0	No	No	
TotalHg-ST16-1/25/08	0805002-11	East Face - North end at corner (scaffolding level)	1/25/08	0.53	Mercury	EPA 324/1631	BRL	1/28/08	< 28.0	No	No	
TotalHg-ST17-1/25/08	0805002-12	North Face - West end at corner (scaffolding level)	1/25/08	0.51	Mercury	EPA 324/1631	BRL	1/28/08	< 29.0	No	No	