

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-1/24/07	07BR0112-01	Southwest Area (sidewalk bridge level)	1/24/07	0.53	Mercury	EPA 324/1631	BRL	1/26/07	< 28.0	No	No	
TotalHg-ST2-1/24/07	07BR0112-02	Southeast Area (sidewalk bridge level)	1/24/07	0.53	Mercury	EPA 324/1631	BRL	1/26/07	< 28.0	No	No	
TotalHg-ST4-1/24/07	07BR0112-03	Northwest Area (street-level)	1/24/07	0.57	Mercury	EPA 324/1631	BRL	1/26/07	< 26.0	No	No	
TotalHg-ST5-1/24/07	07BR0112-04	Firehouse #10 (roof level)	1/24/07	0.54	Mercury	EPA 324/1631	BRL	1/26/07	< 28.0	No	No	
TotalHg-ST10-1/24/07	07BR0112-05	North Side Sidewalk Bridge	1/24/07	0.55	Mercury	EPA 324/1631	BRL	1/26/07	< 27.0	No	No	
TotalHg-ST11-1/24/07	07BR0112-06	90 Trinity Place (roof level)	1/24/07	0.56	Mercury	EPA 324/1631	BRL	1/26/07	< 27.0	No	No	
TotalHg-ST12-1/24/07	07BR0112-07	110 Greenwich Street (roof level)	1/24/07	0.58	Mercury	EPA 324/1631	BRL	1/26/07	< 26.0	No	No	
TotalHg-ST13-1/24/07	07BR0112-08	Marriott Hotel, 38th Floor (roof level)	1/24/07	0.58	Mercury	EPA 324/1631	BRL	1/26/07	< 26.0	No	No	
TotalHg-ST14-1/24/07	07BR0112-09	West Face - South end at corner (scaffolding level)	1/24/07	0.55	Mercury	EPA 324/1631	BRL	1/26/07	< 27.0	No	No	
TotalHg-ST15-1/24/07	07BR0112-10	South Face - East end at corner (scaffolding level)	1/24/07	0.55	Mercury	EPA 324/1631	BRL	1/26/07	< 27.0	No	No	
TotalHg-ST16-1/24/07	07BR0112-11	East Face - North end at corner (scaffolding level)	1/24/07	0.56	Mercury	EPA 324/1631	BRL	1/26/07	< 27.0	No	No	
TotalHg-ST17-1/24/07	07BR0112-12	North Face - West end at corner (scaffolding level)	1/24/07	0.54	Mercury	EPA 324/1631	BRL	1/26/07	< 28.0	No	No	
TotalHg-ST1-1/25/07	07BR0118-01	Southwest Area (sidewalk bridge level)	1/25/07	0.56	Mercury	EPA 324/1631	BRL	1/27/07	< 27.0	No	No	
TotalHg-ST2-1/25/07	07BR0118-02	Southeast Area (sidewalk bridge level)	1/25/07	0.58	Mercury	EPA 324/1631	BRL	1/27/07	< 26.0	No	No	
TotalHg-ST4-1/25/07	07BR0118-03	Northwest Area (street-level)	1/25/07	0.57	Mercury	EPA 324/1631	BRL	1/27/07	< 26.0	No	No	
TotalHg-ST5-1/25/07	07BR0118-04	Firehouse #10 (roof level)	1/25/07	0.56	Mercury	EPA 324/1631	BRL	1/27/07	< 27.0	No	No	
TotalHg-ST10-1/25/07	07BR0118-05	North Side Sidewalk Bridge	1/25/07	0.55	Mercury	EPA 324/1631	BRL	1/27/07	< 27.0	No	No	
TotalHg-ST11-1/25/07	07BR0118-06	90 Trinity Place (roof level)	1/25/07	0.54	Mercury	EPA 324/1631	BRL	1/27/07	< 28.0	No	No	
TotalHg-ST12-1/25/07	07BR0118-07	110 Greenwich Street (roof level)	1/25/07	0.57	Mercury	EPA 324/1631	BRL	1/27/07	< 26.0	No	No	
TotalHg-ST13-1/25/07	07BR0118-08	Marriott Hotel, 38th Floor (roof level)	1/25/07	0.57	Mercury	EPA 324/1631	BRL	1/27/07	< 26.0	No	No	
TotalHg-ST14-1/25/07	07BR0118-09	West Face - South end at corner (scaffolding level)	1/25/07	0.59	Mercury	EPA 324/1631	BRL	1/27/07	< 25.0	No	No	
TotalHg-ST15-1/25/07	07BR0118-10	South Face - East end at corner (scaffolding level)	1/25/07	0.57	Mercury	EPA 324/1631	BRL	1/27/07	< 26.0	No	No	
TotalHg-ST16-1/25/07	07BR0118-11	East Face - North end at corner (scaffolding level)	1/25/07	0.57	Mercury	EPA 324/1631	BRL	1/27/07	< 26.0	No	No	
TotalHg-ST17-1/25/07	07BR0118-12	North Face - West end at corner (scaffolding level)	1/25/07	0.54	Mercury	EPA 324/1631	BRL	1/27/07	< 28.0	No	No	