

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>												
TotalHg-ST1-1/26/08	0805008-01	Southwest Area (sidewalk bridge level)	1/26/08	0.55	Mercury	EPA 324/1631	BRL	1/29/08	< 27.0	No	No	
TotalHg-ST2-1/26/08	0805008-02	Southeast Area (sidewalk bridge level)	1/26/08	0.57	Mercury	EPA 324/1631	BRL	1/29/08	< 26.0	No	No	
TotalHg-ST4-1/26/08	0805008-03	Northwest Area (street-level)	1/26/08	0.59	Mercury	EPA 324/1631	BRL	1/29/08	< 25.0	No	No	
TotalHg-ST5-1/26/08	0805008-04	Firehouse #10 (roof level)	1/26/08	0.59	Mercury	EPA 324/1631	BRL	1/29/08	< 25.0	No	No	
TotalHg-ST10-1/26/08	0805008-05	North Side Sidewalk Bridge	1/26/08	0.59	Mercury	EPA 324/1631	BRL	1/29/08	< 25.0	No	No	
TotalHg-ST11-1/26/08	0805008-06	90 Trinity Place (roof level)	1/26/08	0.56	Mercury	EPA 324/1631	BRL	1/29/08	< 27.0	No	No	
TotalHg-ST12-1/26/08	0805008-07	110 Greenwich Street (roof level)	1/26/08	0.60	Mercury	EPA 324/1631	BRL	1/29/08	< 25.0	No	No	
TotalHg-ST13-1/26/08	0805008-08	Marriott Hotel, 38th Floor (roof level)	1/26/08	0.56	Mercury	EPA 324/1631	BRL	1/29/08	< 27.0	No	No	
TotalHg-ST14-1/26/08	0805008-09	West Face - South end at corner (scaffolding level)	1/26/08	0.58	Mercury	EPA 324/1631	BRL	1/29/08	< 26.0	No	No	
TotalHg-ST15-1/26/08	0805008-10	South Face - East end at corner (scaffolding level)	1/26/08	0.55	Mercury	EPA 324/1631	BRL	1/29/08	< 27.0	No	No	
TotalHg-ST16-1/26/08	0805008-11	East Face - North end at corner (scaffolding level)	1/26/08	0.54	Mercury	EPA 324/1631	BRL	1/29/08	< 28.0	No	No	
TotalHg-ST17-1/26/08	0805008-12	North Face - West end at corner (scaffolding level)	1/26/08	0.54	Mercury	EPA 324/1631	BRL	1/29/08	< 28.0	No	No	
TotalHg-ST1-1/27/08	0805009-01	Southwest Area (sidewalk bridge level)	1/27/08	0.52	Mercury	EPA 324/1631	BRL	1/29/08	< 29.0	No	No	
TotalHg-ST2-1/27/08	0805009-02	Southeast Area (sidewalk bridge level)	1/27/08	0.48	Mercury	EPA 324/1631	BRL	1/29/08	< 31.0	No	No	Note 1
TotalHg-ST4-1/27/08	0805009-03	Northwest Area (street-level)	1/27/08	0.51	Mercury	EPA 324/1631	BRL	1/29/08	< 29.0	No	No	
TotalHg-ST5-1/27/08	0805009-04	Firehouse #10 (roof level)	1/27/08	0.59	Mercury	EPA 324/1631	BRL	1/29/08	< 25.0	No	No	
TotalHg-ST10-1/27/08	0805009-05	North Side Sidewalk Bridge	1/27/08	0.56	Mercury	EPA 324/1631	BRL	1/29/08	< 27.0	No	No	
TotalHg-ST11-1/27/08	0805009-06	90 Trinity Place (roof level)	1/27/08	0.53	Mercury	EPA 324/1631	BRL	1/29/08	< 28.0	No	No	
TotalHg-ST12-1/27/08	0805009-07	110 Greenwich Street (roof level)	1/27/08	0.53	Mercury	EPA 324/1631	BRL	1/29/08	< 28.0	No	No	
TotalHg-ST13-1/27/08	0805009-08	Marriott Hotel, 38th Floor (roof level)	1/27/08	0.59	Mercury	EPA 324/1631	BRL	1/29/08	< 25.0	No	No	
TotalHg-ST14-1/27/08	0805009-09	West Face - South end at corner (scaffolding level)	1/27/08	0.51	Mercury	EPA 324/1631	BRL	1/29/08	< 29.0	No	No	Note 1
TotalHg-ST15-1/27/08	0805009-10	South Face - East end at corner (scaffolding level)	1/27/08	0.58	Mercury	EPA 324/1631	BRL	1/29/08	< 26.0	No	No	
TotalHg-ST16-1/27/08	0805009-11	East Face - North end at corner (scaffolding level)	1/27/08	0.57	Mercury	EPA 324/1631	BRL	1/29/08	< 26.0	No	No	
TotalHg-ST17-1/27/08	0805009-12	North Face - West end at corner (scaffolding level)	1/27/08	0.56	Mercury	EPA 324/1631	BRL	1/29/08	< 27.0	No	No	

Note:

1. Due to an RPD exceedances (35.3% and 38.8%, respectively) at Station 2 (Southeast Area [sidewalk bridge level]) and Station 14 (West Face - South end at corner [scaffolding level]) on January 27, 2008, the sample volumes and subsequent sample results are estimated.