

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-2/1/06	06BR0158-01	Southwest Area (sidewalk bridge level)	2/1/06	0.57	Mercury	EPA 324/1631	BRL	2/3/06	< 26.0	No	No	
TotalHg-ST2-2/1/06	06BR0158-02	Southeast Area (sidewalk bridge level)	2/1/06	0.56	Mercury	EPA 324/1631	BRL	2/3/06	< 27.0	No	No	
TotalHg-ST4-2/1/06	06BR0158-03	Northwest Area (street-level)	2/1/06	0.56	Mercury	EPA 324/1631	BRL	2/3/06	< 27.0	No	No	
TotalHg-ST5-2/1/06	06BR0158-04	Firehouse #10 (roof level)	2/1/06	0.54	Mercury	EPA 324/1631	BRL	2/3/06	< 28.0	No	No	
TotalHg-ST10-2/1/06	06BR0158-05	North Side Sidewalk Bridge	2/1/06	0.58	Mercury	EPA 324/1631	BRL	2/3/06	< 26.0	No	No	
TotalHg-ST11-2/1/06	06BR0158-06	90 Trinity Place (roof level)	2/1/06	0.55	Mercury	EPA 324/1631	BRL	2/3/06	< 27.0	No	No	
TotalHg-ST12-2/1/06	06BR0158-07	110 Greenwich Street (roof level)	2/1/06	0.53	Mercury	EPA 324/1631	BRL	2/3/06	< 28.0	No	No	
TotalHg-ST13-2/1/06	06BR0158-08	Marriott Hotel, 38th Floor (roof level)	2/1/06	0.57	Mercury	EPA 324/1631	BRL	2/3/06	< 26.0	No	No	
TotalHg-ST14-2/1/06	06BR0158-09	West Face - South end at corner (scaffolding level)	2/1/06	0.57	Mercury	EPA 324/1631	BRL	2/3/06	< 26.0	No	No	
TotalHg-ST15-2/1/06	06BR0158-10	South Face - East end at corner (scaffolding level)	2/1/06	0.56	Mercury	EPA 324/1631	BRL	2/3/06	< 27.0	No	No	
TotalHg-ST16-2/1/06	06BR0158-11	East Face - North end at corner (scaffolding level)	2/1/06	0.56	Mercury	EPA 324/1631	BRL	2/3/06	< 27.0	No	No	
TotalHg-ST17-2/1/06	06BR0158-12	North Face - West end at corner (scaffolding level)	2/1/06	0.57	Mercury	EPA 324/1631	BRL	2/3/06	< 26.0	No	No	
TotalHg-ST1-2/2/06	06BR0165-01	Southwest Area (sidewalk bridge level)	2/2/06	0.58	Mercury	EPA 324/1631	BRL	2/4/06	< 26.0	No	No	
TotalHg-ST2-2/2/06	06BR0165-02	Southeast Area (sidewalk bridge level)	2/2/06	0.58	Mercury	EPA 324/1631	BRL	2/4/06	< 26.0	No	No	
TotalHg-ST4-2/2/06	06BR0165-03	Northwest Area (street-level)	2/2/06	0.59	Mercury	EPA 324/1631	BRL	2/4/06	51.5	No	No	
TotalHg-ST5-2/2/06	06BR0165-04	Firehouse #10 (roof level)	2/2/06	0.72	Mercury	EPA 324/1631	BRL	2/4/06	< 21.0	No	No	
TotalHg-ST10-2/2/06	06BR0165-05	North Side Sidewalk Bridge	2/2/06	0.58	Mercury	EPA 324/1631	BRL	2/4/06	< 26.0	No	No	
TotalHg-ST11-2/2/06	06BR0165-06	90 Trinity Place (roof level)	2/2/06	0.57	Mercury	EPA 324/1631	BRL	2/4/06	< 26.0	No	No	
TotalHg-ST12-2/2/06	06BR0165-07	110 Greenwich Street (roof level)	2/2/06	0.57	Mercury	EPA 324/1631	BRL	2/4/06	< 26.0	No	No	
TotalHg-ST13-2/2/06	06BR0165-08	Marriott Hotel, 38th Floor (roof level)	2/2/06	0.55	Mercury	EPA 324/1631	BRL	2/4/06	< 27.0	No	No	
TotalHg-ST14-2/2/06	06BR0165-09	West Face - South end at corner (scaffolding level)	2/2/06	0.58	Mercury	EPA 324/1631	BRL	2/4/06	< 26.0	No	No	
TotalHg-ST15-2/2/06	06BR0165-10	South Face - East end at corner (scaffolding level)	2/2/06	0.58	Mercury	EPA 324/1631	BRL	2/4/06	< 26.0	No	No	
TotalHg-ST16-2/2/06	06BR0165-11	East Face - North end at corner (scaffolding level)	2/2/06	0.57	Mercury	EPA 324/1631	BRL	2/4/06	< 26.0	No	No	
TotalHg-ST17-2/2/06	06BR0165-12	North Face - West end at corner (scaffolding level)	2/2/06	0.58	Mercury	EPA 324/1631	BRL	2/4/06	< 26.0	No	No	