

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-2/6/06	06BR0177-01	Southwest Area (sidewalk bridge level)	2/6/06	0.54	Mercury	EPA 324/1631	BRL	2/8/06	< 28.0	No	No	
TotalHg-ST2-2/6/06	06BR0177-02	Southeast Area (sidewalk bridge level)	2/6/06	0.53	Mercury	EPA 324/1631	BRL	2/8/06	< 28.0	No	No	
TotalHg-ST4-2/6/06	06BR0177-03	Northwest Area (street-level)	2/6/06	0.53	Mercury	EPA 324/1631	BRL	2/8/06	< 28.0	No	No	
TotalHg-ST5-2/6/06	06BR0177-04	Firehouse #10 (roof level)	2/6/06	0.57	Mercury	EPA 324/1631	BRL	2/8/06	< 26.0	No	No	
TotalHg-ST10-2/6/06	06BR0177-05	North Side Sidewalk Bridge	2/6/06	0.54	Mercury	EPA 324/1631	BRL	2/8/06	< 28.0	No	No	
TotalHg-ST11-2/6/06	06BR0177-06	90 Trinity Place (roof level)	2/6/06	0.58	Mercury	EPA 324/1631	BRL	2/8/06	< 26.0	No	No	
TotalHg-ST12-2/6/06	06BR0177-07	110 Greenwich Street (roof level)	2/6/06	0.59	Mercury	EPA 324/1631	BRL	2/8/06	< 25.0	No	No	
TotalHg-ST13-2/6/06	06BR0177-08	Marriott Hotel, 38th Floor (roof level)	2/6/06	0.55	Mercury	EPA 324/1631	BRL	2/8/06	< 27.0	No	No	
TotalHg-ST14-2/6/06	06BR0177-09	West Face - South end at corner (scaffolding level)	2/6/06	0.58	Mercury	EPA 324/1631	BRL	2/8/06	< 26.0	No	No	
TotalHg-ST15-2/6/06	06BR0177-10	South Face - East end at corner (scaffolding level)	2/6/06	0.58	Mercury	EPA 324/1631	BRL	2/8/06	< 26.0	No	No	
TotalHg-ST16-2/6/06	06BR0177-11	East Face - North end at corner (scaffolding level)	2/6/06	0.58	Mercury	EPA 324/1631	BRL	2/8/06	< 26.0	No	No	
TotalHg-ST17-2/6/06	06BR0177-12	North Face - West end at corner (scaffolding level)	2/6/06	0.58	Mercury	EPA 324/1631	BRL	2/8/06	< 26.0	No	No	
TotalHg-ST1-2/7/06	06BR0185-01	Southwest Area (sidewalk bridge level)	2/7/06	0.57	Mercury	EPA 324/1631	BRL	2/9/06	< 26.0	No	No	
TotalHg-ST2-2/7/06	06BR0185-02	Southeast Area (sidewalk bridge level)	2/7/06	0.55	Mercury	EPA 324/1631	BRL	2/9/06	< 27.0	No	No	
TotalHg-ST4-2/7/06	06BR0185-03	Northwest Area (street-level)	2/7/06	0.55	Mercury	EPA 324/1631	BRL	2/9/06	< 27.0	No	No	
TotalHg-ST5-2/7/06	06BR0185-04	Firehouse #10 (roof level)	2/7/06	0.57	Mercury	EPA 324/1631	BRL	2/9/06	< 26.0	No	No	
TotalHg-ST10-2/7/06	06BR0185-05	North Side Sidewalk Bridge	2/7/06	0.56	Mercury	EPA 324/1631	BRL	2/9/06	< 27.0	No	No	
TotalHg-ST11-2/7/06	06BR0185-06	90 Trinity Place (roof level)	2/7/06	0.57	Mercury	EPA 324/1631	BRL	2/9/06	< 26.0	No	No	
TotalHg-ST12-2/7/06	06BR0185-07	110 Greenwich Street (roof level)	2/7/06	0.56	Mercury	EPA 324/1631	BRL	2/9/06	< 27.0	No	No	
TotalHg-ST13-2/7/06	06BR0185-08	Marriott Hotel, 38th Floor (roof level)	2/7/06	0.58	Mercury	EPA 324/1631	BRL	2/9/06	< 26.0	No	No	
TotalHg-ST14-2/7/06	06BR0185-09	West Face - South end at corner (scaffolding level)	2/7/06	0.56	Mercury	EPA 324/1631	BRL	2/9/06	< 27.0	No	No	
TotalHg-ST15-2/7/06	06BR0185-10	South Face - East end at corner (scaffolding level)	2/7/06	0.56	Mercury	EPA 324/1631	BRL	2/9/06	< 27.0	No	No	
TotalHg-ST16-2/7/06	06BR0185-11	East Face - North end at corner (scaffolding level)	2/7/06	0.56	Mercury	EPA 324/1631	BRL	2/9/06	< 27.0	No	No	
TotalHg-ST17-2/7/06	06BR0185-12	North Face - West end at corner (scaffolding level)	2/7/06	0.56	Mercury	EPA 324/1631	BRL	2/9/06	< 27.0	No	No	