

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-2/8/06	06BR0193-01	Southwest Area (sidewalk bridge level)	2/8/06	0.58	Mercury	EPA 324/1631	BRL	2/10/06	< 26.0	No	No	
TotalHg-ST2-2/8/06	06BR0193-02	Southeast Area (sidewalk bridge level)	2/8/06	0.56	Mercury	EPA 324/1631	BRL	2/10/06	< 27.0	No	No	
TotalHg-ST4-2/8/06	06BR0193-03	Northwest Area (street-level)	2/8/06	0.57	Mercury	EPA 324/1631	BRL	2/10/06	< 26.0	No	No	
TotalHg-ST5-2/8/06	06BR0193-04	Firehouse #10 (roof level)	2/8/06	0.58	Mercury	EPA 324/1631	BRL	2/10/06	< 26.0	No	No	
TotalHg-ST10-2/8/06	06BR0193-05	North Side Sidewalk Bridge	2/8/06	0.58	Mercury	EPA 324/1631	BRL	2/10/06	< 26.0	No	No	
TotalHg-ST11-2/8/06	06BR0193-06	90 Trinity Place (roof level)	2/8/06	0.58	Mercury	EPA 324/1631	BRL	2/10/06	< 26.0	No	No	
TotalHg-ST12-2/8/06	06BR0193-07	110 Greenwich Street (roof level)	2/8/06	0.56	Mercury	EPA 324/1631	BRL	2/10/06	< 27.0	No	No	
TotalHg-ST13-2/8/06	06BR0193-08	Marriott Hotel, 38th Floor (roof level)	2/8/06	0.60	Mercury	EPA 324/1631	BRL	2/10/06	< 25.0	No	No	
TotalHg-ST14-2/8/06	06BR0193-09	West Face - South end at corner (scaffolding level)	2/8/06	0.59	Mercury	EPA 324/1631	BRL	2/10/06	< 25.0	No	No	
TotalHg-ST15-2/8/06	06BR0193-10	South Face - East end at corner (scaffolding level)	2/8/06	0.59	Mercury	EPA 324/1631	BRL	2/10/06	< 25.0	No	No	
TotalHg-ST16-2/8/06	06BR0193-11	East Face - North end at corner (scaffolding level)	2/8/06	0.59	Mercury	EPA 324/1631	BRL	2/10/06	< 25.0	No	No	
TotalHg-ST17-2/8/06	06BR0193-12	North Face - West end at corner (scaffolding level)	2/8/06	0.59	Mercury	EPA 324/1631	BRL	2/10/06	< 25.0	No	No	
TotalHg-ST1-2/9/06	06BR0199-01	Southwest Area (sidewalk bridge level)	2/9/06	0.58	Mercury	EPA 324/1631	BRL	2/11/06	< 26.0	No	No	
TotalHg-ST2-2/9/06	06BR0199-02	Southeast Area (sidewalk bridge level)	2/9/06	0.56	Mercury	EPA 324/1631	BRL	2/11/06	< 27.0	No	No	
TotalHg-ST4-2/9/06	06BR0199-03	Northwest Area (street-level)	2/9/06	0.57	Mercury	EPA 324/1631	BRL	2/11/06	< 26.0	No	No	
TotalHg-ST5-2/9/06	06BR0199-04	Firehouse #10 (roof level)	2/9/06	0.57	Mercury	EPA 324/1631	BRL	2/11/06	< 26.0	No	No	
TotalHg-ST10-2/9/06	06BR0199-05	North Side Sidewalk Bridge	2/9/06	0.59	Mercury	EPA 324/1631	BRL	2/11/06	< 25.0	No	No	
TotalHg-ST100-2/9/06FD	06BR0199-13	Station 10 Field Duplicate	2/9/06	0.60	Mercury	EPA 324/1631	BRL	2/11/06	< 25.0	No	No	
TotalHg-ST11-2/9/06	06BR0199-06	90 Trinity Place (roof level)	2/9/06	0.57	Mercury	EPA 324/1631	BRL	2/11/06	< 26.0	No	No	
TotalHg-ST12-2/9/06	06BR0199-07	110 Greenwich Street (roof level)	2/9/06	0.58	Mercury	EPA 324/1631	BRL	2/11/06	< 26.0	No	No	
TotalHg-ST13-2/9/06	06BR0199-08	Marriott Hotel, 38th Floor (roof level)	2/9/06	0.57	Mercury	EPA 324/1631	BRL	2/11/06	< 26.0	No	No	
TotalHg-ST14-2/9/06	06BR0199-09	West Face - South end at corner (scaffolding level)	2/9/06	0.57	Mercury	EPA 324/1631	BRL	2/11/06	< 26.0	No	No	
TotalHg-ST15-2/9/06	06BR0199-10	South Face - East end at corner (scaffolding level)	2/9/06	0.56	Mercury	EPA 324/1631	BRL	2/11/06	< 27.0	No	No	
TotalHg-ST16-2/9/06	06BR0199-11	East Face - North end at corner (scaffolding level)	2/9/06	0.56	Mercury	EPA 324/1631	BRL	2/11/06	< 27.0	No	No	
TotalHg-ST17-2/9/06	06BR0199-12	North Face - West end at corner (scaffolding level)	2/9/06	0.57	Mercury	EPA 324/1631	BRL	2/11/06	< 26.0	No	No	