

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-2/21/07	07BR0239-01	Southwest Area (sidewalk bridge level)	2/21/07	0.58	Mercury	EPA 324/1631	BRL	2/23/07	< 26.0	No	No	
TotalHg-ST2-2/21/07	07BR0239-02	Southeast Area (sidewalk bridge level)	2/21/07	0.60	Mercury	EPA 324/1631	BRL	2/23/07	< 25.0	No	No	
TotalHg-ST4-2/21/07	07BR0239-03	Northwest Area (street-level)	2/21/07	0.56	Mercury	EPA 324/1631	BRL	2/23/07	< 27.0	No	No	
TotalHg-ST5-2/21/07	07BR0239-04	Firehouse #10 (roof level)	2/21/07	0.57	Mercury	EPA 324/1631	BRL	2/23/07	< 26.0	No	No	
TotalHg-ST10-2/21/07	07BR0239-05	North Side Sidewalk Bridge	2/21/07	0.54	Mercury	EPA 324/1631	BRL	2/23/07	< 28.0	No	No	
TotalHg-ST11-2/21/07	07BR0239-06	90 Trinity Place (roof level)	2/21/07	0.56	Mercury	EPA 324/1631	BRL	2/23/07	< 27.0	No	No	
TotalHg-ST12-2/21/07	07BR0239-07	110 Greenwich Street (roof level)	2/21/07	0.61	Mercury	EPA 324/1631	BRL	2/23/07	< 25.0	No	No	
TotalHg-ST13-2/21/07	07BR0239-08	Marriott Hotel, 38th Floor (roof level)	2/21/07	0.62	Mercury	EPA 324/1631	BRL	2/23/07	< 24.0	No	No	
TotalHg-ST14-2/21/07	07BR0239-09	West Face - South end at corner (scaffolding level)	2/21/07	0.55	Mercury	EPA 324/1631	BRL	2/23/07	< 27.0	No	No	
TotalHg-ST15-2/21/07	07BR0239-10	South Face - East end at corner (scaffolding level)	2/21/07	0.52	Mercury	EPA 324/1631	BRL	2/23/07	< 29.0	No	No	
TotalHg-ST16-2/21/07	07BR0239-11	East Face - North end at corner (scaffolding level)	2/21/07	0.53	Mercury	EPA 324/1631	BRL	2/23/07	< 28.0	No	No	
TotalHg-ST17-2/21/07	07BR0239-12	North Face - West end at corner (scaffolding level)	2/21/07	0.57	Mercury	EPA 324/1631	BRL	2/23/07	< 26.0	No	No	
TotalHg-ST1-2/22/07	07BR0247-01	Southwest Area (sidewalk bridge level)	2/22/07	0.57	Mercury	EPA 324/1631	BRL	2/24/07	< 26.0	No	No	
TotalHg-ST2-2/22/07	07BR0247-02	Southeast Area (sidewalk bridge level)	2/22/07	0.58	Mercury	EPA 324/1631	BRL	2/24/07	< 26.0	No	No	
TotalHg-ST4-2/22/07	07BR0247-03	Northwest Area (street-level)	2/22/07	0.56	Mercury	EPA 324/1631	BRL	2/24/07	< 27.0	No	No	
TotalHg-ST5-2/22/07	07BR0247-04	Firehouse #10 (roof level)	2/22/07	0.55	Mercury	EPA 324/1631	BRL	2/24/07	< 27.0	No	No	
TotalHg-ST10-2/22/07	07BR0247-05	North Side Sidewalk Bridge	2/22/07	0.55	Mercury	EPA 324/1631	BRL	2/24/07	< 27.0	No	No	
TotalHg-ST11-2/22/07	07BR0247-06	90 Trinity Place (roof level)	2/22/07	0.60	Mercury	EPA 324/1631	BRL	2/24/07	< 25.0	No	No	
TotalHg-ST12-2/22/07	07BR0247-07	110 Greenwich Street (roof level)	2/22/07	0.57	Mercury	EPA 324/1631	BRL	2/24/07	< 26.0	No	No	
TotalHg-ST13-2/22/07	07BR0247-08	Marriott Hotel, 38th Floor (roof level)	2/22/07	0.58	Mercury	EPA 324/1631	BRL	2/24/07	< 26.0	No	No	
TotalHg-ST14-2/22/07	07BR0247-09	West Face - South end at corner (scaffolding level)	2/22/07	0.60	Mercury	EPA 324/1631	BRL	2/24/07	< 25.0	No	No	
TotalHg-ST15-2/22/07	07BR0247-10	South Face - East end at corner (scaffolding level)	2/22/07	0.57	Mercury	EPA 324/1631	BRL	2/24/07	< 27.0	No	No	
TotalHg-ST16-2/22/07	07BR0247-11	East Face - North end at corner (scaffolding level)	2/22/07	0.58	Mercury	EPA 324/1631	BRL	2/24/07	< 26.0	No	No	
TotalHg-ST17-2/22/07	07BR0247-12	North Face - West end at corner (scaffolding level)	2/22/07	0.58	Mercury	EPA 324/1631	BRL	2/24/07	< 26.0	No	No	