

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Mercury (Total) Concentration (ng/m ³) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|------------|---|-----------------------|---------------------------------|---------|-------------------|-----|-------------------------|--|-----------------------------------|--|----------|
| | | | | | | | | | 300 | | | |
| Target Air Quality Levels | | | | | | | | | | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | 3,000 | | | |
| TotalHg-ST1-3/4/09 | 0910025-01 | Southwest Area (sidewalk bridge level) | 3/4/09 | 0.59 | Mercury | EPA 324/1631 | BRL | 3/6/09 | < 25.0 | No | No | |
| TotalHg-ST2-3/4/09 | 0910025-02 | Southeast Area (sidewalk bridge level) | 3/4/09 | 0.54 | Mercury | EPA 324/1631 | BRL | 3/6/09 | < 28.0 | No | No | |
| TotalHg-ST4-3/4/09 | 0910025-03 | Northwest Area (street-level) | 3/4/09 | 0.54 | Mercury | EPA 324/1631 | BRL | 3/6/09 | < 28.0 | No | No | |
| TotalHg-ST5-3/4/09 | 0910025-04 | Firehouse #10 (roof level) | 3/4/09 | 0.58 | Mercury | EPA 324/1631 | BRL | 3/6/09 | < 26.0 | No | No | |
| TotalHg-ST10-3/4/09 | 0910025-05 | North Side Sidewalk Bridge | 3/4/09 | 0.57 | Mercury | EPA 324/1631 | BRL | 3/6/09 | < 26.0 | No | No | |
| TotalHg-ST11-3/4/09 | 0910025-06 | 90 Trinity Place (roof level) | 3/4/09 | 0.57 | Mercury | EPA 324/1631 | BRL | 3/6/09 | < 26.0 | No | No | |
| TotalHg-ST12-3/4/09 | 0910025-07 | 110 Greenwich Street (roof level) | 3/4/09 | 0.59 | Mercury | EPA 324/1631 | BRL | 3/6/09 | < 25.0 | No | No | |
| TotalHg-ST13-3/4/09 | 0910025-08 | Marriott Hotel, 38th Floor (roof level) | 3/4/09 | 0.55 | Mercury | EPA 324/1631 | BRL | 3/6/09 | < 27.0 | No | No | |
| TotalHg-ST14-3/4/09 | 0910025-09 | West Face - South end at corner (scaffolding level) | 3/4/09 | 0.60 | Mercury | EPA 324/1631 | BRL | 3/6/09 | < 25.0 | No | No | |
| TotalHg-ST15-3/4/09 | 0910025-10 | South Face - East end at corner (scaffolding level) | 3/4/09 | 0.53 | Mercury | EPA 324/1631 | BRL | 3/6/09 | < 28.0 | No | No | |
| TotalHg-ST16-3/4/09 | 0910025-11 | East Face - North end at corner (scaffolding level) | 3/4/09 | 0.56 | Mercury | EPA 324/1631 | BRL | 3/6/09 | < 27.0 | No | No | |
| TotalHg-ST17-3/4/09 | 0910025-12 | North Face - West end at corner (scaffolding level) | 3/4/09 | 0.61 | Mercury | EPA 324/1631 | BRL | 3/6/09 | < 25.0 | No | No | |
| TotalHg-ST1-3/5/09 | 0910030-01 | Southwest Area (sidewalk bridge level) | 3/5/09 | 0.59 | Mercury | EPA 324/1631 | BRL | 3/7/09 | < 25.0 | No | No | |
| TotalHg-ST2-3/5/09 | 0910030-02 | Southeast Area (sidewalk bridge level) | 3/5/09 | 0.55 | Mercury | EPA 324/1631 | BRL | 3/7/09 | < 27.0 | No | No | |
| TotalHg-ST4-3/5/09 | 0910030-03 | Northwest Area (street-level) | 3/5/09 | 0.56 | Mercury | EPA 324/1631 | BRL | 3/7/09 | < 27.0 | No | No | |
| TotalHg-ST5-3/5/09 | 0910030-04 | Firehouse #10 (roof level) | 3/5/09 | 0.56 | Mercury | EPA 324/1631 | BRL | 3/7/09 | < 27.0 | No | No | |
| TotalHg-ST10-3/5/09 | 0910030-05 | North Side Sidewalk Bridge | 3/5/09 | 0.54 | Mercury | EPA 324/1631 | BRL | 3/7/09 | < 28.0 | No | No | |
| TotalHg-ST11-3/5/09 | 0910030-06 | 90 Trinity Place (roof level) | 3/5/09 | 0.54 | Mercury | EPA 324/1631 | BRL | 3/7/09 | < 28.0 | No | No | |
| TotalHg-ST12-3/5/09 | 0910030-07 | 110 Greenwich Street (roof level) | 3/5/09 | 0.54 | Mercury | EPA 324/1631 | BRL | 3/7/09 | < 28.0 | No | No | |
| TotalHg-ST13-3/5/09 | 0910030-08 | Marriott Hotel, 38th Floor (roof level) | 3/5/09 | 0.59 | Mercury | EPA 324/1631 | BRL | 3/7/09 | < 25.0 | No | No | |
| TotalHg-ST14-3/5/09 | 0910030-09 | West Face - South end at corner (scaffolding level) | 3/5/09 | 0.55 | Mercury | EPA 324/1631 | BRL | 3/7/09 | < 27.0 | No | No | |
| TotalHg-ST15-3/5/09 | 0910030-10 | South Face - East end at corner (scaffolding level) | 3/5/09 | 0.56 | Mercury | EPA 324/1631 | BRL | 3/7/09 | < 27.0 | No | No | |
| TotalHg-ST16-3/5/09 | 0910030-11 | East Face - North end at corner (scaffolding level) | 3/5/09 | 0.57 | Mercury | EPA 324/1631 | BRL | 3/7/09 | < 26.0 | No | No | |
| TotalHg-ST17-3/5/09 | 0910030-12 | North Face - West end at corner (scaffolding level) | 3/5/09 | 0.55 | Mercury | EPA 324/1631 | BRL | 3/7/09 | < 27.0 | No | No | |
| TotalHg-ST1-3/6/09 | 0911001-01 | Southwest Area (sidewalk bridge level) | 3/6/09 | 0.54 | Mercury | EPA 324/1631 | BRL | 3/9/09 | < 28.0 | No | No | |
| TotalHg-ST2-3/6/09 | 0911001-02 | Southeast Area (sidewalk bridge level) | 3/6/09 | 0.54 | Mercury | EPA 324/1631 | BRL | 3/9/09 | < 28.0 | No | No | |
| TotalHg-ST4-3/6/09 | 0911001-03 | Northwest Area (street-level) | 3/6/09 | 0.58 | Mercury | EPA 324/1631 | BRL | 3/9/09 | < 26.0 | No | No | |
| TotalHg-ST5-3/6/09 | 0911001-04 | Firehouse #10 (roof level) | 3/6/09 | 0.54 | Mercury | EPA 324/1631 | BRL | 3/9/09 | < 28.0 | No | No | |
| TotalHg-ST10-3/6/09 | 0911001-05 | North Side Sidewalk Bridge | 3/6/09 | 0.57 | Mercury | EPA 324/1631 | BRL | 3/9/09 | < 26.0 | No | No | |
| TotalHg-ST11-3/6/09 | 0911001-06 | 90 Trinity Place (roof level) | 3/6/09 | 0.53 | Mercury | EPA 324/1631 | BRL | 3/9/09 | < 28.0 | No | No | |
| TotalHg-ST12-3/6/09 | 0911001-07 | 110 Greenwich Street (roof level) | 3/6/09 | 0.58 | Mercury | EPA 324/1631 | BRL | 3/9/09 | < 26.0 | No | No | |
| TotalHg-ST13-3/6/09 | 0911001-08 | Marriott Hotel, 38th Floor (roof level) | 3/6/09 | 0.55 | Mercury | EPA 324/1631 | BRL | 3/9/09 | < 27.0 | No | No | |
| TotalHg-ST14-3/6/09 | 0911001-09 | West Face - South end at corner (scaffolding level) | 3/6/09 | 0.55 | Mercury | EPA 324/1631 | BRL | 3/9/09 | < 27.0 | No | No | |
| TotalHg-ST15-3/6/09 | 0911001-10 | South Face - East end at corner (scaffolding level) | 3/6/09 | 0.51 | Mercury | EPA 324/1631 | BRL | 3/9/09 | < 29.0 | No | No | |
| TotalHg-ST16-3/6/09 | 0911001-11 | East Face - North end at corner (scaffolding level) | 3/6/09 | 0.52 | Mercury | EPA 324/1631 | BRL | 3/9/09 | < 29.0 | No | No | |
| TotalHg-ST17-3/6/09 | 0911001-12 | North Face - West end at corner (scaffolding level) | 3/6/09 | 0.51 | Mercury | EPA 324/1631 | BRL | 3/9/09 | < 29.0 | No | No | |