

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-3/8/08	0811009-01	Southwest Area (sidewalk bridge level)	3/8/08	0.51	Mercury	EPA 324/1631	BRL	3/11/08	< 29.0	No	No	
TotalHg-ST2-3/8/08	0811009-02	Southeast Area (sidewalk bridge level)	3/8/08	0.56	Mercury	EPA 324/1631	BRL	3/11/08	< 27.0	No	No	
TotalHg-ST4-3/8/08	0811009-03	Northwest Area (street-level)	3/8/08	0.52	Mercury	EPA 324/1631	BRL	3/11/08	< 29.0	No	No	
TotalHg-ST5-3/8/08	0811009-04	Firehouse #10 (roof level)	3/8/08	0.56	Mercury	EPA 324/1631	BRL	3/11/08	< 27.0	No	No	
TotalHg-ST10-3/8/08	0811009-05	North Side Sidewalk Bridge	3/8/08	0.54	Mercury	EPA 324/1631	BRL	3/11/08	< 28.0	No	No	
TotalHg-ST11-3/8/08	0811009-06	90 Trinity Place (roof level)	3/8/08	0.54	Mercury	EPA 324/1631	BRL	3/11/08	< 28.0	No	No	
TotalHg-ST12-3/8/08	0811009-07	110 Greenwich Street (roof level)	3/8/08	0.52	Mercury	EPA 324/1631	BRL	3/11/08	< 29.0	No	No	
TotalHg-ST13-3/8/08	0811009-08	Marriott Hotel, 38th Floor (roof level)	3/8/08	0.56	Mercury	EPA 324/1631	BRL	3/11/08	< 27.0	No	No	
TotalHg-ST14-3/8/08	0811009-09	West Face - South end at corner (scaffolding level)	3/8/08	0.54	Mercury	EPA 324/1631	BRL	3/11/08	< 28.0	No	No	
TotalHg-ST15-3/8/08	0811009-10	South Face - East end at corner (scaffolding level)	3/8/08	0.53	Mercury	EPA 324/1631	BRL	3/11/08	< 28.0	No	No	
TotalHg-ST16-3/8/08	0811009-11	East Face - North end at corner (scaffolding level)	3/8/08	0.52	Mercury	EPA 324/1631	BRL	3/11/08	< 29.0	No	No	
TotalHg-ST17-3/8/08	0811009-12	North Face - West end at corner (scaffolding level)	3/8/08	0.58	Mercury	EPA 324/1631	BRL	3/11/08	< 26.0	No	No	
TotalHg-ST1-3/9/08	0811010-01	Southwest Area (sidewalk bridge level)	3/9/08	0.56	Mercury	EPA 324/1631	BRL	3/11/08	< 27.0	No	No	
TotalHg-ST2-3/9/08	0811010-02	Southeast Area (sidewalk bridge level)	3/9/08	0.56	Mercury	EPA 324/1631	BRL	3/11/08	< 27.0	No	No	
TotalHg-ST4-3/9/08	0811010-03	Northwest Area (street-level)	3/9/08	0.56	Mercury	EPA 324/1631	BRL	3/11/08	< 27.0	No	No	
TotalHg-ST5-3/9/08	0811010-04	Firehouse #10 (roof level)	3/9/08	0.60	Mercury	EPA 324/1631	BRL	3/11/08	< 25.0	No	No	
TotalHg-ST10-3/9/08	0811010-05	North Side Sidewalk Bridge	3/9/08	0.54	Mercury	EPA 324/1631	BRL	3/11/08	< 28.0	No	No	
TotalHg-ST11-3/9/08	0811010-06	90 Trinity Place (roof level)	3/9/08	0.55	Mercury	EPA 324/1631	BRL	3/11/08	< 27.0	No	No	
TotalHg-ST12-3/9/08	0811010-07	110 Greenwich Street (roof level)	3/9/08	0.56	Mercury	EPA 324/1631	BRL	3/11/08	< 27.0	No	No	
TotalHg-ST13-3/9/08	0811010-08	Marriott Hotel, 38th Floor (roof level)	3/9/08	0.54	Mercury	EPA 324/1631	BRL	3/11/08	< 28.0	No	No	
TotalHg-ST14-3/9/08	0811010-09	West Face - South end at corner (scaffolding level)	3/9/08	0.58	Mercury	EPA 324/1631	BRL	3/11/08	< 26.0	No	No	
TotalHg-ST15-3/9/08	0811010-10	South Face - East end at corner (scaffolding level)	3/9/08	0.55	Mercury	EPA 324/1631	BRL	3/11/08	< 27.0	No	No	
TotalHg-ST16-3/9/08	0811010-11	East Face - North end at corner (scaffolding level)	3/9/08	0.57	Mercury	EPA 324/1631	BRL	3/11/08	< 26.0	No	No	
TotalHg-ST17-3/9/08	0811010-12	North Face - West end at corner (scaffolding level)	3/9/08	0.56	Mercury	EPA 324/1631	BRL	3/11/08	< 27.0	No	No	