

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-3/9/07	07BR0316-01	Southwest Area (sidewalk bridge level)	3/9/07	0.56	Mercury	EPA 324/1631	BRL	3/13/07	< 27.0	No	No	
TotalHg-ST2-3/9/07	07BR0316-02	Southeast Area (sidewalk bridge level)	3/9/07	0.57	Mercury	EPA 324/1631	BRL	3/13/07	< 26.0	No	No	
TotalHg-ST4-3/9/07	07BR0316-03	Northwest Area (street-level)	3/9/07	0.56	Mercury	EPA 324/1631	BRL	3/13/07	< 27.0	No	No	
TotalHg-ST5-3/9/07	07BR0316-04	Firehouse #10 (roof level)	3/9/07	0.55	Mercury	EPA 324/1631	BRL	3/13/07	< 27.0	No	No	
TotalHg-ST10-3/9/07	07BR0316-05	North Side Sidewalk Bridge	3/9/07	0.61	Mercury	EPA 324/1631	BRL	3/13/07	< 25.0	No	No	
TotalHg-ST11-3/9/07	07BR0316-06	90 Trinity Place (roof level)	3/9/07	0.58	Mercury	EPA 324/1631	BRL	3/13/07	< 26.0	No	No	
TotalHg-ST12-3/9/07	07BR0316-07	110 Greenwich Street (roof level)	3/9/07	0.57	Mercury	EPA 324/1631	BRL	3/13/07	< 26.0	No	No	
TotalHg-ST13-3/9/07	07BR0316-08	Marriott Hotel, 38th Floor (roof level)	3/9/07	0.55	Mercury	EPA 324/1631	BRL	3/13/07	< 27.0	No	No	
TotalHg-ST14-3/9/07	07BR0316-09	West Face - South end at corner (scaffolding level)	3/9/07	0.53	Mercury	EPA 324/1631	BRL	3/13/07	< 28.0	No	No	
TotalHg-ST15-3/9/07	07BR0316-10	South Face - East end at corner (scaffolding level)	3/9/07	0.53	Mercury	EPA 324/1631	BRL	3/13/07	< 28.0	No	No	
TotalHg-ST16-3/9/07	07BR0316-11	East Face - North end at corner (scaffolding level)	3/9/07	0.52	Mercury	EPA 324/1631	BRL	3/13/07	< 29.0	No	No	
TotalHg-ST17-3/9/07	07BR0316-12	North Face - West end at corner (scaffolding level)	3/9/07	0.55	Mercury	EPA 324/1631	BRL	3/13/07	< 27.0	No	No	
TotalHg-ST1-3/10/07	07BR0317-01	Southwest Area (sidewalk bridge level)	3/10/07	0.56	Mercury	EPA 324/1631	BRL	3/13/07	< 27.0	No	No	
TotalHg-ST2-3/10/07	07BR0317-02	Southeast Area (sidewalk bridge level)	3/10/07	0.53	Mercury	EPA 324/1631	BRL	3/13/07	< 28.0	No	No	
TotalHg-ST4-3/10/07	07BR0317-03	Northwest Area (street-level)	3/10/07	0.57	Mercury	EPA 324/1631	BRL	3/13/07	< 26.0	No	No	
TotalHg-ST5-3/10/07	07BR0317-04	Firehouse #10 (roof level)	3/10/07	0.55	Mercury	EPA 324/1631	BRL	3/13/07	< 27.0	No	No	
TotalHg-ST10-3/10/07	07BR0317-05	North Side Sidewalk Bridge	3/10/07	0.57	Mercury	EPA 324/1631	BRL	3/13/07	< 26.0	No	No	
TotalHg-ST11-3/10/07	07BR0317-06	90 Trinity Place (roof level)	3/10/07	0.54	Mercury	EPA 324/1631	BRL	3/13/07	< 28.0	No	No	
TotalHg-ST12-3/10/07	07BR0317-07	110 Greenwich Street (roof level)	3/10/07	0.54	Mercury	EPA 324/1631	BRL	3/13/07	< 28.0	No	No	
TotalHg-ST13-3/10/07	07BR0317-08	Marriott Hotel, 38th Floor (roof level)	3/10/07	0.54	Mercury	EPA 324/1631	BRL	3/13/07	< 28.0	No	No	
TotalHg-ST14-3/10/07	07BR0317-09	West Face - South end at corner (scaffolding level)	3/10/07	0.54	Mercury	EPA 324/1631	BRL	3/13/07	< 28.0	No	No	
TotalHg-ST15-3/10/07	07BR0317-10	South Face - East end at corner (scaffolding level)	3/10/07	0.53	Mercury	EPA 324/1631	BRL	3/13/07	< 28.0	No	No	
TotalHg-ST16-3/10/07	07BR0317-11	East Face - North end at corner (scaffolding level)	3/10/07	0.55	Mercury	EPA 324/1631	BRL	3/13/07	< 27.0	No	No	
TotalHg-ST17-3/10/07	07BR0317-12	North Face - West end at corner (scaffolding level)	3/10/07	0.54	Mercury	EPA 324/1631	BRL	3/13/07	< 28.0	No	No	
TotalHg-ST1-3/11/07	07BR0318-01	Southwest Area (sidewalk bridge level)	3/11/07	0.56	Mercury	EPA 324/1631	BRL	3/13/07	< 27.0	No	No	
TotalHg-ST2-3/11/07	07BR0318-02	Southeast Area (sidewalk bridge level)	3/11/07	0.54	Mercury	EPA 324/1631	BRL	3/13/07	< 28.0	No	No	
TotalHg-ST4-3/11/07	07BR0318-03	Northwest Area (street-level)	3/11/07	0.55	Mercury	EPA 324/1631	BRL	3/13/07	< 27.0	No	No	
TotalHg-ST5-3/11/07	07BR0318-04	Firehouse #10 (roof level)	3/11/07	0.59	Mercury	EPA 324/1631	BRL	3/13/07	< 25.0	No	No	
TotalHg-ST10-3/11/07	07BR0318-05	North Side Sidewalk Bridge	3/11/07	0.56	Mercury	EPA 324/1631	BRL	3/13/07	< 27.0	No	No	
TotalHg-ST11-3/11/07	07BR0318-06	90 Trinity Place (roof level)	3/11/07	0.53	Mercury	EPA 324/1631	BRL	3/13/07	< 28.0	No	No	
TotalHg-ST12-3/11/07	07BR0318-07	110 Greenwich Street (roof level)	3/11/07	0.57	Mercury	EPA 324/1631	BRL	3/13/07	< 26.0	No	No	
TotalHg-ST13-3/11/07	07BR0318-08	Marriott Hotel, 38th Floor (roof level)	3/11/07	0.59	Mercury	EPA 324/1631	BRL	3/13/07	< 25.0	No	No	

Note:

1. Mercury samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on March 11, 2007 were not available for analysis. These stations were offline for relocation to the 20th floor scaffolding from the 30th floor scaffolding. Electrical service for these relocated stations was made available at 1100 hrs on 3/12/2007.