

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-3/22/06	06BR0446-01	Southwest Area (sidewalk bridge level)	3/22/06	0.57	Mercury	EPA 324/1631	BRL	3/24/06	< 26.0	No	No	
TotalHg-ST2-3/22/06	06BR0446-02	Southeast Area (sidewalk bridge level)	3/22/06	0.57	Mercury	EPA 324/1631	BRL	3/24/06	< 26.0	No	No	
TotalHg-ST4-3/22/06	06BR0446-03	Northwest Area (street-level)	3/22/06	0.57	Mercury	EPA 324/1631	BRL	3/24/06	< 26.0	No	No	
TotalHg-ST5-3/22/06	06BR0446-04	Firehouse #10 (roof level)	3/22/06	0.58	Mercury	EPA 324/1631	BRL	3/24/06	< 26.0	No	No	
TotalHg-ST10-3/22/06	06BR0446-05	North Side Sidewalk Bridge	3/22/06	0.57	Mercury	EPA 324/1631	BRL	3/24/06	< 26.0	No	No	
TotalHg-ST11-3/22/06	06BR0446-06	90 Trinity Place (roof level)	3/22/06	0.57	Mercury	EPA 324/1631	BRL	3/24/06	< 26.0	No	No	
TotalHg-ST12-3/22/06	06BR0446-07	110 Greenwich Street (roof level)	3/22/06	0.57	Mercury	EPA 324/1631	BRL	3/24/06	< 26.0	No	No	
TotalHg-ST13-3/22/06	06BR0446-08	Marriott Hotel, 38th Floor (roof level)	3/22/06	0.57	Mercury	EPA 324/1631	BRL	3/24/06	< 26.0	No	No	
TotalHg-ST14-3/22/06	06BR0446-09	West Face - South end at corner (scaffolding level)	3/22/06	0.58	Mercury	EPA 324/1631	BRL	3/24/06	< 26.0	No	No	
TotalHg-ST15-3/22/06	06BR0446-10	South Face - East end at corner (scaffolding level)	3/22/06	0.58	Mercury	EPA 324/1631	BRL	3/24/06	< 26.0	No	No	
TotalHg-ST16-3/22/06	06BR0446-11	East Face - North end at corner (scaffolding level)	3/22/06	0.58	Mercury	EPA 324/1631	BRL	3/24/06	< 26.0	No	No	
TotalHg-ST17-3/22/06	06BR0446-12	North Face - West end at corner (scaffolding level)	3/22/06	0.58	Mercury	EPA 324/1631	BRL	3/24/06	< 26.0	No	No	
TotalHg-ST1-3/23/06	06BR0450-01	Southwest Area (sidewalk bridge level)	3/23/06	0.58	Mercury	EPA 324/1631	BRL	3/25/06	< 26.0	No	No	
TotalHg-ST2-3/23/06	06BR0450-02	Southeast Area (sidewalk bridge level)	3/23/06	0.58	Mercury	EPA 324/1631	BRL	3/25/06	< 26.0	No	No	
TotalHg-ST4-3/23/06	06BR0450-03	Northwest Area (street-level)	3/23/06	0.59	Mercury	EPA 324/1631	BRL	3/25/06	< 25.0	No	No	
TotalHg-ST5-3/23/06	06BR0450-04	Firehouse #10 (roof level)	3/23/06	0.57	Mercury	EPA 324/1631	BRL	3/25/06	< 26.0	No	No	
TotalHg-ST10-3/23/06	06BR0450-05	North Side Sidewalk Bridge	3/23/06	0.59	Mercury	EPA 324/1631	BRL	3/25/06	< 25.0	No	No	
TotalHg-ST11-3/23/06	06BR0450-06	90 Trinity Place (roof level)	3/23/06	0.58	Mercury	EPA 324/1631	BRL	3/25/06	< 26.0	No	No	
TotalHg-ST12-3/23/06	06BR0450-07	110 Greenwich Street (roof level)	3/23/06	0.59	Mercury	EPA 324/1631	BRL	3/25/06	< 25.0	No	No	
TotalHg-ST13-3/23/06	06BR0450-08	Marriott Hotel, 38th Floor (roof level)	3/23/06	0.62	Mercury	EPA 324/1631	BRL	3/25/06	< 24.0	No	No	
TotalHg-ST14-3/23/06	06BR0450-09	West Face - South end at corner (scaffolding level)	3/23/06	0.58	Mercury	EPA 324/1631	BRL	3/25/06	< 26.0	No	No	
TotalHg-ST15-3/23/06	06BR0450-10	South Face - East end at corner (scaffolding level)	3/23/06	0.58	Mercury	EPA 324/1631	BRL	3/25/06	< 26.0	No	No	
TotalHg-ST16-3/23/06	06BR0450-11	East Face - North end at corner (scaffolding level)	3/23/06	0.58	Mercury	EPA 324/1631	BRL	3/25/06	< 26.0	No	No	
TotalHg-ST17-3/23/06	06BR0450-12	North Face - West end at corner (scaffolding level)	3/23/06	0.58	Mercury	EPA 324/1631	BRL	3/25/06	< 26.0	No	No	