

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target	Exceeds EPA	Comments
									300	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-3/27/07	07BR0388-01	Southwest Area (sidewalk bridge level)	3/27/07	0.55	Mercury	EPA 324/1631	BRL	3/29/07	< 27.0	No	No	
TotalHg-ST2-3/27/07	07BR0388-02	Southeast Area (sidewalk bridge level)	3/27/07	0.54	Mercury	EPA 324/1631	BRL	3/29/07	< 28.0	No	No	
TotalHg-ST4-3/27/07	07BR0388-03	Northwest Area (street-level)	3/27/07	0.56	Mercury	EPA 324/1631	BRL	3/29/07	< 27.0	No	No	
TotalHg-ST5-3/27/07	07BR0388-04	Firehouse #10 (roof level)	3/27/07	0.60	Mercury	EPA 324/1631	BRL	3/29/07	< 25.0	No	No	
TotalHg-ST10-3/27/07	07BR0388-05	North Side Sidewalk Bridge	3/27/07	0.56	Mercury	EPA 324/1631	BRL	3/29/07	< 27.0	No	No	
TotalHg-ST11-3/27/07	07BR0388-06	90 Trinity Place (roof level)	3/27/07	0.55	Mercury	EPA 324/1631	BRL	3/29/07	< 27.0	No	No	
TotalHg-ST12-3/27/07	07BR0388-07	110 Greenwich Street (roof level)	3/27/07	0.58	Mercury	EPA 324/1631	BRL	3/29/07	< 26.0	No	No	
TotalHg-ST13-3/27/07	07BR0388-08	Marriott Hotel, 38th Floor (roof level)	3/27/07	0.59	Mercury	EPA 324/1631	BRL	3/29/07	< 25.0	No	No	
TotalHg-ST14-3/27/07	07BR0388-09	West Face - South end at corner (scaffolding level)	3/27/07	0.60	Mercury	EPA 324/1631	BRL	3/29/07	< 25.0	No	No	
TotalHg-ST15-3/27/07	07BR0388-10	South Face - East end at corner (scaffolding level)	3/27/07	0.55	Mercury	EPA 324/1631	BRL	3/29/07	< 27.0	No	No	
TotalHg-ST16-3/27/07	07BR0388-11	East Face - North end at corner (scaffolding level)	3/27/07	0.57	Mercury	EPA 324/1631	BRL	3/29/07	< 26.0	No	No	
TotalHg-ST17-3/27/07	07BR0388-12	North Face - West end at corner (scaffolding level)	3/27/07	0.59	Mercury	EPA 324/1631	BRL	3/29/07	< 25.0	No	No	
TotalHg-ST1-3/28/07	07BR0397-01	Southwest Area (sidewalk bridge level)	3/28/07	0.58	Mercury	EPA 324/1631	BRL	3/30/07	< 26.0	No	No	
TotalHg-ST2-3/28/07	07BR0397-02	Southeast Area (sidewalk bridge level)	3/28/07	0.56	Mercury	EPA 324/1631	BRL	3/30/07	< 27.0	No	No	
TotalHg-ST4-3/28/07	07BR0397-03	Northwest Area (street-level)	3/28/07	0.56	Mercury	EPA 324/1631	BRL	3/30/07	< 27.0	No	No	
TotalHg-ST5-3/28/07	07BR0397-04	Firehouse #10 (roof level)	3/28/07	0.58	Mercury	EPA 324/1631	BRL	3/30/07	< 26.0	No	No	
TotalHg-ST10-3/28/07	07BR0397-05	North Side Sidewalk Bridge	3/28/07	0.57	Mercury	EPA 324/1631	BRL	3/30/07	< 26.0	No	No	
TotalHg-ST11-3/28/07	07BR0397-06	90 Trinity Place (roof level)	3/28/07	0.53	Mercury	EPA 324/1631	BRL	3/30/07	< 28.0	No	No	
TotalHg-ST12-3/28/07	07BR0397-07	110 Greenwich Street (roof level)	3/28/07	0.53	Mercury	EPA 324/1631	BRL	3/30/07	< 28.0	No	No	
TotalHg-ST13-3/28/07	07BR0397-08	Marriott Hotel, 38th Floor (roof level)	3/28/07	0.58	Mercury	EPA 324/1631	BRL	3/30/07	< 26.0	No	No	
TotalHg-ST14-3/28/07	07BR0397-09	West Face - South end at corner (scaffolding level)	3/28/07	0.55	Mercury	EPA 324/1631	BRL	3/30/07	< 27.0	No	No	
TotalHg-ST15-3/28/07	07BR0397-10	South Face - East end at corner (scaffolding level)	3/28/07	0.57	Mercury	EPA 324/1631	BRL	3/30/07	< 26.0	No	No	
TotalHg-ST16-3/28/07	07BR0397-11	East Face - North end at corner (scaffolding level)	3/28/07	0.56	Mercury	EPA 324/1631	BRL	3/30/07	< 27.0	No	No	
TotalHg-ST17-3/28/07	07BR0397-12	North Face - West end at corner (scaffolding level)	3/28/07	0.55	Mercury	EPA 324/1631	BRL	3/30/07	< 27.0	No	No	
TotalHg-ST1-3/29/07	07BR0416-01	Southwest Area (sidewalk bridge level)	3/29/07	0.53	Mercury	EPA 324/1631	BRL	3/31/07	< 28.0	No	No	
TotalHg-ST2-3/29/07	07BR0416-02	Southeast Area (sidewalk bridge level)	3/29/07	0.54	Mercury	EPA 324/1631	BRL	3/31/07	< 28.0	No	No	
TotalHg-ST4-3/29/07	07BR0416-03	Northwest Area (street-level)	3/29/07	0.56	Mercury	EPA 324/1631	BRL	3/31/07	< 27.0	No	No	
TotalHg-ST5-3/29/07	07BR0416-04	Firehouse #10 (roof level)	3/29/07	0.59	Mercury	EPA 324/1631	BRL	3/31/07	< 25.0	No	No	
TotalHg-ST10-3/29/07	07BR0416-05	North Side Sidewalk Bridge	3/29/07	0.57	Mercury	EPA 324/1631	BRL	3/31/07	< 26.0	No	No	
TotalHg-ST11-3/29/07	07BR0416-06	90 Trinity Place (roof level)	3/29/07	0.54	Mercury	EPA 324/1631	BRL	3/31/07	< 28.0	No	No	
TotalHg-ST12-3/29/07	07BR0416-07	110 Greenwich Street (roof level)	3/29/07	0.55	Mercury	EPA 324/1631	BRL	3/31/07	< 27.0	No	No	
TotalHg-ST13-3/29/07	07BR0416-08	Marriott Hotel, 38th Floor (roof level)	3/29/07	0.58	Mercury	EPA 324/1631	BRL	3/31/07	< 26.0	No	No	
TotalHg-ST14-3/29/07	07BR0416-09	West Face - South end at corner (scaffolding level)	3/29/07	0.59	Mercury	EPA 324/1631	BRL	3/31/07	< 25.0	No	No	
TotalHg-ST15-3/29/07	07BR0416-10	South Face - East end at corner (scaffolding level)	3/29/07	0.59	Mercury	EPA 324/1631	BRL	3/31/07	< 25.0	No	No	
TotalHg-ST16-3/29/07	07BR0416-11	East Face - North end at corner (scaffolding level)	3/29/07	0.59	Mercury	EPA 324/1631	BRL	3/31/07	< 25.0	No	No	
TotalHg-ST17-3/29/07	07BR0416-12	North Face - West end at corner (scaffolding level)	3/29/07	0.55	Mercury	EPA 324/1631	BRL	3/31/07	< 27.0	No	No	