

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-3/27/08	0813045-01	Southwest Area (sidewalk bridge level)	3/27/08	0.58	Mercury	EPA 324/1631	BRL	3/29/08	< 26.0	No	No	
TotalHg-ST2-3/27/08	0813045-02	Southeast Area (sidewalk bridge level)	3/27/08	0.54	Mercury	EPA 324/1631	BRL	3/29/08	< 28.0	No	No	
TotalHg-ST4-3/27/08	0813045-03	Northwest Area (street-level)	3/27/08	0.58	Mercury	EPA 324/1631	BRL	3/29/08	< 26.0	No	No	
TotalHg-ST5-3/27/08	0813045-04	Firehouse #10 (roof level)	3/27/08	0.56	Mercury	EPA 324/1631	BRL	3/29/08	< 27.0	No	No	
TotalHg-ST10-3/27/08	0813045-05	North Side Sidewalk Bridge	3/27/08	0.58	Mercury	EPA 324/1631	BRL	3/29/08	< 26.0	No	No	
TotalHg-ST11-3/27/08	0813045-06	90 Trinity Place (roof level)	3/27/08	0.57	Mercury	EPA 324/1631	BRL	3/29/08	< 26.0	No	No	
TotalHg-ST12-3/27/08	0813045-07	110 Greenwich Street (roof level)	3/27/08	0.58	Mercury	EPA 324/1631	BRL	3/29/08	< 26.0	No	No	
TotalHg-ST13-3/27/08	0813045-08	Marriott Hotel, 38th Floor (roof level)	3/27/08	0.53	Mercury	EPA 324/1631	BRL	3/29/08	< 28.0	No	No	
TotalHg-ST14-3/27/08	0813045-09	West Face - South end at corner (scaffolding level)	3/27/08	0.57	Mercury	EPA 324/1631	BRL	3/29/08	< 26.0	No	No	
TotalHg-ST15-3/27/08	0813045-10	South Face - East end at corner (scaffolding level)	3/27/08	0.61	Mercury	EPA 324/1631	BRL	3/29/08	< 25.0	No	No	
TotalHg-ST16-3/27/08	0813045-11	East Face - North end at corner (scaffolding level)	3/27/08	0.56	Mercury	EPA 324/1631	BRL	3/29/08	< 27.0	No	No	
TotalHg-ST17-3/27/08	0813045-12	North Face - West end at corner (scaffolding level)	3/27/08	0.61	Mercury	EPA 324/1631	BRL	3/29/08	< 25.0	No	No	
TotalHg-ST1-3/28/08	0814002-01	Southwest Area (sidewalk bridge level)	3/28/08	0.57	Mercury	EPA 324/1631	BRL	3/31/08	< 26.0	No	No	
TotalHg-ST2-3/28/08	0814002-02	Southeast Area (sidewalk bridge level)	3/28/08	0.59	Mercury	EPA 324/1631	BRL	3/31/08	< 25.0	No	No	
TotalHg-ST4-3/28/08	0814002-03	Northwest Area (street-level)	3/28/08	0.61	Mercury	EPA 324/1631	BRL	3/31/08	< 25.0	No	No	
TotalHg-ST5-3/28/08	0814002-04	Firehouse #10 (roof level)	3/28/08	0.57	Mercury	EPA 324/1631	BRL	3/31/08	< 26.0	No	No	
TotalHg-ST10-3/28/08	0814002-05	North Side Sidewalk Bridge	3/28/08	0.62	Mercury	EPA 324/1631	BRL	3/31/08	< 24.0	No	No	
TotalHg-ST11-3/28/08	0814002-06	90 Trinity Place (roof level)	3/28/08	0.56	Mercury	EPA 324/1631	BRL	3/31/08	< 27.0	No	No	
TotalHg-ST12-3/28/08	0814002-07	110 Greenwich Street (roof level)	3/28/08	0.61	Mercury	EPA 324/1631	BRL	3/31/08	< 25.0	No	No	
TotalHg-ST13-3/28/08	0814002-08	Marriott Hotel, 38th Floor (roof level)	3/28/08	0.54	Mercury	EPA 324/1631	BRL	3/31/08	< 28.0	No	No	
TotalHg-ST14-3/28/08	0814002-09	West Face - South end at corner (scaffolding level)	3/28/08	0.53	Mercury	EPA 324/1631	BRL	3/31/08	< 28.0	No	No	
TotalHg-ST15-3/28/08	0814002-10	South Face - East end at corner (scaffolding level)	3/28/08	0.56	Mercury	EPA 324/1631	BRL	3/31/08	< 27.0	No	No	
TotalHg-ST16-3/28/08	0814002-11	East Face - North end at corner (scaffolding level)	3/28/08	0.52	Mercury	EPA 324/1631	BRL	3/31/08	< 29.0	No	No	
TotalHg-ST17-3/28/08	0814002-12	North Face - West end at corner (scaffolding level)	3/28/08	0.56	Mercury	EPA 324/1631	BRL	3/31/08	< 27.0	No	No	