

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-3/30/07	07BR0422-01	Southwest Area (sidewalk bridge level)	3/30/07	0.60	Mercury	EPA 324/1631	BRL	4/3/07	< 25.0	No	No	
TotalHg-ST2-3/30/07	07BR0422-02	Southeast Area (sidewalk bridge level)	3/30/07	0.58	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST4-3/30/07	07BR0422-03	Northwest Area (street-level)	3/30/07	0.57	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST5-3/30/07	07BR0422-04	Firehouse #10 (roof level)	3/30/07	0.57	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST10-3/30/07	07BR0422-05	North Side Sidewalk Bridge	3/30/07	0.57	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST11-3/30/07	07BR0422-06	90 Trinity Place (roof level)	3/30/07	0.60	Mercury	EPA 324/1631	BRL	4/3/07	< 25.0	No	No	
TotalHg-ST12-3/30/07	07BR0422-07	110 Greenwich Street (roof level)	3/30/07	0.59	Mercury	EPA 324/1631	BRL	4/3/07	< 25.0	No	No	
TotalHg-ST13-3/30/07	07BR0422-08	Marriott Hotel, 38th Floor (roof level)	3/30/07	0.58	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST14-3/30/07	07BR0422-09	West Face - South end at corner (scaffolding level)	3/30/07	0.55	Mercury	EPA 324/1631	BRL	4/3/07	< 27.0	No	No	
TotalHg-ST15-3/30/07	07BR0422-10	South Face - East end at corner (scaffolding level)	3/30/07	0.54	Mercury	EPA 324/1631	BRL	4/3/07	< 28.0	No	No	
TotalHg-ST16-3/30/07	07BR0422-11	East Face - North end at corner (scaffolding level)	3/30/07	0.56	Mercury	EPA 324/1631	BRL	4/3/07	< 27.0	No	No	
TotalHg-ST17-3/30/07	07BR0422-12	North Face - West end at corner (scaffolding level)	3/30/07	0.57	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST1-3/31/07	07BR0423-01	Southwest Area (sidewalk bridge level)	3/31/07	0.53	Mercury	EPA 324/1631	BRL	4/3/07	< 28.0	No	No	
TotalHg-ST2-3/31/07	07BR0423-02	Southeast Area (sidewalk bridge level)	3/31/07	0.58	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST4-3/31/07	07BR0423-03	Northwest Area (street-level)	3/31/07	0.54	Mercury	EPA 324/1631	BRL	4/3/07	< 28.0	No	No	
TotalHg-ST5-3/31/07	07BR0423-04	Firehouse #10 (roof level)	3/31/07	0.58	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST10-3/31/07	07BR0423-05	North Side Sidewalk Bridge	3/31/07	0.56	Mercury	EPA 324/1631	BRL	4/3/07	< 27.0	No	No	
TotalHg-ST11-3/31/07	07BR0423-06	90 Trinity Place (roof level)	3/31/07	0.56	Mercury	EPA 324/1631	BRL	4/3/07	< 27.0	No	No	
TotalHg-ST12-3/31/07	07BR0423-07	110 Greenwich Street (roof level)	3/31/07	0.57	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST13-3/31/07	07BR0423-08	Marriott Hotel, 38th Floor (roof level)	3/31/07	0.59	Mercury	EPA 324/1631	BRL	4/3/07	< 25.0	No	No	
TotalHg-ST14-3/31/07	07BR0423-09	West Face - South end at corner (scaffolding level)	3/31/07	0.58	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST15-3/31/07	07BR0423-10	South Face - East end at corner (scaffolding level)	3/31/07	0.56	Mercury	EPA 324/1631	BRL	4/3/07	< 27.0	No	No	
TotalHg-ST16-3/31/07	07BR0423-11	East Face - North end at corner (scaffolding level)	3/31/07	0.57	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST17-3/31/07	07BR0423-12	North Face - West end at corner (scaffolding level)	3/31/07	0.58	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST1-4/01/07	07BR0424-01	Southwest Area (sidewalk bridge level)	4/1/07	0.55	Mercury	EPA 324/1631	BRL	4/3/07	< 27.0	No	No	
TotalHg-ST2-4/01/07	07BR0424-02	Southeast Area (sidewalk bridge level)	4/1/07	0.54	Mercury	EPA 324/1631	BRL	4/3/07	< 28.0	No	No	
TotalHg-ST4-4/01/07	07BR0424-03	Northwest Area (street-level)	4/1/07	0.59	Mercury	EPA 324/1631	BRL	4/3/07	< 25.0	No	No	
TotalHg-ST5-4/01/07	07BR0424-04	Firehouse #10 (roof level)	4/1/07	0.60	Mercury	EPA 324/1631	BRL	4/3/07	< 25.0	No	No	
TotalHg-ST10-4/01/07	07BR0424-05	North Side Sidewalk Bridge	4/1/07	0.56	Mercury	EPA 324/1631	BRL	4/3/07	< 27.0	No	No	
TotalHg-ST11-4/01/07	07BR0424-06	90 Trinity Place (roof level)	4/1/07	0.54	Mercury	EPA 324/1631	BRL	4/3/07	< 28.0	No	No	
TotalHg-ST12-4/01/07	07BR0424-07	110 Greenwich Street (roof level)	4/1/07	0.53	Mercury	EPA 324/1631	BRL	4/3/07	< 28.0	No	No	
TotalHg-ST13-4/01/07	07BR0424-08	Marriott Hotel, 38th Floor (roof level)	4/1/07	0.60	Mercury	EPA 324/1631	BRL	4/3/07	< 25.0	No	No	
TotalHg-ST14-4/01/07	07BR0424-09	West Face - South end at corner (scaffolding level)	4/1/07	0.58	Mercury	EPA 324/1631	BRL	4/3/07	< 26.0	No	No	
TotalHg-ST15-4/01/07	07BR0424-10	South Face - East end at corner (scaffolding level)	4/1/07	0.62	Mercury	EPA 324/1631	BRL	4/3/07	< 24.0	No	No	
TotalHg-ST16-4/01/07	07BR0424-11	East Face - North end at corner (scaffolding level)	4/1/07	0.64	Mercury	EPA 324/1631	BRL	4/3/07	< 23.0	No	No	
TotalHg-ST17-4/01/07	07BR0424-12	North Face - West end at corner (scaffolding level)	4/1/07	0.63	Mercury	EPA 324/1631	BRL	4/3/07	< 24.0	No	No	