

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-4/2/08	0814034-01	Southwest Area (sidewalk bridge level)	4/2/08	0.58	Mercury	EPA 324/1631	BRL	4/4/08	< 26.0	No	No	
TotalHg-ST2-4/2/08	0814034-02	Southeast Area (sidewalk bridge level)	4/2/08	0.56	Mercury	EPA 324/1631	BRL	4/4/08	< 27.0	No	No	
TotalHg-ST4-4/2/08	0814034-03	Northwest Area (street-level)	4/2/08	0.56	Mercury	EPA 324/1631	BRL	4/4/08	< 27.0	No	No	
TotalHg-ST5-4/2/08	0814034-04	Firehouse #10 (roof level)	4/2/08	0.58	Mercury	EPA 324/1631	BRL	4/4/08	< 26.0	No	No	
TotalHg-ST10-4/2/08	0814034-05	North Side Sidewalk Bridge	4/2/08	0.56	Mercury	EPA 324/1631	BRL	4/4/08	< 27.0	No	No	
TotalHg-ST11-4/2/08	0814034-06	90 Trinity Place (roof level)	4/2/08	0.56	Mercury	EPA 324/1631	BRL	4/4/08	< 27.0	No	No	
TotalHg-ST12-4/2/08	0814034-07	110 Greenwich Street (roof level)	4/2/08	0.55	Mercury	EPA 324/1631	BRL	4/4/08	< 27.0	No	No	
TotalHg-ST13-4/2/08	0814034-08	Marriott Hotel, 38th Floor (roof level)	4/2/08	0.58	Mercury	EPA 324/1631	BRL	4/4/08	< 26.0	No	No	
TotalHg-ST14-4/2/08	0814034-09	West Face - South end at corner (scaffolding level)	4/2/08	0.59	Mercury	EPA 324/1631	BRL	4/4/08	< 25.0	No	No	
TotalHg-ST15-4/2/08	0814034-10	South Face - East end at corner (scaffolding level)	4/2/08	0.59	Mercury	EPA 324/1631	BRL	4/4/08	< 25.0	No	No	
TotalHg-ST16-4/2/08	0814034-11	East Face - North end at corner (scaffolding level)	4/2/08	0.59	Mercury	EPA 324/1631	BRL	4/4/08	< 25.0	No	No	
TotalHg-ST17-4/2/08	0814034-12	North Face - West end at corner (scaffolding level)	4/2/08	0.55	Mercury	EPA 324/1631	BRL	4/4/08	< 27.0	No	No	
TotalHg-ST1-4/3/08	0814044-01	Southwest Area (sidewalk bridge level)	4/3/08	0.52	Mercury	EPA 324/1631	BRL	4/5/08	< 29.0	No	No	
TotalHg-ST2-4/3/08	0814044-02	Southeast Area (sidewalk bridge level)	4/3/08	0.54	Mercury	EPA 324/1631	BRL	4/5/08	< 28.0	No	No	
TotalHg-ST4-4/3/08	0814044-03	Northwest Area (street-level)	4/3/08	0.57	Mercury	EPA 324/1631	BRL	4/5/08	< 26.0	No	No	
TotalHg-ST5-4/3/08	0814044-04	Firehouse #10 (roof level)	4/3/08	0.56	Mercury	EPA 324/1631	BRL	4/5/08	< 27.0	No	No	
TotalHg-ST10-4/3/08	0814044-05	North Side Sidewalk Bridge	4/3/08	0.57	Mercury	EPA 324/1631	BRL	4/5/08	< 26.0	No	No	
TotalHg-ST11-4/3/08	0814044-06	90 Trinity Place (roof level)	4/3/08	0.55	Mercury	EPA 324/1631	BRL	4/5/08	< 27.0	No	No	
TotalHg-ST12-4/3/08	0814044-07	110 Greenwich Street (roof level)	4/3/08	0.60	Mercury	EPA 324/1631	BRL	4/5/08	< 25.0	No	No	
TotalHg-ST13-4/3/08	0814044-08	Marriott Hotel, 38th Floor (roof level)	4/3/08	0.58	Mercury	EPA 324/1631	BRL	4/5/08	< 26.0	No	No	
TotalHg-ST14-4/3/08	0814044-09	West Face - South end at corner (scaffolding level)	4/3/08	0.53	Mercury	EPA 324/1631	BRL	4/5/08	< 28.0	No	No	
TotalHg-ST15-4/3/08	0814044-10	South Face - East end at corner (scaffolding level)	4/3/08	0.54	Mercury	EPA 324/1631	BRL	4/5/08	< 28.0	No	No	
TotalHg-ST16-4/3/08	0814044-11	East Face - North end at corner (scaffolding level)	4/3/08	0.56	Mercury	EPA 324/1631	BRL	4/5/08	< 27.0	No	No	
TotalHg-ST17-4/3/08	0814044-12	North Face - West end at corner (scaffolding level)	4/3/08	0.55	Mercury	EPA 324/1631	BRL	4/5/08	< 27.0	No	No	
TotalHg-ST1-4/4/08	0815001-01	Southwest Area (sidewalk bridge level)	4/4/08	0.57	Mercury	EPA 324/1631	BRL	4/7/08	< 26.0	No	No	
TotalHg-ST2-4/4/08	0815001-02	Southeast Area (sidewalk bridge level)	4/4/08	0.54	Mercury	EPA 324/1631	BRL	4/7/08	< 28.0	No	No	
TotalHg-ST4-4/4/08	0815001-03	Northwest Area (street-level)	4/4/08	0.54	Mercury	EPA 324/1631	BRL	4/7/08	< 28.0	No	No	
TotalHg-ST5-4/4/08	0815001-04	Firehouse #10 (roof level)	4/4/08	0.54	Mercury	EPA 324/1631	BRL	4/7/08	< 28.0	No	No	
TotalHg-ST10-4/4/08	0815001-05	North Side Sidewalk Bridge	4/4/08	0.54	Mercury	EPA 324/1631	BRL	4/7/08	< 28.0	No	No	
TotalHg-ST11-4/4/08	0815001-06	90 Trinity Place (roof level)	4/4/08	0.53	Mercury	EPA 324/1631	BRL	4/7/08	< 28.0	No	No	
TotalHg-ST12-4/4/08	0815001-07	110 Greenwich Street (roof level)	4/4/08	0.54	Mercury	EPA 324/1631	BRL	4/7/08	< 28.0	No	No	
TotalHg-ST13-4/4/08	0815001-08	Marriott Hotel, 38th Floor (roof level)	4/4/08	0.56	Mercury	EPA 324/1631	BRL	4/7/08	< 27.0	No	No	
TotalHg-ST14-4/4/08	0815001-09	West Face - South end at corner (scaffolding level)	4/4/08	0.56	Mercury	EPA 324/1631	BRL	4/7/08	< 27.0	No	No	
TotalHg-ST15-4/4/08	0815001-10	South Face - East end at corner (scaffolding level)	4/4/08	0.56	Mercury	EPA 324/1631	BRL	4/7/08	< 27.0	No	No	
TotalHg-ST16-4/4/08	0815001-11	East Face - North end at corner (scaffolding level)	4/4/08	0.55	Mercury	EPA 324/1631	BRL	4/7/08	< 27.0	No	No	
TotalHg-ST17-4/4/08	0815001-12	North Face - West end at corner (scaffolding level)	4/4/08	0.55	Mercury	EPA 324/1631	BRL	4/7/08	< 27.0	No	No	