

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-4/3/06	06BR0497-01	Southwest Area (sidewalk bridge level)	4/3/06	0.57	Mercury	EPA 324/1631	BRL	4/5/06	< 26.0	No	No	
TotalHg-ST2-4/3/06	06BR0497-02	Southeast Area (sidewalk bridge level)	4/3/06	0.58	Mercury	EPA 324/1631	BRL	4/5/06	< 26.0	No	No	
TotalHg-ST4-4/3/06	06BR0497-03	Northwest Area (street-level)	4/3/06	0.56	Mercury	EPA 324/1631	BRL	4/5/06	< 26.0	No	No	
TotalHg-ST5-4/3/06	06BR0497-04	Firehouse #10 (roof level)	4/3/06	0.57	Mercury	EPA 324/1631	BRL	4/5/06	< 26.0	No	No	
TotalHg-ST10-4/3/06	06BR0497-05	North Side Sidewalk Bridge	4/3/06	0.57	Mercury	EPA 324/1631	BRL	4/5/06	< 26.0	No	No	
TotalHg-ST11-4/3/06	06BR0497-06	90 Trinity Place (roof level)	4/3/06	0.57	Mercury	EPA 324/1631	BRL	4/5/06	< 26.0	No	No	
TotalHg-ST12-4/3/06	06BR0497-07	110 Greenwich Street (roof level)	4/3/06	0.58	Mercury	EPA 324/1631	BRL	4/5/06	< 26.0	No	No	
TotalHg-ST13-4/3/06	06BR0497-08	Marriott Hotel, 38th Floor (roof level)	4/3/06	0.57	Mercury	EPA 324/1631	BRL	4/5/06	< 26.0	No	No	
TotalHg-ST14-4/3/06	06BR0497-09	West Face - South end at corner (scaffolding level)	4/3/06	0.57	Mercury	EPA 324/1631	BRL	4/5/06	< 26.0	No	No	
TotalHg-ST15-4/3/06	06BR0497-10	South Face - East end at corner (scaffolding level)	4/3/06	0.58	Mercury	EPA 324/1631	BRL	4/5/06	< 26.0	No	No	
TotalHg-ST16-4/3/06	06BR0497-11	East Face - North end at corner (scaffolding level)	4/3/06	0.57	Mercury	EPA 324/1631	BRL	4/5/06	< 26.0	No	No	
TotalHg-ST17-4/3/06	06BR0497-12	North Face - West end at corner (scaffolding level)	4/3/06	0.58	Mercury	EPA 324/1631	BRL	4/5/06	< 26.0	No	No	
TotalHg-ST1-4/4/06	06BR0500-01	Southwest Area (sidewalk bridge level)	4/4/06	0.57	Mercury	EPA 324/1631	BRL	4/6/06	< 26.0	No	No	
TotalHg-ST2-4/4/06	06BR0500-02	Southeast Area (sidewalk bridge level)	4/4/06	0.58	Mercury	EPA 324/1631	BRL	4/6/06	< 26.0	No	No	
TotalHg-ST4-4/4/06	06BR0500-03	Northwest Area (street-level)	4/4/06	0.57	Mercury	EPA 324/1631	BRL	4/6/06	< 26.0	No	No	
TotalHg-ST5-4/4/06	06BR0500-04	Firehouse #10 (roof level)	4/4/06	0.58	Mercury	EPA 324/1631	BRL	4/6/06	< 26.0	No	No	
TotalHg-ST10-4/4/06	06BR0500-05	North Side Sidewalk Bridge	4/4/06	0.57	Mercury	EPA 324/1631	BRL	4/6/06	< 26.0	No	No	
TotalHg-ST11-4/4/06	06BR0500-06	90 Trinity Place (roof level)	4/4/06	0.57	Mercury	EPA 324/1631	BRL	4/6/06	< 26.0	No	No	
TotalHg-ST12-4/4/06	06BR0500-07	110 Greenwich Street (roof level)	4/4/06	0.56	Mercury	EPA 324/1631	BRL	4/6/06	< 26.0	No	No	
TotalHg-ST13-4/4/06	06BR0500-08	Marriott Hotel, 38th Floor (roof level)	4/4/06	0.58	Mercury	EPA 324/1631	BRL	4/6/06	< 26.0	No	No	
TotalHg-ST14-4/4/06	06BR0500-09	West Face - South end at corner (scaffolding level)	4/4/06	0.57	Mercury	EPA 324/1631	BRL	4/6/06	< 26.0	No	No	
TotalHg-ST15-4/4/06	06BR0500-10	South Face - East end at corner (scaffolding level)	4/4/06	0.57	Mercury	EPA 324/1631	BRL	4/6/06	< 26.0	No	No	
TotalHg-ST16-4/4/06	06BR0500-11	East Face - North end at corner (scaffolding level)	4/4/06	0.57	Mercury	EPA 324/1631	BRL	4/6/06	< 26.0	No	No	
TotalHg-ST17-4/4/06	06BR0500-12	North Face - West end at corner (scaffolding level)	4/4/06	0.58	Mercury	EPA 324/1631	BRL	4/6/06	< 26.0	No	No	