

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-4/4/09	0915006-01	Southwest Area (sidewalk bridge level)	4/4/09	0.56	Mercury	EPA 324/1631	BRL	4/7/09	< 27.0	No	No	
TotalHg-ST2-4/4/09	0915006-02	Southeast Area (sidewalk bridge level)	4/4/09	0.58	Mercury	EPA 324/1631	BRL	4/7/09	< 26.0	No	No	
TotalHg-ST4-4/4/09	0915006-03	Northwest Area (street-level)	4/4/09	0.57	Mercury	EPA 324/1631	BRL	4/7/09	< 26.0	No	No	
TotalHg-ST5-4/4/09	0915006-04	Firehouse #10 (roof level)	4/4/09	0.60	Mercury	EPA 324/1631	BRL	4/7/09	< 25.0	No	No	
TotalHg-ST10-4/4/09	0915006-05	North Side Sidewalk Bridge	4/4/09	0.57	Mercury	EPA 324/1631	BRL	4/7/09	< 26.0	No	No	
TotalHg-ST11-4/4/09	0915006-06	90 Trinity Place (roof level)	4/4/09	0.57	Mercury	EPA 324/1631	BRL	4/7/09	< 26.0	No	No	
TotalHg-ST12-4/4/09	0915006-07	110 Greenwich Street (roof level)	4/4/09	0.54	Mercury	EPA 324/1631	BRL	4/7/09	< 28.0	No	No	
TotalHg-ST13-4/4/09	0915006-08	Marriott Hotel, 38th Floor (roof level)	4/4/09	0.53	Mercury	EPA 324/1631	BRL	4/7/09	< 28.0	No	No	
TotalHg-ST14-4/4/09	0915006-09	West Face - South end at corner (scaffolding level)	4/4/09	0.61	Mercury	EPA 324/1631	BRL	4/7/09	< 25.0	No	No	
TotalHg-ST15-4/4/09	0915006-10	South Face - East end at corner (scaffolding level)	4/4/09	0.56	Mercury	EPA 324/1631	BRL	4/7/09	< 27.0	No	No	
TotalHg-ST16-4/4/09	0915006-11	East Face - North end at corner (scaffolding level)	4/4/09	0.57	Mercury	EPA 324/1631	BRL	4/7/09	< 26.0	No	No	
TotalHg-ST17-4/4/09	0915006-12	North Face - West end at corner (scaffolding level)	4/4/09	0.57	Mercury	EPA 324/1631	BRL	4/7/09	< 26.0	No	No	
TotalHg-ST1-4/5/09	0915007-01	Southwest Area (sidewalk bridge level)	4/5/09	0.62	Mercury	EPA 324/1631	BRL	4/7/09	< 24.0	No	No	
TotalHg-ST2-4/5/09	0915007-02	Southeast Area (sidewalk bridge level)	4/5/09	0.54	Mercury	EPA 324/1631	BRL	4/7/09	< 28.0	No	No	
TotalHg-ST4-4/5/09	0915007-03	Northwest Area (street-level)	4/5/09	0.54	Mercury	EPA 324/1631	BRL	4/7/09	< 28.0	No	No	
TotalHg-ST5-4/5/09	0915007-04	Firehouse #10 (roof level)	4/5/09	0.61	Mercury	EPA 324/1631	BRL	4/7/09	< 25.0	No	No	
TotalHg-ST10-4/5/09	0915007-05	North Side Sidewalk Bridge	4/5/09	0.59	Mercury	EPA 324/1631	BRL	4/7/09	< 25.0	No	No	
TotalHg-ST11-4/5/09	0915007-06	90 Trinity Place (roof level)	4/5/09	0.53	Mercury	EPA 324/1631	BRL	4/7/09	< 28.0	No	No	
TotalHg-ST12-4/5/09	0915007-07	110 Greenwich Street (roof level)	4/5/09	0.59	Mercury	EPA 324/1631	BRL	4/7/09	< 25.0	No	No	
TotalHg-ST13-4/5/09	0915007-08	Marriott Hotel, 38th Floor (roof level)	4/5/09	0.54	Mercury	EPA 324/1631	BRL	4/7/09	< 28.0	No	No	
TotalHg-ST14-4/5/09	0915007-09	West Face - South end at corner (scaffolding level)	4/5/09	0.60	Mercury	EPA 324/1631	BRL	4/7/09	< 25.0	No	No	
TotalHg-ST15-4/5/09	0915007-10	South Face - East end at corner (scaffolding level)	4/5/09	0.54	Mercury	EPA 324/1631	BRL	4/7/09	< 28.0	No	No	
TotalHg-ST16-4/5/09	0915007-11	East Face - North end at corner (scaffolding level)	4/5/09	0.55	Mercury	EPA 324/1631	BRL	4/7/09	< 27.0	No	No	
TotalHg-ST17-4/5/09	0915007-12	North Face - West end at corner (scaffolding level)	4/5/09	0.61	Mercury	EPA 324/1631	BRL	4/7/09	< 25.0	No	No	
TotalHg-ST1-4/6/09	0915011-01	Southwest Area (sidewalk bridge level)	4/6/09	0.61	Mercury	EPA 324/1631	BRL	4/8/09	< 25.0	No	No	
TotalHg-ST2-4/6/09	0915011-02	Southeast Area (sidewalk bridge level)	4/6/09	0.60	Mercury	EPA 324/1631	BRL	4/8/09	< 25.0	No	No	
TotalHg-ST4-4/6/09	0915011-03	Northwest Area (street-level)	4/6/09	0.61	Mercury	EPA 324/1631	BRL	4/8/09	< 25.0	No	No	
TotalHg-ST5-4/6/09	0915011-04	Firehouse #10 (roof level)	4/6/09	0.59	Mercury	EPA 324/1631	BRL	4/8/09	< 25.0	No	No	
TotalHg-ST10-4/6/09	0915011-05	North Side Sidewalk Bridge	4/6/09	0.58	Mercury	EPA 324/1631	BRL	4/8/09	< 26.0	No	No	
TotalHg-ST11-4/6/09	0915011-06	90 Trinity Place (roof level)	4/6/09	0.60	Mercury	EPA 324/1631	BRL	4/8/09	< 25.0	No	No	
TotalHg-ST12-4/6/09	0915011-07	110 Greenwich Street (roof level)	4/6/09	0.57	Mercury	EPA 324/1631	BRL	4/8/09	< 26.0	No	No	
TotalHg-ST13-4/6/09	0915011-08	Marriott Hotel, 38th Floor (roof level)	4/6/09	0.53	Mercury	EPA 324/1631	BRL	4/8/09	< 28.0	No	No	
TotalHg-ST14-4/6/09	0915011-09	West Face - South end at corner (scaffolding level)	4/6/09	0.59	Mercury	EPA 324/1631	BRL	4/8/09	< 25.0	No	No	
TotalHg-ST15-4/6/09	0915011-10	South Face - East end at corner (scaffolding level)	4/6/09	0.56	Mercury	EPA 324/1631	BRL	4/8/09	< 27.0	No	No	
TotalHg-ST16-4/6/09	0915011-11	East Face - North end at corner (scaffolding level)	4/6/09	0.61	Mercury	EPA 324/1631	BRL	4/8/09	< 25.0	No	No	
TotalHg-ST17-4/6/09	0915011-12	North Face - West end at corner (scaffolding level)	4/6/09	0.61	Mercury	EPA 324/1631	BRL	4/8/09	< 25.0	No	No	